



Expertise

Protocol number: 46887938  
Order No. / Reference: 26782891  
Inspection date: 4 Aug 2026

Manufacturer: Opel

Model: Astra 1.5 D Start/Stop Sports Tourer Elegance

VIN: W0VBE8EV2N8037367



ALPHABET



ALPHABET

Vehicle details

Manufacturer / Type / Model / Equipment

Opel Astra 1.5 D Start/Stop Sports Tourer Elegance

|                                      |                   |
|--------------------------------------|-------------------|
| Vehicle Identification number        | W0VBE8EV2N8037367 |
| Mileage (Read)                       | 120,494 km        |
| First registration                   | 2 Mar 2022        |
| Number of holders                    | 1                 |
| Next periodical technical inspection | 04/2027           |
| (Report on hand)                     |                   |

|                                |                             |
|--------------------------------|-----------------------------|
| Fuel type                      | Diesel                      |
| Engine displacement / Cylinder | 1,496 ccm / 3               |
| Power                          | 90 kW                       |
| Gearbox / Number of gears      | Manual / 6                  |
| Type of drive                  | Front drive                 |
| Type of vehicle                | Station wagon               |
| Colour / colour code           | Argonsilber Metallic        |
| Doors / Seats                  | 5 / 5                       |
| Upholstery type                | Cloth / leather combination |
| Colour of upholstery           | Black-Grey                  |
| Re-import                      | no                          |
| Vehicle with smoke odor        | no                          |
| readiness to drive             | Roadworthy                  |



## Vehicle details

|                                                  |                          |                                |                                                            |
|--------------------------------------------------|--------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete | <b>Next maintenance in</b>     | 24 %                                                       |
| <b>Last service on / at</b>                      | 11/2025 at 105,922 km    |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                    | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                          | <b>Letter No.</b>              | GJ633698                                                   |
| <b>Previous damage / Accident</b>                | None detectable          | <b>Repainting</b>              | Detectable                                                 |
| <b>Inspection conditions</b>                     | sufficient               | <b>Lifting equipment / pit</b> | yes                                                        |
| <b>Test drive</b>                                | Not performed            | <b>Engine function test</b>    | Performed                                                  |
| <b>readiness to drive</b>                        | Roadworthy               |                                |                                                            |
| <b>Manufacturer key number/ type code number</b> | 1844 / ALM 00227         |                                |                                                            |
| <b>Emission standard</b>                         | EURO6                    | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 1,945 kg                 | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 205/55 R16 91V | Summer tyres on Light alloy | Dunlop       | 6mm / 6mm   |
| 2) | 205/55 R16 91V | Summer tyres on Light alloy | Dunlop       | 7mm / 7mm   |

### Replacement

| Typ | Tyre size      | Type of tyre          | Manufacturer | Tread depth |
|-----|----------------|-----------------------|--------------|-------------|
| N   | 115/70 R16 92M | Summer tyres on Steel | Continental  | 5 mm        |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



## Equipment

### Equipment

- Klimaautomatik

### Standard equipment

- Storage compartments
- Airbag: Chest-pelvis side airbag for driver and front passenger side
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- third brake light
- Decorative trim strips in piano black
- Tachometer
- Electric windows front and rear
- Speed controller with limiter
- Back window, heater
- Interior lighting, front and rear
- Automatic climate control, two zones
- trunk light
- Front headrests
- LED headlights
- Light alloy wheels 7 J x 16 in a "10-spoke" design
- Lighting equipment
- Electric parking brake
- Upholstery: Fabric/Premium leather look
- Radio: Digital radio reception DAB/DAB+/DMB-R
- Tire pressure monitoring system
- Power steering
- Luggage compartment safety net
- Start/Stop System
- Traction Control (TC) Plus
- Immobiliser
- Central locking with remote control and interior switches
- Airbag for driver and passenger side
- Airbag: Head airbags, 1st and 2nd row (outer seats)
- Ambient lighting, front doors
- Automatic activation of the hazard warning lights
- Hill Start Assist
- On-board computer
- Roof rails, silver
- Diesel particulate filter (DPF)
- Electronic Stability Program Plus (ESP Plus)
- Front camera
- Transmission: 6-speed manual transmission
- rear window wiper
- Instruments, black, with high-gloss chrome rings, 3.5" driver information display
- Rear headrests (3)
- Cargo area cover
- LED daytime running lights
- Steering column, height and reach adjustable
- Sliding center armrest, front
- Pedals: Disengaging safety pedals
- Quickheat rapid heating system
- Radio: Multimedia radio with 7" touchscreen color display
- Rear seat backrest folds forward in a 60:40 split
- Seat belts: Three-point seat belts in all seats
- Visibility equipment
- 12V power outlet in the center console
- Pre-installation for child seat mounting system "ISOFIX"
- Heat-insulating glazing, green tinted, and windshield



## Extra equipment

- Connectivity services (emergency call)
- Heated windscreen, ThermoTec
- Ignition keys, two, both foldable
- Interior equipment Sports Tourer (rear seat backrest foldable in 40:20:40 ratio - rear center armrest with pass-through from the luggage compartment - FlexFold rear seat backrest)
- Package: Elegance Package (IntelliLux LED Matrix headlights - LED taillights - Multimedia Navi Pro voice control touchscreen color display multimedia radio Apple CarPlay/Android Auto Bluetooth - Solar Protect heat-insulating glazing, heavily tinted, in the rear)
- Seats: Ergonomic active seat, driver and front passenger (certified by the Campaign for Healthy Backs (AGR) Driver and front passenger seat: - Length, height and tilt adjustable - Electropneumatic lumbar support adjustable in height and length - Extendable thigh support - Pocket on the back of the front seats, driver and front passenger)
- Wheels: Emergency spare wheel, steel 4Jx16
- Digital reversing camera with steering guidelines
- Paint finish: Metallic
- Park & Go Digital (Automatic parking assistant including parking pilot, front and rear parking aid - blind spot warning in both exterior mirrors - electrically folding exterior mirrors - digital reversing camera with steering guidelines)
- Phone: Wireless charging including 2 USB ports, rear
- Steering wheel: Heated leather steering wheel and seat heating, multi-stage, driver and front passenger (including rear footwell heating)
- Traffic sign assistant with pedestrian detection, front (detection of speed limits, no-overtaking zones and their cancellation, additional information signs (e.g., for wet conditions, slippery surfaces, left/right directions) on standard traffic signs, beginning and end of motorways, expressways and traffic-calmed areas, display of the detected sign in the driver information display (depending on traffic sign quality, visibility and weather conditions), automatic activation between 14 km/h and 200 km/h (during the day) or 150 km/h (at night))

## Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                        |
| Engine function test | An engine test run was performed.                                                                                                                                            |
| readiness to drive   | The vehicle was roadworthy at the time of inspection.                                                                                                                        |

## Value reducing factors

| No. | Component group        | Description                                    |
|-----|------------------------|------------------------------------------------|
| 1   | Sill - right side      | Sill - dent(s) - Smooth repair work            |
| 2   | Boot lid / rear door   | Boot lid - Scratch(es) - Smart repair          |
| 3   | Body                   | A-pillar - right side - dent(s) - Smart repair |
| 4   | Front bumper           | Front bumper - Stone chips - Paint             |
| 5   | Rear bumper            | Rear bumper - Scratched - Paint                |
| 6   | Mudguard - left side   | Mudguard - left side - Scratch(es) - Paint     |
| 7   | Door - front left side | Door - Scratch(es) - Paint                     |
| 8   | Door - rear right side | Door - dent(s) - Repair and paint              |
| 9   | Bonnet                 | Bonnet - Stone chips - Paint                   |
| 10  | Roof                   | Roof - Stone chips - Paint                     |



## Wear and tear

| No. | Component group | Description |
|-----|-----------------|-------------|
|-----|-----------------|-------------|

|   |                 |                                                        |
|---|-----------------|--------------------------------------------------------|
| 1 | Vehicle glazing | Windscreen (Steinschläge) - Stone chips - No deduction |
|---|-----------------|--------------------------------------------------------|

The vehicle shows signs of wear and tear commensurate with its age and use.

## Repainting

### No. Repainting

|   |                                                                                                           |
|---|-----------------------------------------------------------------------------------------------------------|
| 1 | Side panel - rear right side, Door - rear right side, Door - front right side, Professionally carried out |
|---|-----------------------------------------------------------------------------------------------------------|

## Paint coat thickness measurement

|                              |        |                        |        |
|------------------------------|--------|------------------------|--------|
| Side panel - rear right side | 922 µm | Door - rear right side | 205 µm |
| Door - front right side      | 204 µm |                        |        |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)



**Figure 3:** Diagonal rear (left)



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument cluster



Figure 9: Instrument panel



Figure 10: Interior 360° view



Figure 11: Cargo area



Figure 12: VIN



Figure 13: Mounted tyres




Figure 14: Documents



Figure 15: Documents




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Damage 1: Sill - right side: Sill - dent(s) - Smooth repair work



**Damage 1:** Sill - right side: Sill - dent(s) - Smooth repair work




**Damage 2:** Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



**Damage 2:** Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



**Damage 3:** Body: A-pillar - right side - dent(s) - Smart repair



**Damage 3:** Body: A-pillar - right side - dent(s) - Smart repair



**Damage 4:** Front bumper: Front bumper - Stone chips - Paint



**Damage 4:** Front bumper: Front bumper - Stone chips - Paint



**Damage 4:** Front bumper: Front bumper - Stone chips - Paint



**Damage 4:** Front bumper: Front bumper - Stone chips - Paint



**Damage 4:** Front bumper: Front bumper - Stone chips - Paint



**Damage 4:** Front bumper: Front bumper - Stone chips - Paint



**Damage 5:** Rear bumper: Rear bumper - Scratched - Paint



**Damage 5:** Rear bumper: Rear bumper - Scratched - Paint



**Damage 6:** Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



**Damage 6:** Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



**Damage 7:** Door - front left side: Door - Scratch(es) - Paint




**Damage 7:** Door - front left side: Door - Scratch(es) - Paint



**Damage 7:** Door - front left side: Door - Scratch(es) - Paint



**Damage 7:** Door - front left side: Door - Scratch(es) - Paint




**Damage 8:** Door - rear right side: Door - dent(s) - Repair and paint



**Damage 8:** Door - rear right side: Door - dent(s) - Repair and paint



**Damage 9:** Bonnet: Bonnet - Stone chips - Paint



**Damage 9:** Bonnet: Bonnet - Stone chips - Paint



**Damage 9:** Bonnet: Bonnet - Stone chips - Paint




**Damage 10:** Roof: Roof - Stone chips - Paint




**Damage 10:** Roof: Roof - Stone chips - Paint



**Damage 10:** Roof: Roof - Stone chips - Paint



**Wear and tear 1:** Vehicle glazing: Windscreen (Steinschläge) - Stone chips - No deduction



**Wear and tear 1:** Vehicle glazing: Windscreen (Steinschläge) - Stone chips - No deduction



**Wear and tear 1:** Vehicle glazing: Windscreen (Steinschläge) - Stone chips - No deduction



Side panel - rear right side: 922 µm



Door - rear right side: 205 µm



Door - front right side: 204 µm



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VBE8EV2N8037367

Hersteller / Modell: OPEL OPEL Astra 1.5 D Start/Stop Sports Tourer Elegance

| Datum      | KM-Stand | Beschreibung                                                                                                                                                                                                           |
|------------|----------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 19.11.2025 | 105.922  | Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsscheiben hinten; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                |
| 02.04.2025 | 98.392   | AU                                                                                                                                                                                                                     |
| 15.10.2024 | 87.088   | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges                                                                                                                            |
| 29.02.2024 | 66.426   | Bremsscheiben + Klötze v; Wartung Sonstiges                                                                                                                                                                            |
| 24.01.2024 | 62.943   | Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges |
| 31.01.2023 | 32.792   | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges                                                                                                                            |