

DEKRA Automotive Solutions

Vehicle details

VIN	WVWZZZCDZ MW316081	Registration date	01/01/1900	Exterior Color	Unknown
Brand	VW	Licence Plate	2DFU217	Odometer	39 618 km
Model	GOLF				

Inspection Details

Arrival Date	15/07/2026	Inspection ID	7073599	Inspection date	24/07/2026
Assign Date	15/07/2026	Fleet owner	LIZY Belgique	Inspection loc.	Parc Lizy



Generic equipment


Removable element

Spare wheel kit	✓
Load cover	✓

Technical Document

Tyres

Hankook 205/55/16 V All seasons
3.0 mm



Hankook 205/55/16 V All seasons
3.0 mm



Hankook 205/55/16 V All seasons
4.0 mm

Hankook 205/55/16 V All seasons
4.0 mm

Damages

1



Part	Special rim 16"	Repair Time	-	Part Cost	195.00€
Position	Back right	Repair Cost	-	Gross Cost	195.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Repair	Flat Rate	-	Net Cost	195.00€

2



Part	Special rim 16"	Repair Time	-	Part Cost	195.00€
Position	Front right	Repair Cost	-	Gross Cost	195.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Repair	Flat Rate	-	Net Cost	195.00€

DEKRA Automotive Solutions

3		Part	Exterior door mirror shell	Repair Time	0.50	Part Cost	-
		Position	Right	Repair Cost	37.50€	Gross Cost	37.50€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Polishing	Flat Rate	37.50€	Net Cost	37.50€
4		Part	Bonnet	Repair Time	-	Part Cost	-
		Position	Front	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
5		Part	Bumper	Repair Time	2.80	Part Cost	-
		Position	Front	Repair Cost	210.00€	Gross Cost	312.00€
		Damages	Improper repair	Paint Time	1.20	Depreciation %	-
		Severity	-	Paint cost	102.00€	Depreciation	-
		Repair mode	Repair	Flat Rate	-	Net Cost	312.00€
6		Part	Sill	Repair Time	2.00	Part Cost	-
		Position	Left	Repair Cost	150.00€	Gross Cost	243.50€
		Damages	Dent & Chips	Paint Time	1.10	Depreciation %	-
		Severity	-	Paint cost	93.50€	Depreciation	-
		Repair mode	Repair	Flat Rate	-	Net Cost	243.50€
7		Part	Door	Repair Time	1.50	Part Cost	-
		Position	Back left	Repair Cost	112.50€	Gross Cost	223.00€
		Damages	Scratched	Paint Time	1.30	Depreciation %	-
		Severity	-	Paint cost	110.50€	Depreciation	-
		Repair mode	Repair	Flat Rate	-	Net Cost	223.00€
8		Part	Bumper	Repair Time	1.90	Part Cost	-
		Position	Back	Repair Cost	142.50€	Gross Cost	236.00€
		Damages	Dented	Paint Time	1.10	Depreciation %	-
		Severity	-	Paint cost	93.50€	Depreciation	-
		Repair mode	Repair	Flat Rate	-	Net Cost	236.00€
9		Part	Tailgate / Boot door	Repair Time	-	Part Cost	-
		Position	Back	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
10		Part	Interior cleaning	Repair Time	0.50	Part Cost	-
		Position	Front right	Repair Cost	37.50€	Gross Cost	37.50€
		Damages	Stained/dirty	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Cleaning	Flat Rate	37.50€	Net Cost	37.50€

DEKRA Automotive Solutions

11		Part	Tyre	Repair Time	0.50	Part Cost	106.50€
		Position	Back right	Repair Cost	37.50€	Gross Cost	144.00€
		Damages	Cut	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	144.00€

Summary Inspection

Gross Price	1,623.50€	Depreciation	-	Net Price	1,623.50€
-------------	-----------	--------------	---	-----------	-----------


Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	75.00€	9.70	727.50€	-	-	727.50€
Paintwork	85.00€	4.70	399.50€	-	-	399.50€
Paint preparation	85.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	496.50€	-	-	496.50€
Flat Rate	0.00€	-	-	0.00€

Signatures

Signature Receiver	Signature Expert	Signature Customer / Driver
		 Van der Aa 24/07/2026 8:24