



Expertise

Protocol number: 46520930
Order No. / Reference: 26546968
Inspection date: 7 Jul 2026

Manufacturer: Ford

Model: Galaxy 2.5 Duratec FHEV VIGNALE

VIN: WF0KXXWPCHPC18259



Vehicle details

Manufacturer / Type / Model / Equipment

Ford Galaxy 2.5 Duratec FHEV VIGNALE

Vehicle Identification number	WF0KXXWPCHPC18259
Mileage (Read)	38,890 km
First registration	4 May 2023
Number of holders	1
Next periodical technical inspection	05/2026
(Report not on hand)	

Power / Engine displacement	110 kw / 2,488 ccm
Fuel type / Cylinder	Hybrid Petrol / E / 4
Gearbox / Number of gears	Automatic / 1
Type of gearbox	CVT
Type of drive	Front drive
Type of vehicle	Van

Colour / colour code	Agate Black Metallic
Doors / Seats	5 / 7
Upholstery type	Leather
Colour of upholstery	Anthracite-Black

Re-import	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	68 %
Last service on / at	01/2026 at 32,861 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP514221
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BVI 00109		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,595 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103V	Winter tyres on Light alloy	Goodyear	6mm / 6mm
2)	235/55 R17 103V	Winter tyres on Light alloy	Goodyear	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R18 101Y	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	235/50 R18 101Y	Summer tyres on Light alloy	Michelin	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Adaptive LED headlights (Ford Dynamic LED)
- Ambient lighting at the front with LED technology
- Exterior mirrors painted in body color, electrically adjustable, heated and foldable
- Tires: Tire repair kit
- third brake light
- Tachometer
- Electric windows front and rear
- Electronic parking brake
- Ford Power Start function
- Cruise control system with intelligent speed limiter
- Transmission: CVT automatic (continuously variable transmission)
- Interior lighting with delay circuit
- Intelligent security system
- Electric child safety lock
- Front headrests, 4-way height and tilt adjustable
- Steering wheel: Steering column, adjustable in height and reach
- Front center console with padded armrest
- Sony navigation system including Ford SYNC 3 with AppLink, touchscreen and DAB as well as FordPass Connect
- Front and rear parking pilot system
- Upholstery: Premium leather upholstery with massage function
- Rear view camera
- Headlight assistant with day/night sensor
- Headlights washer / wiper system
- Electromechanical power steering
- Seats: 2nd row of seats with 3 individual seats (FoldFlat System)
- Seats: Comfort seats, front
- Power outlet: 12-volt connection in the luggage compartment and in the center console
- Velour carpet floor mats
- Lashing eyes in the luggage compartment
- thermal insulation glazing
- Cigarette lighter
- Airbag: Passenger airbag deactivation
- Anti-lock braking system (ABS)
- Attachment points for safety partition grilles
- Tires: 7.5 J x 18 alloy wheels (4) with 235/50 R 18 tires
- Hill start assist
- Roof rails "aluminum look"
- Lane keeping assist including lane keeping assist and driver fatigue warning
- Ford KeyFree system
- FordPass Connect including eCall, live traffic information and Wi-Fi hotspot
- Back window, heater
- rear window wiper
- Interior upholstered in high-quality leather
- Isofix bracket
- Air conditioning with automatic temperature control
- Paint finish: Metallic
- Steering wheel: Multifunction leather steering wheel
- Reading lights front and rear
- MyKey key system (individually programmable second key)
- Fog lights with LED technology
- Emergency brake light
- Package: Winter
- Pedal assembly with aluminum pads
- Rain sensor
- Tire Pressure Monitoring System (TMPS)
- Headlight dipped beam with switch-off delay including "greeting function"
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Seats: 3rd row of seats with 2 individual seats (FoldFlatSystem)
- Seats: Trays on the front seat backrests
- Power outlet: 230-volt connection (150 watts)
- Front bumper painted in body color
- Traffic sign recognition system
- Electronic immobilizer
- Central locking with remote control



Extra equipment

- Anti-theft alarm system including double locking (with interior monitoring)
- Safety partition net behind the 2nd row of seats for the luggage compartment
- Sunshade blinds integrated into the rear doors
- Package: Business III (Automatic) (Sony Navigation incl. Ford SYNC 3, AppLink, Touchscreen, Voice Control, Radio/CD Player, MP3-compatible, 2 USB ports, 390-watt premium sound system, 12 speakers, steering wheel remote control, Bluetooth hands-free system, FordPass Connect, eCall, DAB/DAB+, Adaptive LED headlights with glare-free high beam, ACC, Traffic Jam Assist, Pre-Collision Assist, Forward Collision Warning, Emergency Brake Assist, Front and Rear View Camera, Blind Spot Assist, Cross Traffic Alert, Dynamic Distance Control, Power Tailgate with Sensors, Ford Key Free System, Park Assist)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was simply read from the vehicle. The undersigned had no documentation for verification.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Sill - Scratch(es) - Smart repair
2	Side panel - rear left side	Sill - Scratch(es) - Smart repair
3	Misc.	Main inspection - Due - Perform
4	Rear bumper	Rear bumper - Scratch(es) - Paint
5	Bonnet	Bonnet (Übermäßige Steinschläge) - Stone chips - Paint
6	Vehicle glazing	Windscreen, heated (Großer Abplatzer im Fahrersichtfeld, Sichtbeeinträchtigung) - Stone chips - Replace

Missing parts

Description

Interior - Separation net

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.
- Für den montierten Radsatz wurde kein Nachweis erbracht.
- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.





Figure 30: Misc.



Figure 31: Misc.




Damage 1: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 1: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 1: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 1: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 2: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 2: Side panel - rear left side: Sill - Scratch(es) - Smart repair




Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Bonnet: Bonnet (Übermäßige Steinschläge) - Stone chips - Paint



Damage 5: Bonnet: Bonnet (Übermäßige Steinschläge) - Stone chips - Paint



Damage 5: Bonnet: Bonnet (Übermäßige Steinschläge) - Stone chips - Paint



Damage 5: Bonnet: Bonnet (Übermäßige Steinschläge) - Stone chips - Paint



Damage 6: Vehicle glazing: Windscreen, heated (Großer Abplatzer im Fahrersichtfeld, Sichtbeeinträchtigung) - Stone chips - Replace



Damage 6: Vehicle glazing: Windscreen, heated (Großer Abplatzer im Fahrersichtfeld, Sichtbeeinträchtigung) - Stone chips - Replace



Missing part 1: Interior: Separation net - Missing - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0KXXWPCHPC18259

Hersteller / Modell: FORD FORD Galaxy 2.5 Duratec FHEV VIGNALE

Datum	KM-Stand	Beschreibung
23.01.2026	32.861	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges