


2-FHV-917

2-FHV-917 · ST Line 1.0i EcoBoost 125pk M6 · 6 August 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FHV-917	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF02XXERK2RA34260
Model	Puma	Cylinder Capacity	999 ^{cm3}
Model Versions	ST Line 1.0i EcoBoost 125pk M6	Transmission Type	Handmatig geschakelde transmissie
		First Admission	16-05-2024
Body Type	5 door hatchback	Odometer	78.360 ^{Km}
Color	Grey	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2024	Number Headrests	5
KW	92		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Leather steering wheel

Navigation system

Rear parking sensors

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate


Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	1 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Left	4 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Front Right	1 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Right	4 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Spare Tire Type	None					

Damages



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No



Damage Part	Damage Type	Repair Type	Acceptable
Windscreen - Front	Chipped	Window Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Front	Collision Damage	Panelbeating & Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper - Front	Broken	Luchtinlaat sierlijst	Replace	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Small dent(s)	Dakstijl	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Dislocated / Loose	Repair	No



Damage Part
Skirt - Right



Damage Type
Missing



Repair Type
Replace

Acceptable
No



Damage Part
Skirt - Left



Damage Type
Missing



Repair Type
Replace

Acceptable
No



Damage Part
Trunkshelf



Damage Type
Missing



Repair Type
Replace

Acceptable
No