



Expertise

Protocol number: 46739972
Order No. / Reference: 26750479
Inspection date: 28 Jul 2026

Manufacturer: Ford

Model: Transit 350 L3H2 Lkw VA Trend

VIN: WF0EXXTTREPP46627



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Transit 350 L3H2 Lkw VA Trend	
Vehicle Identification number	WF0EXXTTREPP46627
Mileage (Read)	39,054 km
First registration	6 Mar 2024
Number of holders	1
Next periodical technical inspection	04/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	96 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Frozen White
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	35,000 km
Last service on / at	04/2026 at 38,561 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GX250328
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	short drive on the company premises	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BNG 10746		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Summer tyres on Steel rim with wheel cover	Continental	5mm / 5mm
2)	235/65 R16 115R	Summer tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Winter tyres on Steel	Pirelli	7mm / 7mm
2)	235/65 R16 115R	Winter tyres on Steel	Pirelli	7mm / 7mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- Rubberized floor, entire vehicle length
- On-board computer
- Double-leaf rear door with 180° opening angle (without window)
- Electronic Stability Program (ESP) with Traction Control (TSC)
- Front electric windows
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Lockable glove compartment with lid
- Front air conditioning
- Cargo area lighting
- MyKey key system
- Package: Technology Package 9
- Wheels: Wheel trims
- Wheels: Steel wheels 6.5 J x 16 with 235/65 R 16 tires
- Sliding door: Sliding door, right
- Rear mud flaps
- Low side paneling
- Seat belts
- Seats: Seat package 13
- Rear bumper with integrated step
- Partition wall (plastic) with window
- Immobiliser
- Central locking with remote control
- Front overhead storage compartment
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- Battery: Battery life, programming of battery life to 10 minutes
- roof, middle
- Tachometer
- Third brake light
- Windows: Sliding windows, right and left (at the height of the 2nd row of seats)
- Ford Easy Fuel
- Generator, high-performance version
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Paint finish: Solid color paint
- Steering column, adjustable in height and reach
- Emergency call assistant
- Particulate filter: diesel particulate filter
- Wheels: Tire repair kit
- Sliding door entry light automatically illuminates when the door is opened
- Side protection strips
- Power steering
- Seats: Rear seat package 2
- Start-stop system
- Daytime running light
- Lashing eyes
- Heat-insulating glazing, lightly tinted
- Second key with remote control

Extra equipment

- Navigation system (dynamic and cloud-based navigation with road map for Western Europe - including automatic climate control - Ford audio system with 12" multifunction display and Ford SYNC 4 - Bluetooth, hands-free system with voice control - music playback with voice control - integration of storage media (USB, MP3 player) - FordPass Connect including Wi-Fi hotspot, control of selected functions with the FordPass app - Emergency call assistant - Ford Power-Up - AppLink, Android Auto, Apple CarPlay - touchscreen)
- Seats: Seat Package 29 (Driver's seat, 4-way electrically adjustable (forward/backward, backrest, seat cushion tilt, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Integrated tray table in the double passenger seat (foldable) - Heated front seats - Interior armrest for driver - Manual lumbar support (driver's seat) - Passenger airbag, front head/shoulder airbags and front side airbags - Seat upholstery: fabric)
- Wheels/Tires: Spare wheel, steel wheel
- 2 batteries single option / cold start package (-29 degrees)
- Double-wing rear doors with a 256° opening angle, (without windows) (without rear windows, with holding magnets)
- LED lights in the cargo area
- Package: Load securing package BDSAH
- Package: Technology Package 10 (Heated windscreen, rain-sensing wipers - Front and rear parking sensors, active emergency braking assist (camera-based) - Lane Keeping Assist with Driver Alert and High Beam Assist; additionally with Lane Departure Warning - Automatic Headlights with Day/Night Sensor - Cruise Control - Rearview Camera with image transmission of the rear view on the multifunction display - LED Downlights - Fog Lights - Ford Audio System with 4" multifunction display)
- Power outlet: Voltage converter 230 V (400 W)
- Side wall cladding up to the roof BBAAD
- Speed limiter 130 km/h (not switchable)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	A short maneuvering and shunting exercise was carried out on the company premises.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Sliding door, right	Sliding door - dent(s) - Smooth repair work
2	Sill - left side	Sill - Scratch(es) - Smart repair
3	Roof	Roof - Corrosion - Smart repair
4	Body	Body - Glued / labelled - De-glue / neutralise
5	Door - front left side	Door - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction
2	Front bumper	Front bumper - Scratch(es) - No deduction
3	Interior	Cargo area floor - Soiled - No deduction
4	Body	Body - Scratch(es) - No deduction
5	Door - front left side	Door edge - Scratch(es) - Smart repair

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der beiliegende Winterradsatz ist kein Bestandteil der Auslieferungsumfangs.

Keine Besichtigung des Unterbodens, Begutachtung Fahrwerk/Achsen/Aggregate nur bedingt möglich, Zusatzkosten können entstehen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.





Figure 30: Misc.





Damage 1: Sliding door, right: Sliding door - dent(s) - Smooth repair work

Damage 1: Sliding door, right: Sliding door - dent(s) - Smooth repair work




Damage 1: Sliding door, right: Sliding door - dent(s) - Smooth repair work

Damage 2: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 2: Sill - left side: Sill - Scratch(es) - Smart repair

Damage 3: Roof: Roof - Corrosion - Smart repair



Damage 3: Roof: Roof - Corrosion - Smart repair



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Door - front left side: Door - Scratch(es) - Paint



Damage 5: Door - front left side: Door - Scratch(es) - Paint



Wear and tear 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 2: Front bumper: Front bumper - Scratch(es) - No deduction



Wear and tear 2: Front bumper: Front bumper - Scratch(es) - No deduction



Wear and tear 5: Door - front left side: Door edge - Scratch(es) - Smart repair



Wear and tear 5: Door - front left side: Door edge - Scratch(es) - Smart repair



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0EXXTTREPP46627
Hersteller / Modell: FORD FORD Transit 350 L3H2 Lkw VA Trend

Datum	KM-Stand	Beschreibung
25.04.2026	38.561	AU; Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges