



Expertise

Protocol number: 46678129
Order No. / Reference: 26620928
Inspection date: 20 Jul 2026

Manufacturer: Opel

Model: Astra 1.5 D Start/Stop Sports Tourer Business Edition

VIN: W0VBD8EV4N8042962



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Astra 1.5 D Start/Stop Sports Tourer Business Edition	
Vehicle Identification number	W0VBD8EV4N8042962
Mileage (Read)	33,728 km
First registration	13 Jun 2022
Number of holders	1
Next periodical technical inspection	07/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,496 ccm / 3
Power	90 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Argonsilber
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Dark grey



Vehicle details			
Maintenance booklet / proof	digital evidence / incomplete	Next maintenance in	0 %
Last service on / at	07/2025 at 21,344 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ664220
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / ALL 00259		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,945 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Goodyear	7mm / 7mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Goodyear	8mm / 8mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91V	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	205/55 R16 91V	Summer tyres on Light alloy	Continental	6mm / 6mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- 2 ignition keys
- Airbag for driver and passenger side
- Airbag: Head airbags, 1st and 2nd row (outer seats)
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- third brake light
- black roof rails
- Diesel particulate filter (DPF)
- Electronic Stability Program Plus (ESP Plus)
- Speed controller with limiter
- Back window, heater
- Interior lighting, front and rear
- Air conditioning
- trunk light
- Front headrests
- LED headlights
- Steering column, height and reach adjustable
- Fog light
- Upholstery: Cloth
- Radio: Digital radio reception DAB/DAB+/DMB-R
- Tire repair kit
- Rear seat backrest folds forward in a 60:40 split
- Seat belts: Three-point seat belts in all seats
- Visibility equipment
- Start/Stop System
- Traction Control (TC) Plus
- Immobiliser
- Central locking with remote control and interior switches

- Storage compartments
- Airbag: Chest-pelvis side airbag for driver and front passenger side
- Automatic activation of the hazard warning lights
- Hill Start Assist
- On-board computer
- Roof design line, above in black
- Decorative trim strips Antelao Sand/Polar Silver
- Tachometer
- Electric windows front and rear
- Transmission: 6-speed manual transmission
- rear window wiper
- Instruments, black, with high-gloss chrome rings, 3.5" driver information display
- Rear headrests (3)
- Cargo area cover
- LED daytime running lights
- Lighting equipment
- Pedals: Disengaging safety pedals
- Quickheat rapid heating system
- Radio: Multimedia radio with 7" touchscreen color display
- Tire pressure monitoring system
- Power steering
- Luggage compartment safety net
- Seats: Comfort seats, front
- 12V power outlet in the center console
- Pre-installation for child seat mounting system "ISOFIX"
- Heat-insulating glazing, green tinted, and windshield

Extra equipment

- Paint finish: Metallic
- Steering wheel: Heated leather steering wheel and seat heating, multi-stage, driver and front passenger (including rear footwell heating)
- Parkpilot, front and rear parking aid (with acoustic warning signal when parking forwards and backwards)
- Seats: Ergonomic active seat (certified by the Campaign for Healthy Backs (AGR) Driver's seat: - Length, height and tilt adjustable - Electropneumatic lumbar support adjustable in height and length - Extendable thigh support - Pocket on the back of the front seats, driver and front passenger)
- Light alloy wheels 7 J x 16 in "10-spoke" design (with tires 205/55 R 16)
- Sliding center armrest, front (with storage compartments and cup holders)
- Radio: Multimedia Navi (Multimedia Radio, 7" touchscreen color display with USB port, hands-free system, voice control, Bluetooth audio streaming, smartphone integration via Apple CarPlay and Android Auto - Navigation system with integrated memory - Road map for over 30 European countries - Map display in 2D and 3D - Dynamic route guidance via map and/or arrow display and voice prompts - Dynamic destination guidance via enhanced Traffic Message Channel (TMCpro))



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Annual inspection - Incomplete - No deduction
2	Front bumper	Spoiler - Scratched - Loss in value
3	Wheel / tyres	Pressure sensor - on - Perform diagnosis
4	Wing mirror - right side	Cap - Scratch(es) - Smart repair
5	Rear bumper	Spoiler - Scratch(es) - Smart repair
6	Door - rear right side	Door - Scratch(es) - Smart repair
7	Sill - left side	Sill - Scratch(es) - Smart repair
8	Sill - right side	Sill - dent(s) - Smooth repair work
9	Front bumper	Front bumper - Scratch(es) - Smart repair
10	Engine	Engine cowling - lower - Broken / torn - Replace
11	Body	Identification plate - Damaged - Replace
12	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - Repair and paint
13	Rear bumper	Rear bumper - Scratch(es) - Paint
14	Side panel - rear left side	Side panel - Scratch(es) - Paint
15	Door - rear left side	Door - Scratch(es) - Paint
16	Boot lid / rear door	Boot lid - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Side panel - rear right side	Side panel ((Polieren)) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Side right, Provided by user / customer, from 14 Oct 2022	7.846,22 €

Repainting

No.	Repainting
1	Mudguard - left side, Professionally carried out, Invoice of repair done Non-existent
2	Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent
3	Door - rear left side, Professionally carried out, Invoice of repair done Non-existent
4	Door - front left side, Professionally carried out, Invoice of repair done Non-existent



Paint coat thickness measurement

Mudguard - left side	184 µm	Side panel - rear left side	187 µm
Door - rear left side	170 µm	Door - front left side	201 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

-Der montierte Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.

Minderwerte höher als HEK



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents




Figure 19: Documents



Figure 20: Additional tyres



Figure 21: Navigation



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.




Figure 36: Misc.



Figure 37: Misc.



Damage 2: Front bumper: Spoiler - Scratched - Loss in value



Damage 2: Front bumper: Spoiler - Scratched - Loss in value



Damage 2: Front bumper: Spoiler - Scratched - Loss in value




Damage 2: Front bumper: Spoiler - Scratched - Loss in value



Damage 3: Wheel / tyres: Pressure sensor - on - Perform diagnosis



Damage 4: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 4: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 5: Rear bumper: Spoiler - Scratch(es) - Smart repair



Damage 5: Rear bumper: Spoiler - Scratch(es) - Smart repair




Damage 6: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 6: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 7: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 7: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 8: Sill - right side: Sill - dent(s) - Smooth repair work



Damage 8: Sill - right side: Sill - dent(s) - Smooth repair work



Damage 9: Front bumper: Front bumper - Scratch(es) - Smart repair




Damage 9: Front bumper: Front bumper - Scratch(es) - Smart repair




Damage 10: Engine: Engine cowling - lower - Broken / torn - Replace



Damage 10: Engine: Engine cowling - lower - Broken / torn - Replace



Damage 11: Body: Identification plate - Damaged - Replace



Damage 11: Body: Identification plate - Damaged - Replace



Damage 12: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 12: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 12: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 14: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 14: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 14: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 14: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 14: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 15: Door - rear left side: Door - Scratch(es) - Paint




Damage 15: Door - rear left side: Door - Scratch(es) - Paint



Damage 15: Door - rear left side: Door - Scratch(es) - Paint



Damage 16: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 16: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 16: Boot lid / rear door: Boot lid - Scratch(es) - Paint




Damage 16: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 16: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 16: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 16: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Repainting 1: Mudguard - left side



Repainting 2: Side panel - rear left side



Repainting 3: Door - rear left side



Repainting 4: Door - front left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VBD8EV4N8042962

Hersteller / Modell: OPEL OPEL Astra 1.5 D Start/Stop Sports Tourer Business Edition

Datum	KM-Stand	Beschreibung
30.07.2025	21.986	Systemtest/Eigendiagnose
04.07.2025	21.344	AU; Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
26.05.2023	12.479	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges