

Expertise

Protocol number: 46193298
Order No. / Reference: 26519093
Inspection date: 19 Jun 2026

Manufacturer: Citroën

Model: e-C4 136 FEEL PACK

VIN: VR7BCZKXCPE017840



Vehicle details

Manufacturer / Type / Model / Equipment

Citroën e-C4 136 FEEL PACK

Vehicle Identification number VR7BCZKXCPE017840

Mileage (Read) 8,755 km

First registration 23 May 2023

Number of holders 1

Next periodical technical inspection 05/2026
(Report not on hand)

Power / Engine displacement 57 kw / 0 ccm

Fuel type / Cylinder Electric / 0

Gearbox / Number of gears Direct drive / 1

Type of drive Front drive

Type of vehicle Saloon car

Colour / colour code Polar Weiß Metallic

Doors / Seats 5 / 5

Upholstery type Cloth / leather combination

Colour of upholstery Black-Grey

Re-import no

readiness to drive Roadworthy



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	
Last service on / at	05/2025 at 2,145 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GG010496
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1889 / ACW 00038		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	2,020 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/60 R18 96H	All-season tyres on Light alloy	Continental	7mm / 7mm
2)	195/60 R18 96H	All-season tyres on Light alloy	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
Tirefit		Expiration date 06/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Storage compartments: Drawer in the dashboard
- Airbag: Front and rear head airbags (except rear center)
- Airbag: Front side airbags
- Anti-lock braking system (ABS) with electronic brake force distribution and brake assist
- Exterior mirror housings in Perla Nera black
- On-board computer
- CITROEN Connect Box (Emergency Call and Assistance System)
- Chassis: Advanced Comfort Suspension
- Windscreen wipers with rain sensor
- Transmission: Direct drive (automatic electric drive with fixed gear ratio)
- Isofix child seat attachments at the rear (except center)
- Automatic climate control (2-zone) with heat pump (rear air vent)
- Headrests (5)
- Steering wheel adjustable in height and reach
- Lights: LED interior lighting front & rear
- Lights: LED daytime running lights (LED headlights with light sensor)
- Package: Color package "Glossy Black" in combination with Elixir Red or Caramel Brown paint finish (Airbump with black decorative surround of the first capsule - decorative surround of the fog lights in black)
- Electric parking brake
- Upholstery: URBAN GREY (fabric "Chevrons" grey with black imitation leather - Citroën Advanced Comfort seats - pocket on front seat back)
- Radio accessories: 10-inch touchscreen
- Indirect tire pressure sensor
- Wheels: 18" alloy wheels, "Crosslight" diamond-cut (with 195/60 R18 96H tires)
- Seats: Driver's seat and passenger seat, height adjustable
- Start&Stop system
- Technical features of electric versions (Acoustic Acoustic Vehicle Alerting System (AVAS) - Driving modes to choose from: "Eco", "Normal", "Sport" - Mode 2 charging cable (Type 2, up to 1.8 kW), 6 meters long - On-board charger 11 kW - three-phase - "Brake" function for energy recuperation when releasing the accelerator pedal)
- Airbag: Driver and front passenger side (front passenger airbag can be deactivated)
- Airbump
- Exterior mirrors (2) electrically folding and adjustable, heated
- Hill start assist
- third brake light
- Electronic Stability Program (ESP) with Traction Control (ASR)
- Electric windows front and rear (with comfort function)
- front and rear floor mats
- Head-Up Display
- Heated rear window
- Child safety lock for rear doors
- Instrument cluster: Illuminated 5.5" digital instrument cluster
- Paint finish: Metallic caramel brown
- Steering wheel: Steering wheel covered in split leather
- Lights: LED fog lights with static cornering lights
- Center console with storage compartment and armrest
- Navigation: Citroën Connect Nav (10" touchscreen - 3D navigation system - Digital radio reception DAB & DAB+ (Digital Audio Broadcasting) - Integrated European map - Reversing camera with Top Rear Vision)
- Package: Safety Package (Active Lane Keeping Assist - Attention Assist - Coffee Break Alert - Cruise Control and Speed Limiter - Collision Warning - Active Emergency Braking Assist (Camera Controlled) - Traffic Sign Recognition)
- Radio accessories: Bluetooth hands-free system
- Tire repair kit with puncture spray
- Power steering
- Seats: Driver's seat with adjustable lumbar support
- Seats: Rear seat backrest split (60/40) and foldable
- Power outlet: Additional 12V socket in the trunk
- Door handles in car color
- Variable boot floor
- Immobiliser
- Central locking with remote control

Extra equipment

- All-weather tires
- Paint finish: Special paint finish Polar White
- Package: Cold Weather Package (Heated steering wheel - Heated windscreen - Heated front seats)
- Rubber floor mats
- Charging cable: Mode 3 charging cable (22 kW, three-phase)
- Blind spot assist with front and rear parking aid



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Front bumper	Front bumper - Soiled - Conditioning
2	Misc.	Main inspection - No evidence - Perform
3	Rear bumper	Rear bumper - Scratch(es) - Smart repair

Wear and tear

No.	Component group	Description
1	Roof	Roof - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Damage 1: Front bumper: Front bumper - Soiled - Conditioning



Damage 1: Front bumper: Front bumper - Soiled - Conditioning



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Smart repair