



## BMW M3 2008

Vehicle reference:

**WBSWL91040P323486**

Body type:

Sedan

Gearbox type:

Automatic

Engine size:

3999 cm<sup>3</sup>

Fuel type:

Petrol

Combustion engine power:

309 kW / 420 hp

Drive:

Rear

# Quick Check

## Damage

This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.

● Damage

## Mileage

The reported odometer readings have a logical progression.

● No issues indicated

## Stolen

Not reported stolen

● No issues reported

## Identity check

Not reported scrapped

● No issues reported

## Import

Not a private import

● No issues reported

## Motor insurance

The liability insurance has expired

● Expired

## Registration status

Vehicle registered in Poland

● No issues reported

Located in Poland



Vehicle age

**17 years**  
**7 months**

# Damage Overview

02/2011



## Affected area



Reported in  
Poland

Damage type/cause  
Not available

Estimated repair cost:


**PLN 5,000 - PLN 6,000**

This is a rough estimate and the actual repair cost may be higher or lower. It does not show whether the damage has already been repaired. Prices are based on local rates and can vary between countries.

12/2021



## Affected area



Reported in  
Poland

Damage type/cause  
Not available

Estimated repair cost:

**PLN 8,000 - PLN 9,000**

This is a rough estimate and the actual repair cost may be higher or lower. It does not show whether the damage has already been repaired. Prices are based on local rates and can vary between countries.

## Damage Glossary

### Damage


Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.




Keep in mind: while our data shows no further damage, additional events may have occurred. CARFAX only reflects information that's been reported to us.

It's still important to take a close look at the vehicle during your test-drive. Small details can sometimes hint at past repairs. Keep an eye out for paint inconsistencies or uneven panels.

## **| Mileage Check**



 **No issues indicated:** The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

# Owners BETA



## Owner 1 in Poland

Purchase year: **2008**

Length of use: **4 years**

Type of owner: **Private individual**

Damage reported on: **02/2011**

## Owner 2 in Poland

Purchase year: **2012**

Length of use: **8 years 6 months**

Type of owner: **Private individual**

## Owner 3 in Poland

Purchase year: **2021**

Type of owner: **Private individual**

Damage reported on: **12/2021**

# History information

<b>Date</b>	<b>Mileage</b>	<b>Event</b>
2008-10-31		<b>Registered in Kraków, Poland</b> New owner reported Owner type: private individual Located in Kraków, Powiat Kraków, Małopolskie, Poland
02/2011		<b>Damage reported in Poland</b>
2012-11-19		<b>New owner reported</b> Owner type: private individual Located in Nowy Sącz, Powiat Nowy Sącz, Małopolskie, Poland
2015-03-06	72,044 km	<b>Inspected in Poland</b> Inspection type: regular Inspection passed
2016-03-31	81,367 km	<b>Inspected in Poland</b> Inspection type: regular Inspection passed
2017-11-29	92,056 km	<b>Inspected in Poland</b> Inspection type: regular Inspection passed
2018-12-10	98,595 km	<b>Inspected in Poland</b> Inspection type: regular Inspection passed
2020-06-19	102,801 km	<b>Inspected in Poland</b> Inspection type: regular Inspection passed

2021-06-16

**New owner reported**

Owner type: private individual  
Located in Nowy Sącz, Powiat Nowy Sącz, Małopolskie, Poland

---

2021-06-18

106,906 km

**Inspected in Poland**

Inspection type: regular  
Inspection passed

---

12/2021

**Damage reported in Poland**

---

2022-08-19

108,398 km

**Inspected in Poland**

Inspection type: regular  
Inspection passed

---

2023-11-30

**Vehicle insured**

Liability insurance valid until 2024-11-29

---

2024-07-05

109,860 km

**Inspected in Poland**

Inspection type: regular  
Inspection passed  
Inspection valid until 2025-07-05

---

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

# Technical details

## Engine and performance

**Fuel type**  
Petrol

**Combustion engine power**  
309 kW / 420 hp

## Environment and consumption

**CO2 emissions in mixed driving**  
285 g/km 

**Fuel consumption in mixed driving**  
11.9 l/100km

## Weight

**Curb weight**  
1,885 kg

**Max payload**  
395 kg

**Gross vehicle weight**  
2,280 kg

## Other information

**European vehicle category**  
M1

**Number of doors**  
2

**Number of seats**  
4

# CARFAX Glossary

## CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

## Model year

This term is defined by the manufacturer but it is typically the year the vehicle is built. If the model year does not appear on the CARFAX report, it is because the manufacturer did not include this information in the VIN. Model year can normally be determined by the vehicle age.

## Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

## Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

## Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

# How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our [Terms and conditions](#).