



Expertise

Protocol number: 46502942
Order No. / Reference: 26482730
Inspection date: 14 Jul 2026

Manufacturer: Ford

Model: Tourneo Custom 320 L1H1 VA Trend

VIN: WF0XXXTA3XRS05905



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Tourneo Custom 320 L1H1 VA Trend	
Vehicle Identification number	WF0XXXTA3XRS05905
Mileage (Read)	19,568 km
First registration	23 Jan 2025
Number of holders	1
Next periodical technical inspection	01/2028
(Report not on hand)	
Power / Engine displacement	100 kw / 1,996 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Blazer Blue uni
Doors / Seats	4 / 8
Upholstery type	Cloth
Colour of upholstery	Anthracite-Dark grey
Re-import	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	35 %
Last service on / at	01/2025 at 20 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HH798569
Previous damage / Accident	None detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / CAE 01461		
Emission standard	EURO6;WLTP;EB;PI/CI;M, N1, N2	fine dust sticker	
Permitted total weight	3,095 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109/107T C	Summer tyres on Light alloy	Goodyear	7mm / 7mm
2)	215/65 R16 109/107T C	Summer tyres on Light alloy	Goodyear	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109/107S C	Winter tyres on Light alloy	Continental	9mm / 9mm
2)	215/65 R16 109/107S C	Winter tyres on Light alloy	Continental	9mm / 9mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- 2 grab handles on the driver and passenger side
- Front storage compartment
- ABS
- Driver's side airbag
- Exterior mirror housings in body color
- roof, flat
- Diesel particulate filter (DPF)
- Third brake light
- Front electric windows
- Ford KeyFree system
- Heated windshield
- Lockable glove compartment with lid
- rear window wiper
- Interior lighting in the passenger compartment
- automatic climate control in the front
- Paint finish: Solid
- LED headlights
- Center console, small
- Emergency call assistant
- Package: Technology Package 2 (Trend)
- Radio accessories: 10 speakers
- Tire repair kit
- Wheels: Alloy wheels 6.5 J x 16
- Sliding door: Sliding door, right
- Rear mud flaps
- Side windows fixed, third row, right and left
- Start-stop system
- Rear bumper partially painted in body color
- Carpet throughout the vehicle
- circulating air heating
- Lashing eyes 2
- Heat-insulating glazing, lightly tinted
- 2-stage unlocking for passenger compartment and cargo area
- Passenger side airbag
- Exterior mirrors, electrically adjustable and heated
- Battery: H7 AGM single battery
- roof console
- Tachometer
- Electronic Safety and Stability Program (ESP)
- Electronic parking brake
- FordPass Connect
- Transmission: 6-speed transmission
- Heated rear window
- Rear swing door
- Front interior light
- Fuel tank 55 l
- Cargo area lighting (LED)
- Steering wheel: Sensico steering wheel in leather look
- Fatigue warning
- Package: Rear Seat Package 5
- Radio: Ford audio system with 13" multifunction display and Ford SYNC 4
- Tire Pressure Monitoring System (TPMS)
- Windscreen wipers with rain sensor
- Rail-based flexible seating system
- Front mud flaps
- Side windows fixed, second row, right and left
- Power outlet: 12-volt connection
- Front bumper partially painted in body color
- Door handles painted in car color
- USB port for the 2nd row of seats
- Immobiliser
- Central locking with remote control

Extra equipment

- Seats: Seat Package 7 (Driver's seat, 4-way manually adjustable - Single passenger seat, 2-way manually adjustable - Lumbar support for driver - Seat heating for driver and front passenger - Driver's seat with adjustable inner armrest - Front passenger seat with inner armrest - Airbag, front passenger - Side airbags, right and left - Head/shoulder airbags, front, right and left - Fabric upholstery Plus Style, seat center in Black Onyx, rest in Ebony)
- Electrically swiveling towbar
- Exterior mirrors with integrated turn signals (electrically adjustable, heated and automatically folding - incl. front electric windows with quickdown/up function for driver and passenger side)
- Floor mats: Carpet floor mats, front
- Fuel tank 70 l



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
2	Sliding door, right	Sliding door with glass panel - Dent / paintcoat damage - Smart repair
3	Front bumper	Front bumper - Damaged - Repair and paint
4	Boot lid / rear door	Boot lid - Deformed - Repair and paint

Wear and tear

No.	Component group	Description
1	Documents	Owner's manual - Missing - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Door - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Door - rear right side	155 µm
------------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 1: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 2: Sliding door, right: Sliding door with glass panel - Dent / paintcoat damage - Smart repair



Damage 2: Sliding door, right: Sliding door with glass panel - Dent / paintcoat damage - Smart repair



Damage 2: Sliding door, right: Sliding door with glass panel - Dent / paintcoat damage - Smart repair



Damage 3: Front bumper: Front bumper - Damaged - Repair and paint




Damage 3: Front bumper: Front bumper - Damaged - Repair and paint




Damage 3: Front bumper: Front bumper - Damaged - Repair and paint




Damage 3: Front bumper: Front bumper - Damaged - Repair and paint




Damage 3: Front bumper: Front bumper - Damaged - Repair and paint




Damage 3: Front bumper: Front bumper - Damaged - Repair and paint




Damage 3: Front bumper: Front bumper - Damaged - Repair and paint




Damage 3: Front bumper: Front bumper - Damaged - Repair and paint



Damage 4: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Damage 4: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Damage 4: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Repainting 1: Door - rear right side