



Expertise

Protocol number: 46427202
Order No. / Reference: 26739835
Inspection date: 8 Jul 2026

Manufacturer: Volkswagen

Model: Caddy Cargo 2.0 TDI BMT

VIN: WV1ZZZSK0PX080472



Vehicle details

Manufacturer / Type / Model / Equipment

Volkswagen Caddy Cargo 2.0 TDI BMT

Vehicle Identification number WV1ZZZSK0PX080472
Mileage (Read) 210,232 km
First registration 29 Jun 2023
Number of holders 1
Next periodical technical inspection 06/2027
(Report not on hand)

Power / Engine displacement 75 kw / 1,968 ccm
Fuel type / Cylinder Diesel / 4
Gearbox / Number of gears Manual / 6
Type of drive Front drive
Type of vehicle Van

Colour / colour code Candyweiß
Doors / Seats 4 / 2
Upholstery type Cloth
Colour of upholstery Black



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	3,100 km
Last service on / at	02/2026 at 185,383 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS577274
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	With complaint
Manufacturer key number/ type code number	0603 / CMF 00371		
Emission standard	EURO6;WLTP;AQ;PI/CI; N1 II	fine dust sticker	
Permitted total weight	2,220 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R15 99H	All-season tyres on Steel rim with wheel cover	Falken	5mm / 5mm
2)	205/65 R15 99H	All-season tyres on Steel rim with wheel cover	Falken	5mm / 5mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/65 R15 99H	All-season tyres on Steel	Vredestein	7 mm
Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.				

Equipment

Standard equipment

- Storage compartments: Glove compartment open
- Airbag, side and head airbags for driver and front passenger
- Exterior mirror housings and door handles in black, sliding door track in silver
- Floor coverings: Carpet in the driver's cab
- third brake light
- Roof rail/roof rack preparation
- Three-point automatic seat belts (with front belt height adjustment and electric belt tensioners)
- Deletion: Without rear window (sheet metal)
- ESP Electronic Stability Program with Brake Assist (incl. Anti-lock Braking System (ABS), Traction Control (ASR), (EDS and MSR))
- Electric windows, front
- Transmission: 6-speed transmission
- Rear wing door (asymmetrically divided) without window cutout
- Instrument cluster (km/h) (displays for speed, total/trip distance, engine speed, fuel level and time)
- Steering wheel: Multifunction steering wheel
- Air vents, front, in matte black
- Multifunction display "Plus"
- Multi-collision brake
- Fatigue detection
- Non-smoking version
- eCall emergency call system
- Particulate filter: Diesel particulate filter (incl. SCR and AdBlue tank)
- Radio "Composition Audio" with 20.96 cm (8.25 inch) touch color display (2 USB interfaces (Type C) in the center console, front - 4 speakers - mobile phone interface)
- Wheels, tires: Wheel covers
- Wheels/Tires: Tire pressure monitoring system
- Wheels/Tires: Steel wheels 6J x 15, in black
- Gearshift lever in plastic
- Sliding door, on the right in the passenger/cargo area
- Standard side panels in the cargo area
- Speed-sensitive power steering (Servotronic)
- Seats: Height adjustment for left seat, manual
- Sun visors without mirrors, with ticket pocket on the driver's side, plus airbag label on the sun visor
- Start-stop system (with brake energy recuperation)
- Telephone: Mobile phone interface
- Partition wall (tall) without window
- First aid kit, warning triangle and high-visibility vest
- Prepared for "We Connect" and "We Connect Plus"
- Electronic immobilizer
- Central locking with remote control and interior operation
- Airbag for driver and front passenger (with passenger airbag deactivation)
- Exterior mirrors: electrically adjustable
- Reinforced battery (70 Ah/ 420 A)
- Operating voltage 12 V
- Brake booster
- Cockpit panel, matte
- Three-phase generator 140 A
- Rear parking assist
- Electronic parking brake including auto-hold function
- Omission: Without additional child seat anchorage
- Automatic headlight control with daytime running lights
- Windows: Laminated glass front pane in heat-insulating glazing
- Cruise control system including speed limiter
- Halogen dual headlights-H7
- Heating and ventilation system in the driver's cab
- Interior lighting in the cargo area (1 light)
- Fuel fill quantity, standard fuel initial fill
- Diesel fuel system
- Headlight range control
- Center console with 2 universal cup holders
- Multifunctional camera
- Multimedia systems: 2 USB ports (Type C) in the center console, front
- Emergency braking assistant "Front Assist" (with pedestrian and cyclist detection)
- Upholstery: Fabric, "Double Grid" design
- "Composition Audio" radio with 20.96 cm (8.25 inch) color touchscreen
- Radio accessories: 4 speakers
- Radio accessories: Digital radio reception DAB+
- Wheels/Tires: 205/65 R 15 99 H XL, optimized for low rolling resistance
- taillights
- Windscreen wiper intermittent control with light sensor
- Keys for locking system: 2 remote control flip keys
- Side indicator lights
- dimmable interior safety mirror
- Seats: Left and right seats in the 1st row (including headrests)
- Lane keeping assistant "Lane Assist"
- Bumper in grey
- Tire Mobility Set (12-volt compressor and tire sealant)
- Door trim and armrest in plastic
- Lashing points: 6 lashing points for securing cargo
- Warning tone and light for unfastened front seat belts
- Green thermal insulation glazing
- Additional dust protection seal on the outside



Extra equipment

- Electrically adjustable and heated exterior mirrors
- Window: Fixed side window in the cargo/passenger compartment, front right
- Fog lights including cornering lights
- Package: Cool & Sound (Refrigerant R1234yf - Safety interior mirror, automatically dimming - Air Care Climatronic air conditioning with 2-zone temperature control and air purification function)
- Wheels/Tires: All-season tires 205/65 R15 99 H XL, optimized for rolling resistance
- Wheels/Tires: Spare wheel in driving tire size, steel (spare wheel in driving tire size, steel - on-board tools and jack)
- Floor coverings, rubber floor covering in the cargo area
- Navigation system "Discover Media" (25.4 cm (10 inch) touch color display - streaming & internet - 2 USB interfaces (Type C) in the center console, front - glove compartment with lockable, illuminated flap - 4 speakers - mobile phone interface)
- Package: Winter package "Basic" (Seat heating for seats in the driver's cab, left and right, separately adjustable - Washer fluid level indicator with enlarged washer fluid reservoir - Heated windshield washer nozzles at the front)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed, problem has been detected This is due to the following reason.: Motorkontrolleuchte

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance (1.,4.,5. und 6. Wartung überzogen)
2	Door - front left side	Door - dent(s) - Smart repair
3	Rear bumper	Rear bumper (Zusätzlich lose) - dent(s) - Loss in value
4	Instrument panel	Indicator light (Motorkontrolleuchte, nicht fahrbereit) - on - Perform diagnosis
5	Seat - front	Seat cover - right side - Holes - Replace
6	Engine	Toothed belt (fällig bei 210000km) - Due - Replace
7	Boot lid / rear door	Rear door - left side - Deformed - Repair and paint
8	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper (unpainted) - Scratch(es) - No deduction
2	Sliding door, right	Sliding door - dent(s) - No deduction
3	Side panel - rear left side	Side panel - dent(s) - No deduction
4	Boot lid / rear door	Rear door - right side - dent(s) - No deduction
5	Bonnet	Bonnet - Dent / paintcoat damage - No deduction
6	Roof	Roof - dent(s) - No deduction
7	Door - front left side	Door edge - Scratch(es) - No deduction
8	Door - front right side	Door - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Damage 2: Door - front left side: Door - dent(s) - Smart repair



Damage 2: Door - front left side: Door - dent(s) - Smart repair



Damage 2: Door - front left side: Door - dent(s) - Smart repair



Damage 3: Rear bumper: Rear bumper (Zusätzlich lose) - dent(s) - Loss in value



Damage 3: Rear bumper: Rear bumper (Zusätzlich lose) - dent(s) - Loss in value




Damage 3: Rear bumper: Rear bumper (Zusätzlich lose) - dent(s) - Loss in value



Damage 3: Rear bumper: Rear bumper (Zusätzlich lose) - dent(s) - Loss in value



Damage 3: Rear bumper: Rear bumper (Zusätzlich lose) - dent(s) - Loss in value



Damage 4: Instrument panel: Indicator light (Motorkontrolleuchte, nicht fahrbereit) - on - Perform diagnosis



Damage 5: Seat - front: Seat cover - right side - Holes - Replace




Damage 5: Seat - front: Seat cover - right side - Holes - Replace




Damage 7: Boot lid / rear door: Rear door - left side - Deformed - Repair and paint



Damage 7: Boot lid / rear door: Rear door - left side - Deformed - Repair and paint



Damage 7: Boot lid / rear door: Rear door - left side - Deformed - Repair and paint



Damage 7: Boot lid / rear door: Rear door - left side - Deformed - Repair and paint



Damage 7: Boot lid / rear door: Rear door - left side - Deformed - Repair and paint



Damage 7: Boot lid / rear door: Rear door - left side - Deformed - Repair and paint



Damage 8: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 8: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 8: Vehicle glazing: Windscreen - Broken / torn - Replace