



Expertise

Protocol number: 46273969
Order No. / Reference: 26631105
Inspection date: 30 Jun 2026

Manufacturer: Skoda
VIN: TMBJG7NX4MY121653

Model: Octavia Combi 2.0 TDI Style



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Octavia Combi 2.0 TDI Style	
Vehicle Identification number	TMBJG7NX4MY121653
Mileage (Read)	179,877 km
First registration	22 Mar 2021
Number of holders	1
Next periodical technical inspection	06/2028
(Report on hand)	
Power / Engine displacement	85 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Moonweiss Perleffekt (S9R)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Dark grey
Vehicle with smoke odor	Yes (not ozone-treated)



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	7,700 km
Last service on / at	11/2025 at 158,171 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA512844
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8004 / AWK 00101		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,940 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91W	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	205/55 R17 91W	Summer tyres on Light alloy	Michelin	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92H	Winter tyres on Light alloy	Dunlop	5mm / 5mm
2)	205/60 R16 92H	Winter tyres on Light alloy	Dunlop	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2024		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • Storage compartment in the luggage compartment with cargo element • Airbag, driver's knee airbag • Airbag, front side airbags • Anti-lock braking system (ABS) • Center section of the dashboard with fabric covering • Electrically adjustable and heated exterior mirrors • Electrically folding exterior mirrors • Hill start assist including auto-hold function • Hydraulic brake assist (HBA) • Grey headliner • Diesel particulate filter • Tachometer • Electronic parking brake • Electronic Stability Control (ESC) • Driving profile selection • Front radar assistant including city emergency braking function and pedestrian and cyclist detection • Tinted windows • Rear lights with crystal glass look and animated turn signals • Rear window wiper including windshield washer system • ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage • Removable boot cover • LED taillights • LED headlights with LED daytime running lights • Steering wheel: height and reach adjustable • Manual headlight range adjustment • Rear center armrest with pass-through option • Engine drag torque control (MSR) • Upholstery: Cloth • Radio accessories: 8 speakers • Radio accessories: Voice control • Tire pressure monitoring • Wheels: 17" alloy wheels Rotare AERO (7J x 17, ET 46 with tires 205/55 R17) • Safety lights in the front side doors • Seats: Electrically adjustable front seats with memory function • SKODA Care Connect (SOS emergency call function (Emergency Call incl. automatic activation in the event of an accident with airbag deployment), Mobility service (connection for rapid assistance in case of breakdown), Information service (connection to the hotline for all questions relating to vehicle functions), Free remote vehicle access for 1 year (Remote Access) with access to vehicle data and functions via smartphone, e.g. parking position, activating hazard warning lights, current fuel level) • Lashing eyes in the trunk • Central locking including remote control integrated into the key and EASY Start | <ul style="list-style-type: none"> • Storage compartments • Airbag, driver and passenger • Airbag, head airbags • Ambient lighting • Traction control (ASR) • Automatically dimming exterior mirror (driver's side) • Exterior mirrors with memory function • Heated windshield washer nozzles including 5l washer fluid reservoir • Glasses compartment in the headliner • Roof rails, anodized • Digital instrument cluster (Virtual Cockpit) 10.2" • Third brake light • Electronic transverse differential lock (XDS+) • Driving light assistant • Electric windows front and rear, including anti-pinch protection and child safety lock • Transmission: 6-speed manual transmission • Green tec: Start/stop system including brake energy recuperation • Heated rear window • Interior mirror automatically dimming • Kessy, keyless entry and start-stop system • Electronic child safety lock • Headrests (5) front and rear height adjustable • LED license plate lights • Remote release of the rear seat backrests in the trunk • Steering wheel: Leather steering wheel with multifunction buttons • Front center armrest, including storage compartment • Front and rear parking sensors • Radio accessories: 2 USB-C ports on the front • Radio accessories: Digital radio reception DAB+ • Rain sensor • Tire mobility kit • Electromechanical power steering • Seat belts • Seats: Heated front seats • Seats: Height-adjustable driver and passenger seats • Seats: Rear seat backrest split 60:40, foldable • Speed limiter • Lane keeping assistant (Lane Assist) • Lane change and parking assist • 12V socket in the trunk • Telephone: Phonebox with inductive charging function (connection via external antenna) • Phone: SmartLink (MirrorLink, Apple CarPlay, Android Auto) • Phone: Wireless SmartLink for Apple CarPlay • Bluetooth hands-free phone system • Immobiliser |
|--|--|



Extra equipment

- Package: Comfort (3-zone Climatronic - Sunset (dark tinted rear window and rear side windows) - Acoustic glazing in the front side windows - Heated front and outer rear seats - Heated steering wheel)
- Package: Travel (Traveller assistance system: - Traffic sign recognition - Predictive and adaptive cruise control (pACC) - Adaptive lane keeping assist - Capacitive steering wheel with hands-off detection - Adaptive cruise control (ACC) (control range 210 km/h) - Driver fatigue detection - Driving profile selection - Automatically dimming exterior mirror (driver's side))
- Heated windscreen
- Package: Infotainment Columbus Plus (Combi) (Columbus navigation system - Infotainment Online (3-year term) - Head-Up Display - Luggage net partition)
- Package: Lights (cornering lights in the fog lights - headlight cleaning system - high beam assist - LED ambient lighting)
- Paint finish: Pearl effect

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
3	Body	Underbody panelling (rechts) - Broken / torn - Replace
4	Rear bumper	Rear bumper - Scratch(es) - Smart repair
5	Interior	Interior - Odour - Ozone treatment
6	Engine	Engine cowling - lower - Broken / torn - Replace
7	Trim / covers	Floor covering - front left side - Burn hole (cigarettes) - Loss in value
8	Wing mirror - left side	Mirror glass - Scratch(es) - Replace
9	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
10	Sill - right side	Sill - Deformed - Repair and paint
11	Body	Body - Damage by hail - repair according to calculation

Wear and tear

No.	Component group	Description
1	Front bumper	Bumper with Parktronic - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 15 Nov 2024	1.420,07 €
2	Side right, Provided by user / customer, from 9 Oct 2024	1.832,98 €



Repainting

No. Repainting

- 1 Roof rail - right side, Side panel - rear left side, Side panel - rear right side, Door - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Roof rail - right side	181 µm	Side panel - rear left side	198 µm
Side panel - rear right side	365 µm	Door - rear right side	215 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Der Winterradsatz ist kein Bestandteil der Ausstattungsliste.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 3: Body: Underbody panelling (rechts) - Broken / torn - Replace



Damage 3: Body: Underbody panelling (rechts) - Broken / torn - Replace



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 6: Engine: Engine cowling - lower - Broken / torn - Replace




Damage 6: Engine: Engine cowling - lower - Broken / torn - Replace



Damage 7: Trim / covers: Floor covering - front left side - Burn hole (cigarettes) - Loss in value



Damage 7: Trim / covers: Floor covering - front left side - Burn hole (cigarettes) - Loss in value




Damage 7: Trim / covers: Floor covering - front left side - Burn hole (cigarettes) - Loss in value



Damage 7: Trim / covers: Floor covering - front left side - Burn hole (cigarettes) - Loss in value



Damage 7: Trim / covers: Floor covering - front left side - Burn hole (cigarettes) - Loss in value



Damage 8: Wing mirror - left side: Mirror glass - Scratch(es) - Replace




Damage 8: Wing mirror - left side: Mirror glass - Scratch(es) - Replace



Damage 9: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 9: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 10: Sill - right side: Sill - Deformed - Repair and paint



Damage 10: Sill - right side: Sill - Deformed - Repair and paint




Damage 10: Sill - right side: Sill - Deformed - Repair and paint




Damage 11: Body: Body - Damage by hail - repair according to calculation




Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation




Damage 11: Body: Body - Damage by hail - repair according to calculation




Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Damage 11: Body: Body - Damage by hail - repair according to calculation



Repainting 1: Roof rail - right side, Side panel - rear left side, Side panel - rear right side, Door - rear right side



Repainting 1: Roof rail - right side, Side panel - rear left side, Side panel - rear right side, Door - rear right side




Repainting 1: Roof rail - right side, Side panel - rear left side, Side panel - rear right side, Door - rear right side




Repainting 1: Roof rail - right side, Side panel - rear left side, Side panel - rear right side, Door - rear right side



Roof rail - right side: 181 μm



Side panel - rear left side: 198 μm



Side panel - rear right side: 365 μm



Door - rear right side: 215 μm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: TMBJG7NX4MY121653

Hersteller / Modell: SKODA SKODA Octavia Combi 2.0 TDI Style

Datum	KM-Stand	Beschreibung
03.06.2026	179.407	AU; Reparatur Sonstiges; Wartung Sonstiges
19.11.2025	158.171	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
01.11.2024	125.307	Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
24.05.2024	110.685	AU
28.02.2024	101.906	Bremse Sonstiges
10.11.2023	92.988	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
30.12.2022	61.986	Bremsflüssigkeit ern; Motoröl b. Wartung; Regelwartungsdienst
02.06.2022	28.191	Motoröl b. Wartung; Regelwartungsdienst