



Expertise

Protocol number: 46288369
Order No. / Reference: 26642218
Inspection date: 1 Jul 2026

Manufacturer: MAN
VIN: WMA03VUY2P9009506

Model: TGE 3.140 4X2F SB



Vehicle details	
Manufacturer / Type / Model / Equipment	
MAN TGE 3.140 4X2F SB	
Vehicle Identification number	WMA03VUY2P9009506
Mileage (Read)	94,578 km
First registration	2 Dec 2022
Number of holders	1
Next periodical technical inspection	12/2026
(Report on hand)	
Power / Engine displacement	103 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candy Weiß
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	3,300 km
Last service on / at	07/2025 at 90,029 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GR210225
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1516 / AYN 58721		
Emission standard	EURO6;WLTP;AR;PI/CI;N1 III, N2	fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/75 R16 113R	Winter tyres on Steel rim with wheel cover	Sonstige	9mm / 9mm
2)	205/75 R16 110R	Winter tyres on Steel rim with wheel cover	Semperit	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/75 R16 113R C	All-season tyres on Steel	Bridgestone	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Extra equipment

- Storage package 2
- Battery with increased capacity
- Fitting point
- Wooden floor in the cargo area with wheel arch cladding
- Center wheel cover with chrome emblem
- Steel spare wheel with road tires
- Side interior paneling in the cargo area made of plywood
- Rear step, across the entire width
- Driver and passenger airbags
- Cab doors, additionally with reinforced door seals
- All-season tyres
- MAN Media Van package with 4 speakers
- Smoker's version
- Rear View reversing camera
- Comfort seat, left
- Lashing rails in the cargo area

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Rear door - right side - dent(s) - Smart repair
2	Interior	Interior (Laderaumverkleidungen) - Differs from the original configuration - Loss in value
3	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Side panel - rear left side	Side panel - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents



Figure 19: Documents




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Damage 1: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair



Damage 1: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair



Damage 2: Interior: Interior (Laderaumverkleidungen) - Differs from the original configuration - Loss in value



Damage 2: Interior: Interior (Laderaumverkleidungen) - Differs from the original configuration - Loss in value



Damage 2: Interior: Interior (Laderaumverkleidungen) - Differs from the original configuration - Loss in value



Damage 2: Interior: Interior (Laderaumverkleidungen) - Differs from the original configuration - Loss in value



Damage 3: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 3: Vehicle glazing: Windscreen - Broken / torn - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WMA03VUY2P9009506

Hersteller / Modell: MAN MAN TGE 3.140 4X2F SB

Datum	KM-Stand	Beschreibung
25.02.2025	74.561	Reparatur Sonstiges; Reparatur Sonstiges
12.04.2024	48.353	Bremsinspektion vo + hi; Bremsbelagfühler ern; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne
29.01.2024	39.286	Regelwartungsdienst; Systemtest/Eigendiagnose
14.11.2023	32.075	Wartung Sonstiges
19.10.2023	30.337	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Systemtest/Eigendiagnose; Wartung Sonstiges