



Expertise

Protocol number: 46898786
Order No. / Reference: 26760582
Inspection date: 5 Aug 2026

Manufacturer: Ford

Model: S-Max 2.5 Duratec FHEV (7-Sitzer) TITANIUM

VIN: WF0JXXWPCHPC17810



Vehicle details

Manufacturer / Type / Model / Equipment

Ford S-Max 2.5 Duratec FHEV (7-Sitzer) TITANIUM

Vehicle Identification number	WF0JXXWPCHPC17810
Mileage (Read)	135,198 km
First registration	22 Mar 2023
Number of holders	1
Next periodical technical inspection	03/2028
(Report on hand)	

Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	2,488 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 1
Type of drive	Front drive
Type of vehicle	Saloon car

Colour / colour code	Agate Black Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black

Re-import	no
Vehicle with smoke odor	no
readiness to drive	Not roadworthy / moveable



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	28 %
Last service on / at	04/2026 at 122,754 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP515322
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	8566 / BVI 00097		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,350 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103Y	Summer tyres on Light alloy	Pirelli	3mm / 3mm
2)	235/55 R17 103Y	Summer tyres on Light alloy	Pirelli	3mm / 3mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103V	Winter tyres on Light alloy	Goodyear	4mm / 4mm
2)	235/55 R17 103V	Winter tyres on Light alloy	Goodyear	4mm / 4mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Equipment

- Klimaautomatik

Standard equipment

- Ambient lighting at the front
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Hill start assist
- Overhead console with glasses storage compartment and child observation mirror
- Lane keeping assist including lane keeping assist and driver fatigue warning
- Electronic parking brake
- Ford EasyFold: 2nd row seat backrests fold down electrically at the touch of a button.
- Luggage compartment cover
- Cruise control system with intelligent speed limiter
- Back window, heater
- Interior lighting with delay circuit
- Intelligent Protection System (IPS)
- Electric child safety lock
- Rear headrests (3)
- Steering wheel: Steering column, adjustable in height and reach
- Front center console with padded armrest
- Ford navigation system including Ford SYNC3
- Emergency brake light
- Front and rear parking pilot system
- Radio: Ford SYNC 3
- Tire Pressure Monitoring System (TPMS)
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Side skirts and bumpers painted in body color
- Seats: 2nd row of seats with 3 individual seats (FoldFlat System)
- Seats: Driver and passenger seats, 4-way manually adjustable
- 230 volt socket
- Trays on the front seatbacks
- LED daytime running lights
- Traffic sign recognition system
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats
- Cigarette lighter
- Anti-lock braking system (ABS)
- Attachment points for safety partition grilles
- Tires: 7.5 J x 17 alloy wheels (4) with 235/55 R 17 tires
- Third brake light
- Roof rails "aluminum look"
- Tachometer
- Electric windows front and rear
- High Beam Assist
- Ford Easy Fuel
- Ford Power start function with Ford Key Free system
- FordPass Connect including eCall and Wi-Fi hotspot
- Luggage compartment lighting
- Transmission: CVT automatic
- Rear window wiper
- Interior mirror, automatically dimming
- Isofix bracket
- Air conditioning with automatic temperature control
- Front headrests, 4-way height and tilt adjustable
- Steering wheel: Multifunction leather steering wheel
- Reading lights front and rear
- MyKey key system (individually programmable second key)
- Fog lights with LED technology
- Package: Winter
- Upholstery: Cloth
- Tire repair kit
- LED taillights
- Headlight dipped beam with switch-off delay including "greeting function"
- Electromechanical power steering
- Seats: 3rd row of seats with 2 individual seats (Easy FoldFlat System)
- Seats: Front sports seats
- Seats: Front seats can be heated individually and variably.
- Power outlet: 12-volt connection in the luggage compartment and in the center console
- Premium carpet floor mats, front and rear
- Lashing eyes in the luggage compartment
- Immobiliser
- Central locking with remote control



Extra equipment

- Detachable towbar (including ESP trailer stabilization)
- Paint finish: Metallic
- Rear leveling system, automatic
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Package: Business Package III (Sony navigation system incl. Ford SYNC 3 - Adaptive LED headlights with glare-free high beam - Adaptive cruise control with traffic jam assist and stop & go function - Pre-Collision Assist (distance display and distance warning, collision warning system and active emergency braking assist) - Front camera with "Split View" technology incl. reversing camera - Blind Spot Assist incl. Cross Traffic Alert - Electric, sensor-controlled tailgate and Ford Key Free System - Park Assist with automatic parking function)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Steering system	Steering wheel - Damaged - Smart repair
2	Rear bumper	Cover - bumper - rear - Damaged - Replace
3	Rear bumper	Rear bumper - Scratch(es) - Smart repair
4	Sill - left side	Sill - Scratch(es) - Smart repair
5	Body	B-pillar - right side - Dent / paintcoat damage - Smart repair
6	Side panel - rear right side	Sill - Dent / paintcoat damage - Smart repair
7	Instrument panel	Indicator light (Motorkontrollleuchte) - on - Perform diagnosis
8	Rear bumper	Rear bumper - Scratch(es) - Paint
9	Bonnet	Bonnet - Stone chips - Paint
10	Door - rear left side	Door - Scratch(es) - Paint
11	Front bumper	Front bumper - Stone chips - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.




Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Damage 1: Steering system: Steering wheel - Damaged - Smart repair



Damage 1: Steering system: Steering wheel - Damaged - Smart repair



Damage 2: Rear bumper: Cover - bumper - rear - Damaged - Replace



Damage 2: Rear bumper: Cover - bumper - rear - Damaged - Replace



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 3: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 4: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 4: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 5: Body: B-pillar - right side - Dent / paintcoat damage - Smart repair




Damage 5: Body: B-pillar - right side - Dent / paintcoat damage - Smart repair




Damage 6: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 6: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 6: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 6: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 7: Instrument panel: Indicator light (Motorkontrollleuchte) - on - Perform diagnosis




Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Bonnet: Bonnet - Stone chips - Paint



Damage 9: Bonnet: Bonnet - Stone chips - Paint



Damage 9: Bonnet: Bonnet - Stone chips - Paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint




Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 11: Front bumper: Front bumper - Stone chips - Paint



Damage 11: Front bumper: Front bumper - Stone chips - Paint



Damage 11: Front bumper: Front bumper - Stone chips - Paint



Damage 11: Front bumper: Front bumper - Stone chips - Paint



Damage 11: Front bumper: Front bumper - Stone chips - Paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0JXXWPCHPC17810

Hersteller / Modell: FORD FORD S-Max 2.5 Duratec FHEV (7-Sitzer) TITANIUM

Datum	KM-Stand	Beschreibung
01.04.2026	122.754	AU; Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
16.12.2025	112.694	Systemtest/Eigendiagnose
03.12.2025	110.954	Systemtest/Eigendiagnose
31.10.2025	106.928	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/ Eigendiagnose; Wartung Sonstiges; Zündkerzen ern
10.06.2025	89.447	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Systemtest/Eigendiagnose; Wartung Sonstiges
21.01.2025	73.606	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst
13.08.2024	54.658	Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Zündkerzen ern
29.02.2024	36.827	Motoröl b. Wartung; Ölfilter ern; Ölwechsel
10.11.2023	25.500	Regelwartungsdienst
12.09.2023	19.518	Motoröl b. Wartung; Ölfilter ern; Ölwechsel