



Expertise

Protocol number: 46382987
Order No. / Reference: 26555092
Inspection date: 7 Jul 2026

Manufacturer: Ford

Model: S-Max 2.0 EcoBlue Allrad Aut. TITANIUM

VIN: WF0JXXWPCJNM04469



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford S-Max 2.0 EcoBlue Allrad Aut. TITANIUM	
Vehicle Identification number	WF0JXXWPCJNM04469
Mileage (Read)	113,740 km
First registration	11 Oct 2022
Number of holders	1
Next periodical technical inspection	02/2028
(Report not on hand)	
Power / Engine displacement	140 kw / 1,995 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	Van
Colour / colour code	Frost-Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Grey



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	29,000 km
Last service on / at	06/2026 at 113,720 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GK854778
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BQS 00257		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,635 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103Y	Summer tyres on Light alloy	Pirelli	6mm / 6mm
2)	235/55 R17 103Y	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103V	Winter tyres on Light alloy	Pirelli	6mm / 6mm
2)	235/55 R17 103V	Winter tyres on Light alloy	Pirelli	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Ambient lighting at the front
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Hill start assist
- roof console
- Diesel particulate filter (DPF)
- Electronic Shifter
- Lane keeping assist including lane keeping assist and driver fatigue warning
- Electronic parking brake
- Ford EasyFold: 2nd row seat backrests fold down electrically at the touch of a button.
- luggage compartment cover
- Cruise control system with intelligent speed limiter
- Back window, heater
- Interior lighting with delay circuit
- Intelligent security system
- Electric child safety lock
- Steering wheel: Steering column, adjustable in height and reach
- Front center console with padded armrest
- Ford navigation system including Ford SYNC 3 with AppLink, touchscreen, DAB/DAB+ and FordPass Connect
- Package: Winter
- Upholstery: Cloth
- Tire Pressure Monitoring System (TPMS)
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Electromechanical power steering
- Seats: Flexible seating system "FoldFlatSystem (FFS)"
- Seats: Front sports seats
- Start-stop system
- Power outlet: 12-volt connection in the luggage compartment and in the center console
- LED daytime running lights
- Traffic sign recognition system
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats
- Cigarette lighter
- All-wheel drive
- Anti-lock braking system (ABS)
- Attachment points for safety partition grilles
- Tires: 7.5 J x 17 alloy wheels (4) with 235/55 R 17 tires
- third brake light
- Roof rails "aluminum look"
- Tachometer
- Driver information system display 25.4 cm color
- Electric windows front and rear
- High Beam Assist
- Ford Easy Fuel
- Ford Power Start function
- Ford Power start function with Ford Key Free system
- Luggage compartment lighting
- Transmission: 8-speed automatic transmission
- rear window wiper
- Interior mirror, automatically dimming
- Isofix bracket
- Air conditioning with automatic temperature control
- Steering wheel: Multifunction leather steering wheel
- Reading lights front and rear
- MyKey key system (individually programmable second key)
- Fog light
- Emergency brake light
- Front and rear parking pilot system
- Tire repair kit
- LED taillights
- Headlight dipped beam with switch-off delay including "greeting function"
- Seats: Driver and passenger seats, 4-way manually adjustable
- Seats: Front seats can be heated individually and variably.
- 230 volt socket
- Bumpers painted in body color
- Trays on the front seatbacks
- Premium carpet floor mats, front and rear
- Lashing eyes in the luggage compartment
- Immobiliser
- Central locking with remote control



Extra equipment

- Electrically swiveling towbar (including ESP trailer stabilization)
- Fuel-operated auxiliary heater (including remote control and heated windscreen)
- Paint finish: Frost White
- Safety partition net behind the 2nd row of seats
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Sunshades in the rear side doors (manual)
- Package: Business I (Ford navigation system incl. Ford SYNC 3, AppLink, 20.3 cm touchscreen, DAB/DAB+, voice control, support for Android Auto and Apple CarPlay, Bluetooth hands-free system and audio streaming, FordPass Connect, eCall emergency call system, live traffic information, Wi-Fi hotspot, radio/CD player, 2 USB ports, 8 speakers, steering wheel controls, LED daytime running lights, park assist with automatic parallel and perpendicular parking function, pre-collision assist, forward collision warning, active emergency braking, reversing camera)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Side panel - rear right side	Sill - dent(s) - Smooth repair work
3	Trim / covers	Door trim - rear left side - dent(s) - Smart repair
4	Trim / covers	Door trim - rear right side - Scratched - Smart repair
5	Sill - left side	Sill - Scratch(es) - Smart repair
6	Misc.	Misc. (Sonnenblende Heck) - Holes - Replace
7	Mudguard - right side	Mudguard - right side - Stone chips - Smart repair
8	Front bumper	Front bumper - Stone chips - Smart repair
9	Trim / covers	Boot lining - Scratched - Loss in value
10	Trim / covers	Boot lid - interior trim - Scratched - Replace
11	Front bumper	Spoiler - Scratched - Repair and paint
12	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 16 Sept 2024	4.146,65 €



Paint coat thickness measurement

Roof	100 µm	Roof rail - left side	98 µm
Roof rail - right side	107 µm	Boot lid / rear door	104 µm
Mudguard - left side	104 µm	Mudguard - right side	111 µm
Bonnet	105 µm	Side panel - rear left side	101 µm
Side panel - rear right side	100 µm	Door - rear left side	110 µm
Door - rear right side	102 µm	Door - front left side	112 µm
Door - front right side	109 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Mounted tyres



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.




Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.




Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.




Figure 41: Misc.



Figure 42: Misc.



Figure 43: Misc.



Figure 44: Misc.



Figure 45: Misc.




Figure 46: Misc.




Figure 47: Misc.




Damage 2: Side panel - rear right side: Sill - dent(s) - Smooth repair work




Damage 2: Side panel - rear right side: Sill - dent(s) - Smooth repair work




Damage 3: Trim / covers: Door trim - rear left side - dent(s) - Smart repair



Damage 3: Trim / covers: Door trim - rear left side - dent(s) - Smart repair



Damage 3: Trim / covers: Door trim - rear left side - dent(s) - Smart repair



Damage 4: Trim / covers: Door trim - rear right side - Scratched - Smart repair



Damage 4: Trim / covers: Door trim - rear right side - Scratched - Smart repair




Damage 5: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 5: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 6: Misc.: Misc. (Sonenblende Heck) - Holes - Replace



Damage 6: Misc.: Misc. (Sonenblende Heck) - Holes - Replace



Damage 7: Mudguard - right side: Mudguard - right side - Stone chips - Smart repair



Damage 7: Mudguard - right side: Mudguard - right side - Stone chips - Smart repair




Damage 8: Front bumper: Front bumper - Stone chips - Smart repair



Damage 8: Front bumper: Front bumper - Stone chips - Smart repair



Damage 8: Front bumper: Front bumper - Stone chips - Smart repair



Damage 9: Trim / covers: Boot lining - Scratched - Loss in value



Damage 9: Trim / covers: Boot lining - Scratched - Loss in value



Damage 9: Trim / covers: Boot lining - Scratched - Loss in value



Damage 9: Trim / covers: Boot lining - Scratched - Loss in value




Damage 10: Trim / covers: Boot lid - interior trim - Scratched - Replace



Damage 10: Trim / covers: Boot lid - interior trim - Scratched - Replace



Damage 10: Trim / covers: Boot lid - interior trim - Scratched - Replace



Damage 10: Trim / covers: Boot lid - interior trim - Scratched - Replace



Damage 11: Front bumper: Spoiler - Scratched - Repair and paint



Damage 11: Front bumper: Spoiler - Scratched - Repair and paint



Damage 11: Front bumper: Spoiler - Scratched - Repair and paint



Damage 11: Front bumper: Spoiler - Scratched - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Wear and tear 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 2: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 2: Vehicle glazing: Windscreen - Stone chips - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0JXXWPCJNM04469

Hersteller / Modell: FORD FORD S-Max 2.0 EcoBlue Allrad Aut. TITANIUM

Datum	KM-Stand	Beschreibung
15.05.2026	112.331	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
16.02.2026	104.985	AU; Batterie ern; Systemtest/Eigendiagnose
06.06.2025	83.720	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
06.05.2025	81.398	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
13.08.2024	60.833	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
22.09.2023	30.709	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges