



Expertise

Protocol number: 46563853
Order No. / Reference: 26689447
Inspection date: 16 Jul 2026

Manufacturer: Skoda
VIN: TMBGF7NY8PF050222

Model: Enyaq Coupe iV RS



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Enyaq Coupe iV RS	
Vehicle Identification number	TMBGF7NY8PF050222
Mileage (Read)	54,590 km
First registration	17 May 2023
Number of holders	1
Next periodical technical inspection	05/2026
(Report not on hand)	
Power / Engine displacement	77 kw /
Fuel type / Cylinder	Electric / 0
Gearbox / Number of gears	Direct drive / 1
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Black-Magic Perleffekt
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	324 Tag(e)
Last service on / at	06/2025 at 40,838 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT098577
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8004 / AWZ 00011		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	2,750 kg	Empty weight	

Tyres			
Mounted tyres			
#	Tyre size	Type of tyre	Tread depth
1)	235/50 R20 100T	Summer tyres on Light alloy	6mm / 6mm
2)	235/50 R20 100T	Summer tyres on Light alloy	6mm / 6mm

Replacement			
Typ	Tyre size	Type of tyre	Tread depth
	Tirefit	Expiration date 03/2027	

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • Storage compartments • Airbag, driver and passenger • Airbag, front side airbags • Permanent all-wheel drive • Anti-lock braking system (ABS) • Evasive steering assist including turn assist • Exterior mirrors in black, door handles painted in body color • Hill start assist • Digital instrument cluster (Virtual Cockpit) • E-Sound • Increased battery charging power max. 125 kW • Driving profile selection • Electric windows front and rear • Transmission: 1-speed (EV) • Tinted windows • Heated rear window • Isofix anchorage on the front passenger seat • Child safety locks on the rear doors • Removable boot cover • Charging cable for AC charging stations (Mode 3 charging cable, Type 2, 16A) • Steering wheel adjustable for height and reach • Multi-collision brake • Package: ADVANCED (RS) • Front and rear parking sensors • Rain sensor and driving light assistant with coming and leaving home function • Wheels: 20" Taurus Aero Black alloy wheel • Rear seat backrest split 60:40, foldable • Seat belts • Skoda Care Connect • 12V socket - in the trunk • Immobiliser | <ul style="list-style-type: none"> • Airbag, center airbag front • Airbag, front and rear head airbags • acoustic windscreen • Trailer hitch preparation • Traction control (ASR) • Electrically adjustable, heated and folding exterior mirrors, including automatic dimming. • Outdoor temperature display • Design RS Lounge • Third brake light • Electronic parking brake including auto-hold function • ESC Electronic Stability Control • Chassis: Sport chassis • Front radar assistant with pedestrian and cyclist detection and city emergency braking function • Head-up display • Automatic interior mirror dimming • Isofix anchorage on the outer rear seats including top tether • Rear headrests are height-adjustable, front headrests are integrated (sports seat) • LED taillights • Steering wheel: Heated sports leather steering wheel with multifunction buttons • Panoramic glass roof • Radio: Infotainment system with capacitive 13" color display • Tire pressure monitoring • Rear view camera • Power steering • Safety lights in the front side doors • Speed limiter • Traffic sign recognition • heat pump |
|--|---|

Extra equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • Swiveling trailer hitch (including trailer stabilization) • Package: Seating Comfort PLUS | <ul style="list-style-type: none"> • Paint finish: Pearl effect |
|--|--|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Rear bumper	Spoiler - Scratched - Smart repair
2	Rear bumper	Rear bumper - Scratched - Smart repair
3	Door - front left side	Door edge - Scratched - Smart repair
4	Side panel - rear left side	Side panel (Aufpolieren) - Scratched - Smart repair

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction
2	Door - rear left side	Door edge - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 19 Sept 2024	1.183,97 €
2	Roof, Provided by user / customer, from 19 Sept 2024	2.442,12 €

Repainting

No.	Repainting
1	Door - front left side

Paint coat thickness measurement

Door - front left side	179 µm
------------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.




Figure 31: Misc.




Figure 32: Misc.




Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Damage 1: Rear bumper: Spoiler - Scratched - Smart repair



Damage 1: Rear bumper: Spoiler - Scratched - Smart repair




Damage 1: Rear bumper: Spoiler - Scratched - Smart repair



Damage 1: Rear bumper: Spoiler - Scratched - Smart repair




Damage 2: Rear bumper: Rear bumper - Scratched - Smart repair




Damage 2: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 3: Door - front left side: Door edge - Scratched - Smart repair




Damage 3: Door - front left side: Door edge - Scratched - Smart repair




Damage 3: Door - front left side: Door edge - Scratched - Smart repair



Damage 4: Side panel - rear left side: Side panel (Aufpolieren) - Scratched - Smart repair



Damage 4: Side panel - rear left side: Side panel (Aufpolieren) - Scratched - Smart repair




Wear and tear 1: Front bumper: Front bumper - Stone chips - No deduction



Wear and tear 1: Front bumper: Front bumper - Stone chips - No deduction



Wear and tear 2: Door - rear left side: Door edge - Scratched - No deduction



Wear and tear 2: Door - rear left side: Door edge - Scratched - No deduction



Repainting 1: Door - front left side



Repainting 1: Door - front left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: TMBGF7NY8PF050222
Hersteller / Modell: SKODA SKODA Enyaq Coupe iV RS

Datum	KM-Stand	Beschreibung
23.06.2025	40.838	Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst