



Expertise

Protocol number: 46872489
Order No. / Reference: 26754769
Inspection date: 4 Aug 2026

Manufacturer: Ford

Model: Focus Turnier 2.0 EcoBlue Start-Stopp-System Aut.
COOL&CONNECT

VIN: WF0PXXGCHPLL42683



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Focus Turnier 2.0 EcoBlue Start-Stopp-System Aut. COOL&CONNECT	
Vehicle Identification number	WF0PXXGCHPLL42683
Mileage (Read)	194,236 km
First registration	23 Nov 2020
Number of holders	1
Next periodical technical inspection	03/2028 (Report not on hand)
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Polar-Silber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black
Re-import	no
readiness to drive	Roadworthy



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	38 %
Last service on / at	01/2026 at 182,557 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FY018258
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BQQ 00177		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,105 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Light alloy	Bridgestone	6mm / 6mm
2)	205/60 R16 92H	Winter tyres on Light alloy	Goodyear	4mm / 4mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92V	Summer tyres on Light alloy	Continental	3mm / 3mm
2)	205/60 R16 92V	Summer tyres on Light alloy	Continental	3mm / 3mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2024		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Equipment

- Klimaanlage

Standard equipment

- Airbag: Passenger airbag deactivation
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Tires: 6.5 J x 16 alloy wheels (4) with 205/60 R 16 tires
- Fabric headliner
- Roof spoiler painted in car color
- Tachometer
- Driver information system
- Lane keeping assist including lane keeping assist
- Electric parking brake with auto-hold function
- FordPass Connect including eCall, live traffic information (only with navigation) and Wi-Fi hotspot
- Speed limiter
- Transmission: 8-speed automatic transmission
- Back window, heater
- Interior lighting with LED technology
- Intelligent security system
- air conditioning, manual
- Charging station for mobile devices (inductive)
- Steering wheel: Leather steering wheel, 3-spoke design
- Center console "Premium" front
- Navigation: Ford Navigation, Ford SYNC 3 with AppLink, 8" touchscreen (20.3 cm) with DAB/DAB+
- Front and rear parking pilot system
- Upholstery: Cloth
- Pre-Collision Assist
- Tire Pressure Monitoring System (TPMS)
- Headlight assistant with day/night sensor
- Seats: Passenger seat, 2-way adjustable
- Seats: Rear seat backrest
- Start-stop system
- Lashing eyes in the luggage compartment
- Electronic immobilizer
- Heat-insulating glazing, tinted
- Additional heating

Extra equipment

- Swiveling towbar (incl. ESP trailer stabilization)
- Package: Winter (heated windscreen - heated steering wheel - individually and variably heated front seats)

- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Mounting points behind the second row of seats
- Chrome decor
- Roof rails, aluminum
- Diesel particulate filter (DPF)
- Electronic Safety and Stability Program (ESP)
- Driving mode switch, selective
- Electric windows front and rear
- Ford ECO-Coach
- Luggage compartment lighting
- Luggage compartment floor, adjustable in two ways
- Cruise control
- Illuminated glove compartment
- rear window wiper
- Instrument lighting, adjustable
- Isofix bracket
- Headrests: 2 front and 3 rear, height adjustable
- LED daytime running lights
- Adjustable steering column
- MyKey key system (individually programmable second key)
- Fog light
- Emergency brake light
- Pollen filter and dust filter
- Post-Collision Assist
- Tire repair kit
- Reversing camera with "Split View" technology
- Electromechanical power steering
- Seats: Driver's seat height adjustable
- Seats: Front sports seats with enhanced lateral support
- 12-volt power outlet in the luggage compartment
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats
- Central/Double Locking

- Paint finish: Metallic
- Safety partition net to separate passenger and luggage compartments



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Door - front right side	Door - dent(s) - Smooth repair work
3	Mudguard - left side	Mudguard - left side - dent(s) - Smooth repair work
4	Side panel - rear left side	Sill - dent(s) - Smart repair
5	Interior	Interior - Odour - Ozone treatment
6	Bonnet	Bonnet (4 Dellen) - dent(s) - Smooth repair work
7	Rear bumper	Rear bumper - Scratch(es) - Paint
8	Front bumper	Spoiler (Linke und rechte seite) - Scratch(es) - Replace
9	Roof	Roof - dent(s) - repair according to calculation
10	Front bumper	Front bumper - Scratch(es) - Paint
11	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint
12	Door - rear left side	Door - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front right side - Scratch(es) - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 18 Mar 2025	2.633,46 €
2	Rear, Provided by user / customer, from 2 Oct 2025	8.901,62 €

Repainting

No.	Repainting
1	Roof, Roof rail - left side, Roof rail - right side, Boot lid / rear door, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Side panel - rear right side, Door - rear left side, Door - rear right side, Door - front left side, Door - front right side



Paint coat thickness measurement

Roof	267 µm	Roof rail - left side	212 µm
Roof rail - right side	205 µm	Boot lid / rear door	264 µm
Mudguard - left side	208 µm	Mudguard - right side	219 µm
Bonnet	230 µm	Side panel - rear left side	237 µm
Side panel - rear right side	209 µm	Door - rear left side	215 µm
Door - rear right side	238 µm	Door - front left side	213 µm
Door - front right side	229 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Für den montierten Radsatz wurde kein Nachweis erbracht.

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument cluster



Figure 9: Instrument panel



Figure 10: Interior 360° view



Figure 11: Cargo area



Figure 12: VIN



Figure 13: Mounted tyres




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 3: Mudguard - left side: Mudguard - left side - dent(s) - Smooth repair work



Damage 3: Mudguard - left side: Mudguard - left side - dent(s) - Smooth repair work



Damage 4: Side panel - rear left side: Sill - dent(s) - Smart repair



Damage 4: Side panel - rear left side: Sill - dent(s) - Smart repair



Damage 6: Bonnet: Bonnet (4 Dellen) - dent(s) - Smooth repair work



Damage 6: Bonnet: Bonnet (4 Dellen) - dent(s) - Smooth repair work



Damage 6: Bonnet: Bonnet (4 Dellen) - dent(s) - Smooth repair work



Damage 6: Bonnet: Bonnet (4 Dellen) - dent(s) - Smooth repair work



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Front bumper: Spoiler (Linke und rechte Seite) - Scratch(es) - Replace



Damage 8: Front bumper: Spoiler (Linke und rechte Seite) - Scratch(es) - Replace



Damage 8: Front bumper: Spoiler (Linke und rechte seite) - Scratch(es) - Replace



Damage 8: Front bumper: Spoiler (Linke und rechte seite) - Scratch(es) - Replace




Damage 9: Roof: Roof - dent(s) - repair according to calculation



Damage 9: Roof: Roof - dent(s) - repair according to calculation




Damage 9: Roof: Roof - dent(s) - repair according to calculation



Damage 9: Roof: Roof - dent(s) - repair according to calculation




Damage 9: Roof: Roof - dent(s) - repair according to calculation



Damage 10: Front bumper: Front bumper - Scratch(es) - Paint




Damage 10: Front bumper: Front bumper - Scratch(es) - Paint



Damage 11: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - rear left side: Door - Scratch(es) - Paint




Damage 12: Door - rear left side: Door - Scratch(es) - Paint



Wear and tear 1: Wheel / tyres: Alloy rim - front right side - Scratch(es) - No deduction



Wear and tear 1: Wheel / tyres: Alloy rim - front right side - Scratch(es) - No deduction



Roof: 267 µm



Roof rail - left side: 212 µm




Roof rail - right side: 205 µm



Boot lid / rear door: 264 µm



Mudguard - left side: 208 µm



Mudguard - right side: 219 µm




Bonnet: 230 µm



Side panel - rear left side: 237 µm



Side panel - rear right side: 209 µm



Door - rear left side: 215 µm



Door - rear right side: 238 µm



Door - front left side: 213 µm



Door - front right side: 229 µm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0PXXGCHPLL42683

Hersteller / Modell: FORD FORD Focus Turnier 2.0 EcoBlue Start-Stopp-System Aut.
COOL&CONNECT

Datum	KM-Stand	Beschreibung
18.03.2026	186.246	AU
22.01.2026	182.557	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
18.10.2024	148.869	Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Keilriemen ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges; Wasserpumpe ern
14.11.2023	122.977	AU; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
14.09.2022	87.612	Bremsflüssigkeit ern; Motoröl b. Wartung; Regelwartungsdienst
22.02.2022	58.447	Kleine Inspektion; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Wartung Sonstiges
22.11.2021	43.902	Bremsscheiben + Klötze h
05.08.2021	28.659	Kleine Inspektion; Motoröl b. Wartung