



Expertise

Protocol number: 46381892
Order No. / Reference: 26529119
Inspection date: 7 Jul 2026

Manufacturer: Kia

Model: Ceed SW 1.6 GDI DCT OPF Plug-in-Hybrid Spirit

VIN: U5YH581AGPL038978



Vehicle details	
Manufacturer / Type / Model / Equipment	
Kia Ceed SW 1.6 GDI DCT OPF Plug-in-Hybrid Spirit	
Vehicle Identification number	U5YH581AGPL038978
Mileage (Read)	73,085 km
First registration	26 Jun 2023
Number of holders	1
Next periodical technical inspection	06/2026
(Report not on hand)	
Power / Engine displacement	77 kw / 1,580 ccm
Fuel type / Cylinder	Hybr.B/E ext.aufll / 4
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Zillinaschwarz Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Grey
Re-import	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	Available / incomplete	Next maintenance in	0 km
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY684991
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	2234 / ABD 00014		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,030 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	All-season tyres on Light alloy	Continental	5mm / 5mm
2)	205/55 R16 91H	All-season tyres on Light alloy	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- ABS (Anti-lock Braking System) with electronic brake force distribution
- Airbag: 2 curtain airbags
- Active brake light (Emergency Stop Signal, ESS)
- Alarm system
- Highway Driving Assist (HDA)
- Electrically folding exterior mirrors
- Exterior mirrors with integrated turn signals
- On-board computer
- Overhead console with glasses compartment
- Roof rails
- Tachometer
- Drive Mode Select
- EcoDynamics (start-stop system ISG)
- Electronic Stability Control (ESC) with Traction Control System (TCS)
- High beam assist
- floor mat set
- luggage compartment cover
- Adaptive cruise control including Stop&Go function
- Transmission: 6-speed direct-shift gearbox (DCT)
- Back window, heater
- Auto-dimming interior rearview mirror
- ISOFIX mounts
- Headrests on all seats are height-adjustable.
- LED fog lights
- LED daytime running lights at the rear
- Heated steering wheel
- Steering wheel: Multifunction steering wheel
- front center armrest
- Navigation: Kia map navigation (10.25 inch)
- Otto particulate filter
- Rear parking sensors (PDW-R)
- Cross-traffic alert system for detecting vehicles in the blind spot
- Radio accessories: 2 tweeters
- Radio accessories: DAB radio
- Rain sensor
- Tire repair kit
- Rear view camera
- Front seat belts are height-adjustable
- Seats: Driver's seat height adjustable
- Seats: Rear bench seat split 60:40, foldable
- Smart Key and Start Button
- Sun visors with illuminated makeup mirrors
- Lane Follow Assist (LFA)
- Supervision instrument display with a 10.7 cm (4.2 inch) screen diagonal
- Traffic sign recognition for speed limits
- Immobiliser
- thermal insulation glazing
- Airbag: 2 front airbags
- Airbag: 2 side airbags
- Active lane keeping assist with corrective steering intervention (Lane Keep Assist, LKA)
- Safe Exit Warner (SEW)
- Heated exterior mirrors
- Electrically adjustable exterior mirrors
- Hill Start Assist Control (HAC)
- Brake Assist (BAS)
- Front overhead console with reading lights and central lighting
- Third brake light (LED) in the rear spoiler
- twilight sensor
- Inserts in glossy black
- Energy regeneration system
- Electric windows front and rear
- Front collision warning
- Luggage net eyelets
- Luggage compartment lighting
- Cruise control, navigation-based
- Front cup holder
- rear window wiper
- Rear Seat Alert (RSA)
- Automatic climate control, 2 zones, with anti-fog sensor
- LED headlights
- LED taillights
- LED daytime running lights at the front
- Steering wheel: Leather steering wheel
- Armrest - centre, rear
- Fatigue warning
- Online services UVO CONNECT with Kia Live
- Electronic parking brake
- Upholstery: Cloth
- Radio accessories: 2 front speakers
- Radio accessories: 2 rear speakers
- Radio accessories: Bluetooth hands-free system
- Radio accessories: USB interface
- Tire pressure monitoring system (TPMS)
- Wheels: 16-inch alloy wheels with 205/55 R16 tires
- Power steering
- Seats: Passenger seat height adjustable
- Seats: Lumbar support
- Seats: Heated front seats
- Smartphone interface Android Auto and Apple CarPlay with voice control
- 12V power outlet
- Blind Spot Assist with active steering and braking intervention (BCA)
- Virtual Engine Sound System (VESS) for pedestrian protection
- Central locking with remote control



Extra equipment

- All-weather tires
- Type 2 to Type 2 charging cable
- Package: P4 - Seating comfort (seat covers in fabric-leather combination (with high-quality imitation leather): Black - driver's seat electrically adjustable with memory function - rear seat heating (outer seats) - rear bench seat foldable in a 40:20:40 ratio)
- Paint finish: Metallic paint
- Package: P1 - Technology (Intelligent parking system (Parking Assist-Perpendicular Reverse, PA-PDR) with parking assistant for parallel and perpendicular parking as well as parallel exiting - Inductive charging station (for smartphones) in the center console with charging indicator - Electric tailgate, sensor-controlled - Front parking sensors (PDW))

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Door - front right side	Door (Türfeststeller, Schraube lose) - Malposition - Un- / install
2	Vehicle glazing	Rear window - Glued / labelled - Remove
3	Sill - left side	Sill - dent(s) - Smooth repair work
4	Mudguard - right side	Mudguard - right side - Scratch(es) - Smart repair
5	Misc.	Main inspection - Due - Perform
6	Misc.	Inspection / maintenance (keine Historie) - Due - Perform
7	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Replace
8	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Replace
9	Bonnet	Bonnet - Stone chips - Paint
10	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint
11	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
12	Front bumper	Front bumper - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Rear bumper	Rear bumper - Scratch(es) - No deduction
3	Door - rear left side	Door - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side right, Provided by user / customer, from 20 Feb 2024	8.001,30 €



Repainting

No. Repainting

1 Side panel - rear right side, Door - front right side

Paint coat thickness measurement

Side panel - rear right side	659 µm	Door - front right side	177 µm
------------------------------	--------	-------------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - front



Figure 7: Interior - rear



Figure 8: Interior - rear



Figure 9: Instrument cluster



Figure 10: Instrument panel



Figure 11: Interior 360° view



Figure 12: Cargo area



Figure 13: VIN



Figure 14: Mounted tyres



Figure 15: Mounted tyres



Figure 16: Documents




Figure 17: Documents



Figure 18: Navigation



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.



Figure 41: Misc.



Figure 42: Misc.



Figure 43: Misc.



Figure 44: Misc.



Figure 45: Misc.






Figure 46: Misc.




Damage 1: Door - front right side: Door (Türfeststeller, Schraube lose) - Malposition - Un- / install




Damage 1: Door - front right side: Door (Türfeststeller, Schraube lose) - Malposition - Un- / install



Damage 2: Vehicle glazing: Rear window - Glued / labelled - Remove



Damage 2: Vehicle glazing: Rear window - Glued / labelled - Remove



Damage 3: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 3: Sill - left side: Sill - dent(s) - Smooth repair work




Damage 4: Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair



Damage 4: Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair



Damage 4: Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair



Damage 6: Misc.: Inspection / maintenance (keine Historie) - Due - Perform



Damage 7: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Replace



Damage 7: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Replace



Damage 7: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Replace



Damage 8: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace




Damage 8: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace




Damage 8: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 9: Bonnet: Bonnet - Stone chips - Paint




Damage 9: Bonnet: Bonnet - Stone chips - Paint



Damage 9: Bonnet: Bonnet - Stone chips - Paint




Damage 9: Bonnet: Bonnet - Stone chips - Paint




Damage 9: Bonnet: Bonnet - Stone chips - Paint




Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 11: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 11: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 11: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 12: Front bumper: Front bumper - Broken / torn - Replace



Damage 12: Front bumper: Front bumper - Broken / torn - Replace



Damage 12: Front bumper: Front bumper - Broken / torn - Replace



Damage 12: Front bumper: Front bumper - Broken / torn - Replace



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 2: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 3: Door - rear left side: Door - Scratch(es) - No deduction



Side panel - rear right side: 659 µm



Side panel - rear right side: 659 µm



Door - front right side: 177 µm



Door - front right side: 177 µm