



Expertise

Protocol number: 46404128
Order No. / Reference: 26539896
Inspection date: 8 Jul 2026

Manufacturer: Ford

Model: Kuga 2.5 Duratec PHEV VIGNALE

VIN: WF0FXXWPMHLD28332



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Kuga 2.5 Duratec PHEV VIGNALE	
Vehicle Identification number	WF0FXXWPMHLD28332
Mileage (Read)	103,787 km
First registration	25 Mar 2021
Number of holders	2
Next periodical technical inspection	02/2028
(Report on hand)	
Power / Engine displacement	112 kw / 2,488 ccm
Fuel type / Cylinder	Hybrid P / E ext. charg. / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Mineral-Silber Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	11 %
Last service on / at	09/2025 at 91,778 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FV091511
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BTM 00007		
Emission standard	EURO6;WLTP;DG;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,320 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/60 R18 104V	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	225/60 R18 104V	Winter tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/60 R18 104V	Summer tyres on Light alloy	Hankook	5mm / 4mm
2)	225/60 R18 104V	Summer tyres on Light alloy	Hankook	5mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2024		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- Acoustic Vehicle Alerting System (AVAS)
- Anti-lock braking system
- Electrically adjustable, heated and folding exterior mirrors (VIGNALE) (painted in body color - with memory function - with integrated turn signals and ambient lighting)
- Tires: Tire repair kit (maximum speed 80 km/h when used)
- Fabric headliner
- Roof rails, silver-colored
- 12.3-inch digital instrument panel
- Tachometer
- Electronic Stability Program (ESP) (with hill start assist, traction control and emergency brake assist)
- Lane keeping assist including lane keeping assist
- Electric parking brake with auto hold function
- Ford Easy Fuel (Ford Easy Fuel comfort refueling system (Eliminates the need for a separate internal fuel cap and prevents misfueling by detecting the size difference between petrol and diesel nozzles. The filler neck only opens when the correct fuel is used.))
- Luggage compartment cover, roller blind, removable
- Luggage compartment lighting
- Transmission: continuously variable automatic transmission (CVT)
- Heated rear window
- rear window wiper
- Interior mirror, automatically dimming
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- Front and rear headrests (5) height adjustable
- Paint finish: Mineral Silver Metallic
- LED taillights
- Steering wheel: Steering wheel, 3-spoke design, in Sensico synthetic leather
- Front center console with integrated armrest (2 front cup holders (illuminated) - 12-volt socket)
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Package: Winter II (Heated windscreen - Heated leather steering wheel - Heated outer rear seats)
- Pedal assembly with aluminum surface
- Upholstery: Premium leather upholstery (seat center panels and side bolsters in leather - driver's seat 10-way electrically adjustable with memory function and electrically adjustable lumbar support)
- Radio accessories: B&O Sound System (575 Watt premium sound system with 10 speakers, including subwoofer - based on the renowned sound and design expertise of Bang & Olufsen)
- Tire Pressure Monitoring System (TPMS)
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Ambient lighting (front including front door storage, footwell and cup holder lighting with LED technology)
- Passenger airbag deactivation
- Tires: 7.5 J x 18 light alloy wheels (4) in 5x4 spoke design Luster Nickel premium paint finish (with tires 225/60 R 18)
- third brake light
- Overhead console with glasses storage compartment
- Roof spoiler (painted in car color)
- Dual exhaust system
- Front door sill trims, Vignale design
- Selective driving mode switch (5 driving modes to choose from: Normal, Sport, Eco, Slippery and Unpaved Roads)
- Electric front and rear windows (with quick-down function including all-around closing function)
- Ford EcoCoach (shows the efficiency of current driving behavior)
- Ford Power Start function & Ford Key Free system (keyless locking/unlocking)
- FordPass Connect (including eCall, live traffic information and Wi-Fi hotspot)
- Cruise control
- Illuminated glove compartment
- Electric tailgate, sensor-controlled (opens and closes via foot movement)
- Inductive charging station for mobile devices
- Intelligent Protection System (IPS) (front airbag for driver and front passenger - front and rear head and shoulder airbags - side airbag for driver and front passenger - seat belt tensioners and force limiters in the front and on the outer seats of the 2nd row - 3-point seat belts in all seats, height-adjustable in the front - warning system for unfastened driver and front passenger seat belts)
- Charging cable (for household sockets and public charging stations)
- Steering column, adjustable in height and reach
- Rear center armrest with cup holder
- MyKey key system (individually programmable second key)
- Navigation system: Ford navigation system incl. Ford SYNC 3 (AppLink, Android Auto, Apple CarPlay - 8" touchscreen (20.3cm screen diagonal) - DAB/DAB+ radio reception (Digital Audio Broadcasting) - 6 speakers - Steering wheel controls - Bluetooth® hands-free system and audio streaming - 2 USB ports - Voice control for audio and telephone - SMS text-to-speech function - Road map for Europe)
- Post-Collision Assist
- Pre-Collision Assist (including forward alert system (FA) with pedestrian and bicycle detection - active from approx. 5 km/h to 130 km/h, pedestrian and bicycle detection up to approx. 80 km/h.)
- Wheel arch trim painted in vehicle color
- Rear view camera
- Headlights with delayed shut-off
- Side windows from the 2nd row of seats and rear window, dark tinted.



- Power steering (electro-mechanical, speed-dependent (EPAS - Electric Power Assisted Steering))
- Seats: Rear bench seat, sliding, with split-folding backrest
- Seats: Front sports seats with integrated headrests
- Sun visor on driver and passenger side
- Power outlet: 12-volt connection in the luggage compartment
- Immobiliser

- Seats: Map pockets on the driver's and front passenger's seat backrests
- Seats: Front seats, individually and variably heated
- Static LED headlights (high beam assist - LED fog lights)
- Carpet floor mats front and rear
- Electric door child safety lock
- Central locking with remote control and remote luggage compartment release

Extra equipment

- Swiveling towbar (ESP trailer stabilization function)
- Package: Driver Assistance Package
- Safety partition net (including attachment points behind the first and second rows of seats)
- Reversible luggage compartment mat
- Panoramic sliding sunroof, electric, including roof console with glasses storage compartment
- Cigarette lighter and ashtray in the center console

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Wing mirror - left side	Cap - Scratch(es) - Smart repair
3	Wing mirror - right side	Cap - Scratched - Smart repair
4	2nd wheel set	1 alloy rim - Scratch(es) - Loss in value
5	Bonnet	Insulation lining - Damage caused by marten / rodent - Replace
6	Engine	Engine cover - Damage caused by marten / rodent - Replace
7	Steering system	Steering wheel - Glued / labelled - Replace
8	Wing mirror - right side	Mirror housing - Scratch(es) - Replace
9	Rear bumper	Rear bumper - Scratched - Paint
10	Side panel - rear left side	Side panel - Scratch(es) - Paint
11	Boot lid / rear door	Boot lid - dent(s) - Repair and paint

Wear and tear

No.	Component group	Description
1	Door - rear left side	Door - Scratch(es) - No deduction
2	Interior	Interior - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Front bumper	Front bumper - Stone chips - No deduction
5	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Side - left, Provided by user / customer, from 3 Jul 2024	5.523,23 €

Repainting

No.	Repainting
1	Bonnet, Door - front left side, Professionally carried out

Paint coat thickness measurement

Bonnet	262 µm	Door - front left side	169 µm
--------	--------	------------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.
- Der Winterradsatz ist kein Bestandteil der Ausstattungsliste.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents

		(1)	Fz.-Ident.-Nr.: WF0FXXWPM
		(5)	Fz.-Klasse: M1 / AF
			HSN: 8566
			TSN / VSN: BTM / 0000
		(4)	Kilometerstand: 99094 km
			letzte HU: 03.24
unter Untersuchungsart geprüft und abschließend folgendes Ergebnis fest			
ette	(8) Nächste HU:		Wie
lt	02.28		
	Berechn. Druck (bar)	Summe der Bremskräfte Σ FB Ist (daN)	Erforderliche Bremskräfte Σ FB Min (daN)
	-	479	269
	-	434	269
			Bremsk anteil (%)
			75
			2

Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Navigation




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 2: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 3: Wing mirror - right side: Cap - Scratched - Smart repair



Damage 3: Wing mirror - right side: Cap - Scratched - Smart repair



Damage 4: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 4: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 5: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace



Damage 6: Engine: Engine cover - Damage caused by marten / rodent - Replace



Damage 7: Steering system: Steering wheel - Glued / labelled - Replace




Damage 7: Steering system: Steering wheel - Glued / labelled - Replace



Damage 7: Steering system: Steering wheel - Glued / labelled - Replace



Damage 7: Steering system: Steering wheel - Glued / labelled - Replace



Damage 7: Steering system: Steering wheel - Glued / labelled - Replace



Damage 8: Wing mirror - right side: Mirror housing - Scratch(es) - Replace



Damage 8: Wing mirror - right side: Mirror housing - Scratch(es) - Replace



Damage 9: Rear bumper: Rear bumper - Scratched - Paint



Damage 9: Rear bumper: Rear bumper - Scratched - Paint




Damage 9: Rear bumper: Rear bumper - Scratched - Paint




Damage 9: Rear bumper: Rear bumper - Scratched - Paint



Damage 9: Rear bumper: Rear bumper - Scratched - Paint




Damage 9: Rear bumper: Rear bumper - Scratched - Paint



Damage 10: Side panel - rear left side: Side panel - Scratch(es) - Paint




Damage 10: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 10: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 10: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 11: Boot lid / rear door: Boot lid - dent(s) - Repair and paint



Damage 11: Boot lid / rear door: Boot lid - dent(s) - Repair and paint



Damage 11: Boot lid / rear door: Boot lid - dent(s) - Repair and paint



Damage 11: Boot lid / rear door: Boot lid - dent(s) - Repair and paint




Repainting 1: Bonnet, Door - front left side



Repainting 1: Bonnet, Door - front left side



Repainting 1: Bonnet, Door - front left side



Repainting 1: Bonnet, Door - front left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0FXXWPMHLD28332
Hersteller / Modell: FORD FORD Kuga 2.5 Duratec PHEV VIGNALE

Datum	KM-Stand	Beschreibung
17.02.2026	99.094	AU
09.01.2026	96.687	Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten
18.09.2025	91.778	Bremsflüssigkeit; Bremsflüssigkeit ern; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
19.12.2024	75.147	Motoröl b. Wartung; Regelwartungsdienst; Wartung Sonstiges
03.04.2024	61.205	Batterie ern; Systemtest/Eigendiagnose
28.03.2024	61.053	AU
09.01.2024	56.640	Batterie ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges; Zündkerzen ern
15.02.2023	37.864	Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
28.03.2022	18.728	Motoröl b. Wartung; Regelwartungsdienst