



Expertise

Protocol number: 46529253
Order No. / Reference: 26733729
Inspection date: 15 Jul 2026

Manufacturer: Ford

Model: Focus Turnier 1.0 EcoBoost Hybrid ST-LINE STYLE

VIN: WF0PXXGCHPNR13237



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Focus Turnier 1.0 EcoBoost Hybrid ST-LINE STYLE	
Vehicle Identification number	WF0PXXGCHPNR13237
Mileage (Read)	100,482 km
First registration	24 Feb 2023
Number of holders	1
Next periodical technical inspection	06/2028
(Report on hand)	
Power / Engine displacement	92 kw / 999 ccm
Fuel type / Cylinder	Hybrid Petrol / E / 3
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Agate Black Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite
Re-import	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	88 %
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP470984
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BUC 00125		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,970 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R17 95V	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	215/50 R17 95V	Summer tyres on Light alloy	Continental	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92H	Winter tyres on Light alloy	Semperit	2mm / 2mm
2)	205/60 R16 92H	Winter tyres on Light alloy	Semperit	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Passenger airbag deactivation
- Electrically folding exterior mirrors
- Attachment points behind the second row of seats for mounting the safety partition net
- Body styling kit
- Roof rails, black
- Dual exhaust system
- Third brake light
- Driver information system with on-board computer, color (10.7 cm screen diagonal)
- Electric windows front and rear
- Ford Easy Fuel
- Ford Power Start function
- Luggage compartment cover
- Cruise control
- Illuminated glove compartment
- Rear window wiper
- Interior mirror automatically dimming
- Isofix bracket
- Headrests (5)
- LED headlights
- Steering wheel: Steering column, adjustable in height and reach
- MyKey key system (individually programmable second key)
- Emergency brake light
- Otto particulate filter
- Upholstery: Cloth
- Pre-Collision Assist
- Tire Pressure Monitoring System (TPMS)
- Gear knob including gear shift boot with decorative stitching in red
- Headlight assistant with day/night sensor
- Electromechanical speed-dependent power steering
- Seats: Driver and front passenger seat backrests with map mesh
- Seats: Front sports seats
- 12-volt power outlet in the luggage compartment
- Black trim around the side windows
- Lashing eyes in the luggage compartment
- Immobiliser
- Central locking with remote control and remote luggage compartment release
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Tires: 7 J x 17 alloy wheels (4) with 215/50 R 17 tires
- Hill start assist
- Black woven fabric headliner
- Roof spoiler painted in car color
- Tachometer
- Electronic Safety and Stability Program (ESP)
- Lane keeping assist including lane keeping assist
- Chassis: Sport-tuned
- Electric parking brake with auto-hold function
- Ford EcoCoach
- FordPass Connect including eCall and Wi-Fi hotspot
- Speed limiter
- Transmission: 6-speed manual transmission
- Back window, heater
- Interior lighting with LED technology
- Intelligent security system
- Air conditioning with automatic temperature control
- LED taillights
- Steering wheel: ST-Line design
- Make-up mirrors in driver and passenger sun visors
- Center console "Premium" front
- Navigation: Ford SYNC 3 with AppLink, 8" touchscreen and DAB/DAB+
- Front and rear parking pilot system
- Post-Collision Assist
- Tire repair kit
- Rear seat backrest, foldable, 60:40 split
- Windscreen wipers with rain sensor
- Headlight low beam
- Selective driving mode switch
- Seats: Passenger seat, 2-way adjustable
- Seats: Driver's seat manually height-adjustable
- Seats: Driver's seat with adjustable lumbar support
- Start-stop system
- Carpet floor mats in the front
- Variable radiator air intake
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats



Extra equipment

- Towbar preparation kit
- Package: Driver Assistance Package I (Intelligent Adaptive Cruise Control (iACC), Traffic Sign Recognition System, Wrong-Way Driver Warning, Evasive Steering Assist (ESA), Distance Display and Distance Warning, Driver Alert, High Beam Assist, Blind Spot Assist with Cross Traffic Alert including Emergency Braking Function (when reversing out of parking spaces) and Trailer Detection, Rearview Camera with Split View Technology)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Safety partition net for luggage compartment
- Paint finish: Special metallic paint
- Package: ST-Line styling package (red painted brake calipers - large roof spoiler painted in body color - pedals with aluminum covers - front door sill trims, ST-Line design)
- Package: Winter (heated windscreen - heated steering wheel - individually and variably heated front seats)
- Radio: Ford SYNC 3 Light with AppLink, 8" touchscreen (20.3 cm screen diagonal) and DAB/DAB+ (6 speakers - Android Auto and Apple CarPlay - Bluetooth hands-free system and audio streaming - steering wheel controls - voice control via phone - USB port)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Bonnet	Insulation lining - Broken / torn - Replace
2	2nd wheel set	1 tyre - Defective - Replace
3	Door - rear right side	Door - dent(s) - Smart repair
4	Vehicle glazing	Rear window - Scratched - Loss in value
5	2nd wheel set	2 tyres (Einseitig abgefahren) - Worn - Replace
6	Sill - left side	Trim - Scratched - Paint
7	Front bumper	Bumper with Parktronic - Scratched - Paint
8	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
9	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint
10	Rear bumper	Bumper with Parktronic - Deformed - Replace

Wear and tear

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Professionally repaired, Invoice of repair done Non-existent, from 4 Feb 2026	2.500,00 €



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Damage 1: Bonnet: Insulation lining - Broken / torn - Replace




Damage 1: Bonnet: Insulation lining - Broken / torn - Replace




Damage 2: 2nd wheel set: 1 tyre - Defective - Replace



Damage 2: 2nd wheel set: 1 tyre - Defective - Replace



Damage 3: Door - rear right side: Door - dent(s) - Smart repair



Damage 3: Door - rear right side: Door - dent(s) - Smart repair



Damage 4: Vehicle glazing: Rear window - Scratched - Loss in value



Damage 4: Vehicle glazing: Rear window - Scratched - Loss in value



Damage 4: Vehicle glazing: Rear window - Scratched - Loss in value



Damage 4: Vehicle glazing: Rear window - Scratched - Loss in value



Damage 5: 2nd wheel set: 2 tyres (Einseitig abgefahren) - Worn - Replace



Damage 5: 2nd wheel set: 2 tyres (Einseitig abgefahren) - Worn - Replace



Damage 5: 2nd wheel set: 2 tyres (Einseitig abgefahren) - Worn - Replace



Damage 6: Sill - left side: Trim - Scratched - Paint



Damage 6: Sill - left side: Trim - Scratched - Paint




Damage 6: Sill - left side: Trim - Scratched - Paint



Damage 7: Front bumper: Bumper with Parktronic - Scratched - Paint




Damage 7: Front bumper: Bumper with Parktronic - Scratched - Paint



Damage 7: Front bumper: Bumper with Parktronic - Scratched - Paint



Damage 7: Front bumper: Bumper with Parktronic - Scratched - Paint



Damage 8: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 8: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 8: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 10: Rear bumper: Bumper with Parktronic - Deformed - Replace




Damage 10: Rear bumper: Bumper with Parktronic - Deformed - Replace



Damage 10: Rear bumper: Bumper with Parktronic - Deformed - Replace



Damage 10: Rear bumper: Bumper with Parktronic - Deformed - Replace



Damage 10: Rear bumper: Bumper with Parktronic - Deformed - Replace