



Expertise

Protocol number: 46623711  
Order No. / Reference: 26512627  
Inspection date: 17 Jul 2026

Manufacturer: Mercedes-Benz  
VIN: W1VVLFEZ1P4263360

Model: Vito 116 CDI Tourer Lang Aut. BASE



| Vehicle details                                  |                         |
|--------------------------------------------------|-------------------------|
| Manufacturer / Type / Model / Equipment          |                         |
| Mercedes-Benz Vito 116 CDI Tourer Lang Aut. BASE |                         |
| Vehicle Identification number                    | W1VVLFEZ1P4263360       |
| Mileage (Read)                                   | 112,820 km              |
| First registration                               | 19 Jun 2023             |
| Number of holders                                | 1                       |
| Fuel type                                        | Diesel                  |
| Engine displacement / Cylinder                   | 1,950 ccm / 4           |
| Power                                            | 120 kW                  |
| Gearbox / Number of gears                        | Automatic / 9           |
| Type of drive                                    | Rear drive              |
| Type of vehicle                                  | Van                     |
| Colour / colour code                             | brillantsilber metallic |
| Doors / Seats                                    | 4 / 5                   |
| Upholstery type                                  | Cloth                   |
| Colour of upholstery                             | Black                   |
| Vehicle with smoke odor                          | no                      |



## Vehicle details

|                                                  |                          |                                |                                                            |
|--------------------------------------------------|--------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete | <b>Next maintenance in</b>     | 363 Tag(e)                                                 |
| <b>Last service on / at</b>                      | 06/2025 at 84,333 km     |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                    | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                          | <b>Letter No.</b>              | GU444154                                                   |
| <b>Previous damage / Accident</b>                | None detectable          | <b>Repainting</b>              | None detectable                                            |
| <b>Inspection conditions</b>                     | sufficient               | <b>Lifting equipment / pit</b> | yes                                                        |
| <b>Test drive</b>                                | Not performed            | <b>Engine function test</b>    | Performed                                                  |
| <b>Manufacturer key number/ type code number</b> | 2222 / ABB 03518         |                                |                                                            |
| <b>Emission standard</b>                         | EURO6                    | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 3,100 kg                 | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 205/65 R16 107T | Winter tyres on Light alloy | Pirelli      | 3mm / 3mm   |
| 2) | 205/65 R16 107T | Winter tyres on Light alloy | Pirelli      | 3mm / 3mm   |

### Additional tyres

| #  | Tyre size       | Type of tyre                               | Manufacturer | Tread depth |
|----|-----------------|--------------------------------------------|--------------|-------------|
| 1) | 205/65 R16 107T | Summer tyres on Steel rim with wheel cover | Continental  | 5mm / 5mm   |
| 2) | 205/65 R16 107T | Summer tyres on Steel rim with wheel cover | Continental  | 4mm / 4mm   |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

## Equipment

### Standard equipment

- ABS, ESP, ASR, EBV, BAS
- Passenger side airbag
- ATTENTION ASSIST
- Exterior mirrors, manually adjustable (2)
- Battery: Backup battery for starting process
- Hill start assist
- Brake lights, adaptive
- Standard roof lining, pillars B to D
- Electronic tachometer
- Window in rear door/tailgate
- Front left window fixed in SW/ cargo area sliding door
- Electric windows, driver/passenger
- Generator management
- Transmission: 9G-TRONIC
- Seatbelt warning device for driver's seat
- Main tank 57 liters
- HOLD function
- Interior lights in the rear
- Interior trim of cargo area, side
- Instrument cluster with pixel matrix display
- Headrests (2), front
- Steering wheel adjustable for tilt and height
- Mercedes-Benz emergency call system
- Package: Aerodynamics
- Breakdown management
- Tires: 205/65 R 16
- Tires: Premium protection tires (3 years)
- Tire pressure monitoring
- Headlights: halogen technology
- Crosswind Assist
- Seats: Adjustable passenger seat
- Seats: Rear seat mounting with quick-release fasteners, 2 rows of seats
- Cruise control
- Pre-installation for Remote Services Plus
- Warning triangle
- ASSYST maintenance interval indicator
- Heat-insulating glass
- Auxiliary heater, electric
- Screw-in towing eye front/rear
- Driver's side airbag
- Increased load capacity to 3,100 kg
- Outdoor temperature display
- Battery: fleece battery 12 V / 92 Ah
- third brake light
- Front cupholder
- Diesel particulate filter and SCR
- Chassis: Comfort
- Left/right window in SW/ Cargo area sliding door
- Front right window fixed in SW/ cargo area sliding door
- Generator 14 V / 200 A
- Speed limit 210 km/h
- Seatbelt warning device for front passenger seat
- Lockable glove box
- Boot lid
- Wooden floor (cargo area)
- Interior mirror
- Child safety locks on doors in the passenger compartment
- Communication module (LTE) for digital services
- Paint finish: Solid color paint
- Headlight range control
- Multifunctional steering wheel
- Package: BlueEFFICIENCY
- Upholstery: Caluma fabric, black
- Tires: Tires without specified make
- Tires: Summer tires
- Wheels: Steel rims 6.5 J x 16
- Sliding door on the right, cargo/passenger compartment
- electromechanical power steering
- Seats: Driver's seat
- Start-stop function
- 12V socket
- First aid kit
- Warm air duct to the passenger compartment
- Windshield washer fluid level warning light
- Immobiliser
- Central locking with radio remote control
- Car registration



## Extra equipment

- Towbar (detachable ball head)
- Overhead control unit Comfort in conjunction with air conditioning and driving light assistant
- Driving light assistant
- All-weather floor mats
- Rear camera not foldable
- Large fuel tank, approx. 70 liters
- LED Intelligent Light System (ILS) (including dynamic cornering lights, country road and motorway lights, turning lights, dynamic headlight range control, automatic high beam assist, LED taillights)
- Package: Park (front and rear parking aid, visual and acoustic warning, parking space detection, automatic steering - reversing camera)
- Package: Mirrors (automatically dimming interior mirror - automatically dimming exterior mirror - electrically folding exterior mirrors)
- Radio: Digital Radio DAB
- Rain sensor
- Seats: 3-seater bench in the 1st row of the passenger compartment (with individual seat elements - folding outer seat)
- Seat heating on driver's side
- Carpet in the front of the vehicle interior
- Elimination of rear lettering
- Electrically adjustable and heated exterior mirrors, left and right
- Double cup holder in the center of the cockpit
- Chassis: Standard chassis Plus
- Generator 14 V / 250 A
- Tempmatic controlled air conditioning
- Paint finish: Metallic
- leather steering wheel
- Navigation accessories: Live Traffic Information
- Package: Driver Assistance Package (Lane Keeping Assist - Blind Spot Assist - Active Brake Assist)
- Package: Seating comfort (seat cushion depth adjustment driver/passenger seat - lumbar support driver/passenger seat)
- Radio/Navigation: Multimedia radio and navigation system "Audio 40" (7-inch LCD touchscreen - FM/AM/DAB+ - Apple CarPlay and Android Auto - Bluetooth 3.0 - 2-way speakers front and rear)
- Rear door, double-leaf, 180° opening, without window
- Seats: Comfort passenger seat
- Seats: Comfort driver's seat
- Seat heating on passenger side
- Lane Keeping Assist for automatic transmission
- Blind Spot Assist

## Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                        |
| Engine function test | An engine test run was performed.                                                                                                                                            |

## Value reducing factors

| No. | Component group              | Description                                                     |
|-----|------------------------------|-----------------------------------------------------------------|
| 1   | Wing mirror - right side     | Cap - Scratch(es) - Smart repair                                |
| 2   | Boot lid / rear door         | Rear door - left side - Glued / labelled - De-glue / neutralise |
| 3   | Rear bumper                  | Rear bumper (unpainted) - Scratch(es) - Loss in value           |
| 4   | Side panel - rear left side  | Wheel arch (Innen) - Dent / paintcoat damage - Smart repair     |
| 5   | Side panel - rear right side | Wheel arch (Innen) - Dent / paintcoat damage - Smart repair     |
| 6   | Bonnet                       | Bonnet - Stone chips - Paint                                    |

## Wear and tear

| No. | Component group | Description                     |
|-----|-----------------|---------------------------------|
| 1   | Body            | Underbody panelling - Scratched |

The vehicle shows signs of wear and tear commensurate with its age and use.



## Missing parts

### Description

Documents - Main inspection certificate

Equipment - Tirefit complete

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
*(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
*(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)



**Figure 3:** Diagonal rear (left)



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 2: Boot lid / rear door: Rear door - left side - Glued / labelled - De-glue / neutralise



**Damage 2:** Boot lid / rear door: Rear door - left side - Glued / labelled - De-glue / neutralise



**Damage 3:** Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



**Damage 3:** Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



**Damage 3:** Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



**Damage 3:** Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



**Damage 4:** Side panel - rear left side: Wheel arch (Innen) - Dent / paintcoat damage - Smart repair



**Damage 4:** Side panel - rear left side: Wheel arch (Innen) - Dent / paintcoat damage - Smart repair




**Damage 4:** Side panel - rear left side: Wheel arch (Innen) - Dent / paintcoat damage - Smart repair



**Damage 4:** Side panel - rear left side: Wheel arch (Innen) - Dent / paintcoat damage - Smart repair



**Damage 5:** Side panel - rear right side: Wheel arch (Innen) - Dent / paintcoat damage - Smart repair




**Damage 5:** Side panel - rear right side: Wheel arch (Innen) - Dent / paintcoat damage - Smart repair



**Damage 5:** Side panel - rear right side: Wheel arch (Innen) - Dent / paintcoat damage - Smart repair




**Damage 6:** Bonnet: Bonnet - Stone chips - Paint




**Damage 6:** Bonnet: Bonnet - Stone chips - Paint




**Damage 6:** Bonnet: Bonnet - Stone chips - Paint




**Damage 6:** Bonnet: Bonnet - Stone chips - Paint



**Damage 6:** Bonnet: Bonnet - Stone chips - Paint



**Damage 6:** Bonnet: Bonnet - Stone chips - Paint



**Damage 6:** Bonnet: Bonnet - Stone chips - Paint



**Wear and tear 1:** Body: Underbody panelling - Scratched



**Wear and tear 1:** Body: Underbody panelling - Scratched



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1VVLFEZ1P4263360

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ Vito 116 CDI Tourer Lang  
Aut. BASE

| Datum      | KM-Stand | Beschreibung             |
|------------|----------|--------------------------|
| 13.06.2025 | 84.333   | Regelwartungsdienst      |
| 06.02.2025 | 68.304   | Bremsscheiben+Beläge v+h |
| 02.07.2024 | 42.024   | Regelwartungsdienst      |