



Expertise

Protocol number: 46695485
Order No. / Reference: 26747179
Inspection date: 21 Jul 2026

Manufacturer: Opel	Model: Astra 1.5 D Start/Stop Sports Tourer Automatik Design&Tech
VIN: W0VBE8EV6N8044130	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Astra 1.5 D Start/Stop Sports Tourer Automatik Design&Tech	
Vehicle Identification number	W0VBE8EV6N8044130
Mileage (Read)	125,836 km
First registration	4 Jul 2022
Number of holders	1
Next periodical technical inspection	07/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,496 ccm / 3
Power	90 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Argonsilber
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Grey



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	54 %
Last service on / at	07/2026 at 125,835 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ670188
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	Conditional: Light/moisture/dirt	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Not possible
Manufacturer key number/ type code number	1844 / ALM 00263		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,980 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Pirelli	4mm / 4mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Pirelli	5mm / 5mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91V	Summer tyres on Light alloy	Continental	3mm / 3mm
2)	205/55 R16 91V	Summer tyres on Light alloy	Pirelli	6mm / 6mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- 2 ignition keys (one of which is foldable)
- Airbag for driver and front passenger side (passenger airbag can be deactivated)
- Airbag: Chest-pelvis side airbag for driver and front passenger side
- Airbag: Head airbags, 1st and 2nd row (outer seats)
- Ambient lighting, front doors
- Automatic activation of the hazard warning lights (and unlocking of the doors after deployment of the airbag or seatbelt pretensioner)
- Hill Start Assist
- On-board computer (with check control system)
- Roof design line, above in black
- Decorative trim strips in piano black
- Tachometer
- Electric windows front and rear (with one-touch function and anti-pinch protection)
- Speed controller with limiter
- Transmission: 9-speed automatic transmission
- Back window, heater
- rear window wiper
- Interior lighting, front and rear
- Instruments, black, with high-gloss chrome rings, 3.5" driver information display
- Automatic climate control, two zones (with separate temperature control for driver and front passenger, including: - recirculation mode, manual - particle/activated carbon filter - automatic air distribution - sun position sensor - humidity sensor)
- LED headlights
- Light alloy wheels 7 J x 16 in "5-twin-spoke" design in Technical Grey (with tires 205/55 R 16)
- Steering column, height and reach adjustable
- Lighting equipment (illuminated make-up mirrors in sun visors - reading lights, rear - ambient lighting in the roof console)
- Parkpilot, rear parking aid (with acoustic warning signal when reversing)
- Upholstery: Fabric/Premium leather look
- Radio: Digital radio reception DAB/DAB+/DMB-R (Digital Audio Broadcasting)
- Tire repair kit (including tire sealant and 12-volt compressor (without jack))
- Tire pressure monitoring system (tire pressure display for each wheel)
- Rear seat backrest folds forward in a 60:40 split
- Power steering (speed-dependent)
- Seat belts: Three-point seat belts in all seats (belt force limiter and belt tensioner in the front and on the outer rear seats - warning tone and light for unfastened seat belts in all seats)
- Visibility features (rain sensor, front interior rearview mirror automatically dimming, automatic dimming headlights with tunnel detection)
- Storage compartments (storage compartment in the center console and instrument panel, driver's side - storage compartment in the front doors, suitable for 1.5-liter beverage bottles - storage compartment in the rear doors, suitable for 0.5-liter beverage bottles - 4 lashing eyes in the luggage compartment)
- Anti-lock braking system (ABS) (with cornering brake control (CBC) and brake assist)
- Electrically adjustable and heated exterior mirrors for driver and passenger side (manually foldable - exterior mirror housing in black)
- third brake light
- Roof rails, silver
- Diesel particulate filter (DPF) (maintenance-free)
- Electronic Stability Program Plus (ESP Plus)
- Front camera (forward collision warning with automatic emergency braking: active from 8 km/h, range 60 m. Monitors the distance to the vehicle ahead. Lane departure warning and lane keeping assist: warns of unintentional lane departure (between 60 km/h and 180 km/h) via a warning light in the driver information display. The lane keeping assist also alerts the driver by gently counter-steering, but does not continuously steer the vehicle. Distance indicator: displays the distance to the vehicle ahead.)
- trunk light
- Rear headrests (3) (height adjustable)
- Front headrests (height adjustable)
- Cargo area cover
- LED daytime running lights (including LED turn signals, front, manual headlight range adjustment)
- Steering wheel: Leather steering wheel (steering wheel remote control)
- Sliding center armrest, front (with storage compartments and cup holders)
- Electric parking brake
- Pedal system: Disengaging safety pedals (PRS (Pedal Release System))
- Quickheat rapid heating system (electric auxiliary heater)
- Radio: Multimedia radio with 7" touchscreen color display (automatic music recognition (title, album, artist, cover) for audio devices with USB connection, Bluetooth audio streaming, hands-free calling via Bluetooth interface, display of phonebook and call lists, smartphone integration via Apple CarPlay and Android Auto, voice control, navigation (Google Maps, Apple Maps), music, phone, text message reading and dictation, speed-dependent volume and bass control, USB interface and Aux-In, 6 speakers)
- Safety net for luggage compartment (incl. mounting hardware behind 1st or 2nd row of seats)
- Seats: Comfort seats, front (driver's seat adjustable in 6 ways (length, height) - passenger seat adjustable in 4 ways (length))
- 12V power outlet in the center console
- Traction Control (TC) Plus (traction control with engine and brake intervention)



- | | |
|--|--|
| <ul style="list-style-type: none"> • Start/Stop system (driving assistant - reinforced starter - high-performance battery - eco switch to deactivate the start/stop function - brake energy recuperation) • Door sill trims (with OPEL lettering, front) • Immobiliser • Heat-insulating glazing, green tinted, and windshield | <ul style="list-style-type: none"> • Pre-installation for child seat restraint system "ISOFIX" (incl. top tether attachment points, rear outer) • Central locking with remote control and interior switches (ignition key matching exterior color) |
|--|--|

Extra equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • Radio: Multimedia Navi (Multimedia Radio, 7" touchscreen color display with USB port, hands-free system, voice control, Bluetooth audio streaming, smartphone integration via Apple CarPlay and Android Auto - Navigation system with integrated memory - Road map for over 30 European countries - Map display in 2D and 3D - Dynamic route guidance via map and/or arrow display and voice prompts - Dynamic destination guidance via enhanced Traffic Message Channel (TMCpro)) | <ul style="list-style-type: none"> • Detachable trailer hitch (including trailer stability program TSP) • Paint finish: Metallic • Steering wheel: Heated leather steering wheel and seat heating, multi-stage, driver and front passenger (including rear footwell heating) |
|--|---|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/dampness or dirt. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run could not be performed. This is due to the following reason.: Siehe Kostenvoranschlag



Value reducing factors

No.	Component group	Description
1	Wing mirror - left side	Cap - Scratch(es) - Smart repair
2	Wing mirror - right side	Cap - Scratch(es) - Smart repair
3	Trim / covers	Floor mats - Broken / torn - Replace
4	Interior	Cargo area floor - Scratch(es) - Loss in value
5	2nd wheel set	1 tyre - Broken / torn - Replace
6	Door - front left side	Door - Scratch(es) - Smart repair
7	Boot lid / rear door	Boot lid - Scratch(es) - Smart repair
8	Body	Body - Glued / labelled - De-glue / neutralise
9	Mudguard - left side	Mudguard - left side - Dent / paintcoat damage - Smart repair
10	2nd wheel set	1 alloy rim - Scratch(es) - Replace
11	Braking system	Brake discs and pads - rear (Tragbild mangelhaft, Rost) - Corrosion - Replace
12	Braking system	Brake discs and brake pads - front (Tragbild mangelhaft, Rost) - Corrosion - Replace
13	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
14	Front bumper	Front bumper - Scratch(es) - Paint
15	Door - rear left side	Door - Scratch(es) - Paint
16	Door - rear right side	Door - Scratch(es) - Paint
17	Rear bumper	Rear bumper - Dent / paintcoat damage - Repair and paint
18	Trim / covers	Roof lining - Broken / torn - Replace
19	Vehicle glazing	Windscreen - Broken / torn - Replace
20	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint
21	Engine	Engine (Ölpumpe) - Loose - repair according to calculation
22	Roof	Roof - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Side panel - rear left side	Side panel - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent
2	Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent
3	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
4	Door - front left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - right side	187 µm	Side panel - rear left side	285 µm
Side panel - rear right side	173 µm	Door - front left side	169 µm



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Damage 1: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 1: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 3: Trim / covers: Floor mats - Broken / torn - Replace



Damage 4: Interior: Cargo area floor - Scratch(es) - Loss in value



Damage 4: Interior: Cargo area floor - Scratch(es) - Loss in value




Damage 5: 2nd wheel set: 1 tyre - Broken / torn - Replace




Damage 5: 2nd wheel set: 1 tyre - Broken / torn - Replace




Damage 5: 2nd wheel set: 1 tyre - Broken / torn - Replace



Damage 6: Door - front left side: Door - Scratch(es) - Smart repair



Damage 6: Door - front left side: Door - Scratch(es) - Smart repair



Damage 7: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



Damage 7: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair




Damage 8: Body: Body - Glued / labelled - De-glue / neutralise



Damage 8: Body: Body - Glued / labelled - De-glue / neutralise




Damage 9: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Smart repair



Damage 9: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Smart repair



Damage 10: 2nd wheel set: 1 alloy rim - Scratch(es) - Replace



Damage 10: 2nd wheel set: 1 alloy rim - Scratch(es) - Replace



Damage 11: Braking system: Brake discs and pads - rear (Tragbild mangelhaft, Rost) - Corrosion - Replace



Damage 11: Braking system: Brake discs and pads - rear (Tragbild mangelhaft, Rost) - Corrosion - Replace



Damage 12: Braking system: Brake discs and brake pads - front (Tragbild mangelhaft, Rost) - Corrosion - Replace




Damage 12: Braking system: Brake discs and brake pads - front (Tragbild mangelhaft, Rost) - Corrosion - Replace



Damage 13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 14: Front bumper: Front bumper - Scratch(es) - Paint




Damage 14: Front bumper: Front bumper - Scratch(es) - Paint



Damage 14: Front bumper: Front bumper - Scratch(es) - Paint




Damage 15: Door - rear left side: Door - Scratch(es) - Paint



Damage 15: Door - rear left side: Door - Scratch(es) - Paint



Damage 16: Door - rear right side: Door - Scratch(es) - Paint



Damage 16: Door - rear right side: Door - Scratch(es) - Paint



Damage 17: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint




Damage 17: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 17: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 17: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 18: Trim / covers: Roof lining - Broken / torn - Replace



Damage 18: Trim / covers: Roof lining - Broken / torn - Replace



Damage 19: Vehicle glazing: Windscreen - Broken / torn - Replace




Damage 19: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 20: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 20: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 20: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 20: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint

Kund.-Nr. 35553-K0-Vel. 4		Int. Serviceberater Torsten Schulz			
Kennz.: ES-TK 1677		Fahrzeug-Nr.: MOVBE8EV6N8044130			
Modell: ASTRA K SPORTS		Motor-Nr.: 125835			
Zul-Dat.: 4-07-22		km-Stand: 125835			
TUV/AD: 07-27 / 07-27		Leist-Dat.: 09.02.26-10.02.26			
AN	Service-Nr.	Bezeichnung	Rab. EUR-Wert		
		FAHRZEUG EINGESCHLEPPT:			
		FEHLER OLDRECK; MOTOR FEHLER			
		ESC PRF, ABS LEUCHTEN			
8	4065870	FEHLERSPEICHER AUSLESEN	108,00		
	8007000	OLWANNE ZUR DIAGNOSE AUSSAUEN	148,50		
		***** BEFINDERBEREICH *****			
26	4066070	ZAHNRAD ÖLPUMPE LOSE	351,00		
		ÖLPUMPE - AUSTAUSCH	607,50		
		Summe Leistungen			
Menge	HR Teile-Nr.	Bezeichnung	Einz.-Pr.	Rab.	EUR-Wert
1	01 11548183	SCHRAUBE	1,81	10,0	1,63
1	01 1679592380	ABDICHTMITTEL	25,51	10,0	22,96
1	01 55486383	GEHÄUSE	92,87	10,0	83,58
1	01 55490854	ZAHNRADEN	124,32	10,0	111,89
1	01 55512722	SPANNER	64,64	10,0	58,18
1	01 55516890	MOTORÖLPUMPE	338,99	10,0	305,09
		RABATT AUF TEILE BEREITS BEACHTET			
(HR 01 = Original Opel Teile)		Summe Teile+Zubehör			583,33
		Netto-Betrag	EUR		1.190,83
		19,0 % MwSt	EUR		226,26
		Endbetrag (i.v.v.)	EUR		1.417,09
		zahlbar sofort ohne Abzug			
"Bei Fragen wenden Sie sich an service-reinfeld@ello.de"					

Erst-Dat. Druck & Art. K-02

Steuernummer: 2771/00000

USt-IdNr. B410

Deutsche Bank AG







Damage 21: Engine: Engine (Ölpumpe) - Loose - repair according to calculation



Damage 22: Roof: Roof - Scratch(es) - Paint




Damage 22: Roof: Roof - Scratch(es) - Paint



Damage 22: Roof: Roof - Scratch(es) - Paint



Damage 22: Roof: Roof - Scratch(es) - Paint



Repainting 1: Mudguard - right side




Repainting 1: Mudguard - right side



Repainting 2: Side panel - rear left side



Repainting 2: Side panel - rear left side



Repainting 3: Side panel - rear right side



Repainting 3: Side panel - rear right side



Repainting 4: Door - front left side



Repainting 4: Door - front left side