

Expertise

Protocol number: 45928660
Order No. / Reference: 26489866
Inspection date: 15 Jun 2026

Manufacturer: Skoda

Model: Octavia Combi 2.0 TDI DSG Ambition

VIN: TMBJJ8NX0PY078425



Vehicle details

Manufacturer / Type / Model / Equipment

Skoda Octavia Combi 2.0 TDI DSG Ambition

| | |
|---|---------------------------------|
| Vehicle Identification number | TMBJJ8NX0PY078425 |
| Mileage (Read) | 183,754 km |
| First registration | 28 Feb 2023 |
| Number of holders | 1 |
| Next periodical technical inspection | 02/2028 (Report not on hand) |

| | |
|------------------------------------|--------------------|
| Power / Engine displacement | 110 kw / 1,968 ccm |
|------------------------------------|--------------------|

| | |
|-----------------------------|------------|
| Fuel type / Cylinder | Diesel / 4 |
|-----------------------------|------------|

| | |
|----------------------------------|---------------|
| Gearbox / Number of gears | Automatic / 7 |
|----------------------------------|---------------|

| | |
|----------------------|-------------|
| Type of drive | Front drive |
|----------------------|-------------|

| | |
|------------------------|---------------|
| Type of vehicle | Station wagon |
|------------------------|---------------|

| | |
|-----------------------------|--------------------------|
| Colour / colour code | moonweiss-metallic (S9R) |
|-----------------------------|--------------------------|

| | |
|----------------------|-------|
| Doors / Seats | 5 / 5 |
|----------------------|-------|

| | |
|------------------------|-------|
| Upholstery type | Cloth |
|------------------------|-------|

| | |
|-----------------------------|------------|
| Colour of upholstery | Black-Grey |
|-----------------------------|------------|



Vehicle details

| | | | |
|--|------------------------------|--------------------------------|--|
| Maintenance booklet / proof | digital proof / complete | Next maintenance in | 12,700 km |
| Last service on / at | 12/2025 at 170,729 km | | |
| Key is / should be | 2 / 2 | FZG documents | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | Letter No. | GQ539406 |
| Previous damage / Accident | Detectable | Repainting | Detectable |
| Inspection conditions | sufficient | Lifting equipment / pit | yes |
| Test drive | Not performed | Engine function test | Performed |
| Manufacturer key number/ type code number | 8004 / AWL 00288 | | |
| Emission standard | EURO6;WLTP;AP;PI/CI; M, N1 I | fine dust sticker | |
| Permitted total weight | 1,990 kg | Empty weight | |

Tyres

Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 205/60 R16 96H | Winter tyres on Light alloy | Semperit | 2mm / 2mm |
| 2) | 205/60 R16 96H | Winter tyres on Light alloy | Semperit | 6mm / 6mm |

Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 205/60 R16 92V | Summer tyres on Light alloy | Hankook | 5mm / 5mm |
| 2) | 205/60 R16 92V | Summer tyres on Light alloy | Hankook | 5mm / 5mm |

Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|-----|-----------|-------------------------|--------------|-------------|
| | Tirefit | Expiration date 10/2026 | | |

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Storage compartment in the luggage compartment with cargo element
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors
- Heated windshield washer nozzles including 5l washer fluid reservoir
- Glasses compartment in the headliner
- AERO roof rails in black
- Diesel particulate filter
- Third brake light
- Electronic transverse differential lock (XDS+)
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Cruise control system
- Tinted windows
- Heated rear window
- Rear window wiper including windshield washer system
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Removable boot cover
- Paint finish: Solid
- LED taillights
- LED headlights with LED daytime running lights
- Steering wheel: Leather steering wheel with multifunction buttons and paddle shifters.
- Front center armrest, including storage compartment
- Multifunction display in the instrument cluster
- Rear parking sensors
- Radio: Bolero music system with 10" display
- Radio accessories: 8 speakers
- Radio accessories: Digital radio reception DAB+
- Radio accessories: Voice control
- Tire pressure monitoring
- Wheels: 16" Twister AERO alloy wheels
- Seat belts
- Seats: Rear seat backrest split 60:40, foldable
- Speed limiter
- 12V socket in the trunk
- Lashing eyes in the trunk
- Central locking including remote control integrated into the key and EASY Start
- Storage compartments
- Airbag, driver and passenger
- Airbag, head airbags
- Airbag: Center airbag front
- Traction control (ASR)
- Electrically folding exterior mirrors
- Hill start assist
- Hydraulic brake assist (HBA)
- Grey headliner
- Decorative strip in Goldress matte
- Tachometer
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC)
- Front radar assistant including city emergency braking function and pedestrian and cyclist detection
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec: Start/stop system including brake energy recuperation
- Interior mirror automatically dimming
- Child safety lock for the rear doors and windows
- Climatronic air conditioning (2-zone)
- Headrests (5) front and rear height adjustable
- LED fog lights
- LED license plate lights
- Steering wheel: height and reach adjustable
- Manual headlight range adjustment
- Rear center armrest with pass-through option
- Engine drag torque control (MSR)
- Fatigue detection
- Upholstery: Cloth
- Radio accessories: 2 USB-C ports on the front
- Radio accessories: Bluetooth hands-free system
- Radio accessories: SmartLink
- Rain sensor and driving light assistant
- Tire mobility kit
- Electromechanical power steering
- Seats: Height-adjustable driver and passenger seats
- SKODA Care Connect
- Lane keeping assistant (Lane Assist)
- Phone: Wireless SmartLink for Apple CarPlay
- Immobiliser



Extra equipment

- Anti-theft alarm system including safe system with interior monitoring and tilt sensor
- Package: Comfort (3-zone Climatronic - Sunset (dark tinted rear window and rear side windows) - Acoustic glazing in the front side windows - Heated front and outer rear seats - Heated steering wheel - KESSY, keyless entry and start-stop system - Auto-dimming exterior mirror (driver's side))
- Front and rear parking sensors
- Paint finish: Pearl effect
- Package: Infotainment Package Business Columbus (DSG) (Columbus navigation system - Bluetooth free. - Infotainment Online (3-year subscription), online map updates: for navigation, traffic situation, gas stations and parking space search - Digital Cockpit Plus - 3 USB charging ports - Driving profile selection - Adaptive Cruise Control (ACC) - Phonebox with inductive charging. - Traveller Assist system: - Traffic sign recognition - Adaptive lane keeping assist - Emergency and traffic jam assist - Capacitate steering wheel with hands-off detection)

Brief expert findings

| | |
|----------------------|--|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

Value reducing factors

| No. | Component group | Description |
|-----|----------------------|---|
| 1 | Seat - front | Seat cover - left side - Soiled - Clean |
| 2 | Rear bumper | Spoiler - Malposition - Repair |
| 3 | Seat - rear | Upholstery (+ verschmutzt) - Scratch(es) - Smart repair |
| 4 | Roof | Roof (Randbereich) - Stone chips - Smart repair |
| 5 | Mudguard - left side | Mudguard - left side (Klarlackmangel) - Unprofessionally repaired - Paint |
| 6 | Sill - left side | Sill (Hinten) - Broken / torn - repair according to calculation |

Wear and tear

| No. | Component group | Description |
|-----|-----------------|--|
| 1 | Wheel / tyres | Tyre - front (2mm) - Does not meet the leasing specifications - No deduction |
| 2 | Bonnet | Bonnet - Stone chips - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

| No. | Previous damage | Extent of damage (Net) |
|-----|--|------------------------|
| 1 | Front, Provided by user / customer, from 31 Aug 2024 | 995,70 € |
| 2 | Side - left, Provided by user / customer, from 1 Sept 2024 | 1.843,13 € |
| 3 | Side right, Provided by user / customer, from 30 Nov 2023 | 4.894,98 € |
| 4 | Side - left, Provided by user / customer, from 23 Jun 2023 | 9.895,23 € |



Repainting

No. Repainting

- 1 Mudguard - right side, Door - rear left side, Door - rear right side, Door - front left side, Professionally carried out, Invoice of repair done Non-existent
- 2 Mudguard - left side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

| | | | |
|------------------------|--------|------------------------|--------|
| Mudguard - left side | 202 µm | Mudguard - right side | 163 µm |
| Door - rear left side | 174 µm | Door - rear right side | 177 µm |
| Door - front left side | 208 µm | | |

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.

Der montierte Radsatz ist nicht Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Damage 1: Seat - front: Seat cover - left side - Soiled - Clean




Damage 2: Rear bumper: Spoiler - Malposition - Repair



Damage 2: Rear bumper: Spoiler - Malposition - Repair



Damage 2: Rear bumper: Spoiler - Malposition - Repair



Damage 3: Seat - rear: Upholstery (+ verschmutzt) - Scratch(es) - Smart repair




Damage 3: Seat - rear: Upholstery (+ verschmutzt) - Scratch(es) - Smart repair



Damage 4: Roof: Roof (Randbereich) - Stone chips - Smart repair



Damage 4: Roof: Roof (Randbereich) - Stone chips - Smart repair



Damage 4: Roof: Roof (Randbereich) - Stone chips - Smart repair



Damage 5: Mudguard - left side: Mudguard - left side (Klarlackmangel) - Unprofessionally repaired - Paint



Damage 5: Mudguard - left side: Mudguard - left side (Klarlackmangel) - Unprofessionally repaired - Paint



Damage 6: Sill - left side: Sill (Hinten) - Broken / torn - repair according to calculation



Damage 6: Sill - left side: Sill (Hinten) - Broken / torn - repair according to calculation



Damage 6: Sill - left side: Sill (Hinten) - Broken / torn - repair according to calculation



Repainting 1: Mudguard - right side, Door - rear left side, Door - rear right side, Door - front left side



Repainting 1: Mudguard - right side, Door - rear left side, Door - rear right side, Door - front left side



Repainting 1: Mudguard - right side, Door - rear left side, Door - rear right side, Door - front left side



Repainting 1: Mudguard - right side, Door - rear left side, Door - rear right side, Door - front left side



Repainting 2: Mudguard - left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: TMBJJ8NX0PY078425
Hersteller / Modell: SKODA SKODA Octavia Combi 2.0 TDI DSG Ambition

| Datum | KM-Stand | Beschreibung |
|------------|----------|---|
| 13.02.2026 | 177.865 | AU; Reparatur Sonstiges; Systemtest/Eigendiagnose |
| 11.02.2026 | 170.729 | Systemtest/Eigendiagnose |
| 01.12.2025 | 170.729 | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges |
| 28.05.2025 | 141.750 | Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Getriebeöl ern/prüfen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges |
| 08.10.2024 | 109.508 | Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges |
| 29.02.2024 | 55.544 | Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges |
| 18.12.2023 | 33.914 | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges |