



Expertise

Protocol number: 46210481
Order No. / Reference: 26535079
Inspection date: 25 Jun 2026

Manufacturer: Ford
VIN: WF0JXXWPCJNP22584

Model: S-Max 2.0 EcoBlue Aut. Trend



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford S-Max 2.0 EcoBlue Aut. Trend	
Vehicle Identification number	WF0JXXWPCJNP22584
Mileage (Read)	111,166 km
First registration	20 Apr 2023
Number of holders	1
Power / Engine displacement	110 kw / 1,995 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Obsidian Black Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	5 Monat(e)
Last service on / at	11/2025 at 100,215 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP448041
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BKM 01249		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,555 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103Y	Summer tyres on Light alloy	Barum	8mm / 8mm
2)	235/55 R17 103Y	Summer tyres on Light alloy	Barum	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Storage compartments (illuminated glove compartment - map pockets on the driver's and passenger's seat backrests)
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated (with integrated turn signals and ambient lighting and electrically foldable)
- third brake light
- Tachometer
- Electric front and rear windows (with anti-pinch protection and automatic opening and closing function)
- Electronic parking brake
- Luggage compartment cover (removable)
- Transmission: 8-speed automatic transmission (with manual shift option)
- Interior lighting with delay circuit
- Isofix mounting (on all seats in the 2nd row)
- Electric child safety lock
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- Radiator grille (upper part) - with chrome decorative trim
- Steering wheel: Steering column, adjustable in height and reach
- Steering wheel: Paddle shifters on the steering wheel
- Front center console with padded armrest (storage compartment under the armrest - 2 cup holders - 12-volt socket at the rear)
- Fog lights (with static cornering lights)
- Emergency brake light (pulsating illumination of the brake lights during hard braking)
- Upholstery: Cloth
- Tire repair kit (for use at a maximum speed of 80 km/h)
- Tire Pressure Monitoring System (TPMS)
- Headlight dipped beam with switch-off delay including "greeting function"
- Seats: Driver and front passenger seats, 4-way manually adjustable (including manually adjustable lumbar support)
- Seats: Front sports seats
- Start-stop system
- Storage compartment under driver and passenger seats
- Daytime running light
- Carpet floor mats in the front
- Immobiliser
- Central locking with remote control (and remote luggage compartment release; door lock only on driver's side)
- Anti-lock braking system (ABS) (with Electronic Stability Program (ESP), Roll Stability Control (RSC) and Traction Control System (TCS))
- Tires: 7.5 J x 17 alloy wheels (4) with 235/55 R 17 tires (in 10-spoke design)
- Hill start assist
- Diesel particulate filter (DPF)
- Driver information system display 10.7cm color (on-board computer with fuel consumption and mileage information as well as outside temperature display)
- Ford Power Start function (keyless start)
- Luggage compartment lighting
- Back window, heater
- rear window wiper
- Intelligent Protection System (IPS): - Active headrests, front, height-adjustable - Front airbag for driver and front passenger - Knee airbag for driver - Head and shoulder airbags, front and for 2nd row of seats - Side airbag for driver and front passenger - Seat belt tensioners and belt force limiters, front - 3-point seat belts on all seats, height-adjustable in the front)
- Steering wheel: Multifunction leather steering wheel and leather gear knob
- Front and rear reading lights (with LED technology)
- MyKey key system (individually programmable second key) (setting options include: - Limiting the maximum speed and radio volume (to max. volume 15 out of 32) - Speed warning (when the set speed limit is exceeded) - Safety assistance systems cannot be deactivated - Extended warning system for unfastened seat belts)
- Radio equipment: Audio system CD (Radio-CD player MP3-compatible, 8 speakers, USB port, diversity antenna and steering wheel remote control)
- Electro-mechanical power steering (EPAS - Electric Power Assisted Steering)
- Seats: Flexible seating system "FoldFlatSystem (FFS)" (2nd row of seats with 3 individual seats - adjustable longitudinally - seat backrests adjustable for tilt and individually foldable - headrests retractable)
- Power outlet: 12-volt connection at the front (and in the first row of seats in the passenger compartment)
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats

Extra equipment

- Business Package
- Package: Winter (heated windscreen - individually and variably heated front seats)
- Safety partition net behind the 2nd row of seats
- Paint finish: Metallic
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Blind Spot Assist



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Door - front right side	Door handle - outside - Scratch(es) - Smart repair
2	Boot lid / rear door	Seal - Broken / torn - Replace
3	Door - rear right side	Door - Scratch(es) - Smart repair
4	Door - rear left side	Door (Wellig) - Unprofessionally repaired - Repair and paint
5	Door - front left side	Door (Wellig) - Unprofessionally repaired - Repair and paint
6	Door - front right side	Door (Wellig) - Unprofessionally repaired - Repair and paint

Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
2	Bonnet	Bonnet - dent(s) - No deduction
3	Front bumper	Front bumper - dent(s) - No deduction
4	Boot lid / rear door	Boot lid - dent(s) - No deduction
5	Side panel - rear left side	Side panel - dent(s) - No deduction
6	Vehicle glazing	Windscreen - Stone chips - No deduction
7	Side panel - rear right side	Side panel - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Interior - Separation net

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, not professionally repaired	
2	Side right, not professionally repaired	



Repainting

No. Repainting

- 1 Bonnet, Side panel - rear left side, Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
- 2 Door - rear left side, Door - front left side, Unprofessionally carried out, Invoice of repair done Non-existent
- 3 Door - front right side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Bonnet	221 µm	Side panel - rear left side	281 µm
Side panel - rear right side	161 µm	Door - rear left side	167 µm
Door - front left side	185 µm	Door - front right side	213 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

An unprofessionally repaired previous damage was found at the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Navigation



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Damage 1: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 1: Door - front right side: Door handle - outside - Scratch(es) - Smart repair




Damage 1: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 2: Boot lid / rear door: Seal - Broken / torn - Replace




Damage 2: Boot lid / rear door: Seal - Broken / torn - Replace




Damage 2: Boot lid / rear door: Seal - Broken / torn - Replace




Damage 3: Door - rear right side: Door - Scratch(es) - Smart repair




Damage 3: Door - rear right side: Door - Scratch(es) - Smart repair




Damage 4: Door - rear left side: Door (Wellig) - Unprofessionally repaired - Repair and paint



Damage 4: Door - rear left side: Door (Wellig) - Unprofessionally repaired - Repair and paint




Damage 4: Door - rear left side: Door (Wellig) - Unprofessionally repaired - Repair and paint



Damage 4: Door - rear left side: Door (Wellig) - Unprofessionally repaired - Repair and paint




Damage 5: Door - front left side: Door (Wellig) - Unprofessionally repaired - Repair and paint



Damage 5: Door - front left side: Door (Wellig) - Unprofessionally repaired - Repair and paint



Damage 5: Door - front left side: Door (Wellig) - Unprofessionally repaired - Repair and paint



Damage 5: Door - front left side: Door (Wellig) - Unprofessionally repaired - Repair and paint



Damage 6: Door - front right side: Door (Wellig) - Unprofessionally repaired - Repair and paint



Damage 6: Door - front right side: Door (Wellig) - Unprofessionally repaired - Repair and paint



Damage 6: Door - front right side: Door (Wellig) - Unprofessionally repaired - Repair and paint



Damage 6: Door - front right side: Door (Wellig) - Unprofessionally repaired - Repair and paint



Repainting 1: Bonnet, Side panel - rear left side, Side panel - rear right side




Repainting 1: Bonnet, Side panel - rear left side, Side panel - rear right side



Repainting 1: Bonnet, Side panel - rear left side, Side panel - rear right side



Repainting 1: Bonnet, Side panel - rear left side, Side panel - rear right side



Repainting 1: Bonnet, Side panel - rear left side, Side panel - rear right side



Repainting 1: Bonnet, Side panel - rear left side, Side panel - rear right side



Repainting 2: Door - rear left side, Door - front left side



Repainting 2: Door - rear left side, Door - front left side



Repainting 2: Door - rear left side, Door - front left side



Repainting 2: Door - rear left side, Door - front left side



Repainting 3: Door - front right side



Repainting 3: Door - front right side