



VOLVO V40: [Redacted]

Vinnumber:	YV1MV2181J2486879	Versionname:	T2 Eco Kinetic
First Registrationdate:	10/01/2018	Fiscalpower:	
Expertise Mileage:	114598	Power Kw:	90
Bodytype:		Body colour:	Silver
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1231
Fueltype:	Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Tyres

205/55/16/92 H			
Winter tyres:	Fr.L. Vredestein: 5 mm	Fr.R. Vredestein: 5 mm	
	Re.L. Vredestein: 5 mm	Re.R. Vredestein: 5 mm	
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			205/55 R 16 92 H
Tyre size FR			205/55 R 16 92 H
Tyre size RL			205/55 R 16 92 H
Tyre size RR			205/55 R 16 92 H
Tyre type FL			Winter
Tyre type FR			Winter
Tyre type RL			Winter
Tyre type RR			Winter
Tyre make FL			2480
Tyre make FR			2480
Tyre make RL			2480
Tyre make RR			2480

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	2916,41
Interior, Stain, Forfeit	50,00



Steering wheel, Worn, Acceptable 0,00



Bumper F, Scratch(es), Repair and paint (complete) 296,58



Alloy rim RL, Scratch(es), Repair and paint (complete) 133,03



Door RL, Dent(s) and scratch(es), Repair and paint (complete) 445,79



Alloy rim FL, Scratch(es), Repair and paint (complete) 133,03



Bumper R, Scratch(es), Repair and paint (complete) 296,58



Rear window, Scratch(es), Replace 0,00



Alloy rim FR, Scratch(es), Acceptable 0,00



Wing RR, Dent(s) and scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Repair and paint (complete) 133,03



Door RR, Scratch(es), Repair and paint (complete)	445,79
---	--------



Roof pillar R, Chemical polution, Repair and paint (complete)	308,32
---	--------



Roof, Chemical polution, Repair and paint (complete)	674,26
--	--------

