



Expertise

Protocol number: 46297600  
Order No. / Reference: 26642169  
Inspection date: 4 Jun 2026

|                        |                                                                 |
|------------------------|-----------------------------------------------------------------|
| Manufacturer: Ford     | Model: Focus Turnier 1.5 EcoBlue Start-Stopp-System Aut. ACTIVE |
| VIN: WF0PXXGCHPNA25666 |                                                                 |



| Vehicle details                                               |                   |
|---------------------------------------------------------------|-------------------|
| Manufacturer / Type / Model / Equipment                       |                   |
| Ford Focus Turnier 1.5 EcoBlue Start-Stopp-System Aut. ACTIVE |                   |
| Vehicle Identification number                                 | WF0PXXGCHPNA25666 |
| Mileage (Read)                                                | 90,943 km         |
| First registration                                            | 7 Feb 2023        |
| Number of holders                                             | 1                 |
| Next periodical technical inspection                          | 05/2028           |
| (Report not on hand)                                          |                   |
| Power / Engine displacement                                   | 85 kw / 1,499 ccm |
| Fuel type / Cylinder                                          | Diesel / 4        |
| Gearbox / Number of gears                                     | Automatic / 8     |
| Type of drive                                                 | Front drive       |
| Type of vehicle                                               | Station wagon     |
| Colour / colour code                                          | Silber-Metallic   |
| Doors / Seats                                                 | 5 / 5             |
| Upholstery type                                               | Cloth             |
| Colour of upholstery                                          | Black             |
| Vehicle with smoke odor                                       | no                |



## Vehicle details

|                                                  |                              |                                |                                                            |
|--------------------------------------------------|------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete     | <b>Next maintenance in</b>     | 50 %                                                       |
| <b>Last service on / at</b>                      | 07/2025 at 80,105 km         |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                        | <b>FZG documents</b>           | ZB#1 (S) was available (copy), ZB#2 (B) was not available. |
|                                                  |                              | <b>Letter No.</b>              | GP499351                                                   |
| <b>Previous damage / Accident</b>                | Detectable                   | <b>Repainting</b>              | Detectable                                                 |
| <b>Inspection conditions</b>                     | sufficient                   | <b>Lifting equipment / pit</b> | No                                                         |
| <b>Test drive</b>                                | Not performed                | <b>Engine function test</b>    | Performed                                                  |
| <b>Manufacturer key number/ type code number</b> | 8566 / BYE 00003             |                                |                                                            |
| <b>Emission standard</b>                         | EURO6;WLTP;AP;PI/CI; M, N1 I | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,035 kg                     | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 215/55 R17 94W | Summer tyres on Light alloy | Goodyear     | 6mm / 6mm   |
| 2) | 215/55 R17 94W | Summer tyres on Light alloy | Goodyear     | 6mm / 6mm   |

### Additional tyres

| #  | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 215/55 R17 98V | Winter tyres on Light alloy | Dunlop       | 6mm / 6mm   |
| 2) | 215/55 R17 98V | Winter tyres on Light alloy | Dunlop       | 6mm / 6mm   |

### Replacement

| Typ | Tyre size | Type of tyre            | Manufacturer | Tread depth |
|-----|-----------|-------------------------|--------------|-------------|
|     | Tirefit   | Expiration date 12/2026 |              |             |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



## Equipment

## Standard equipment

- Airbag: Passenger airbag deactivation
- Exterior mirrors painted in body color, electrically adjustable, heated and foldable (with integrated turn signals)
- Tires: 7 J x 17 alloy wheels (4) with 215/55 R 17 tires (in 5-spoke design, in Black Foundry premium paint finish, diamond-turned)
- Fabric headliner
- Roof rails, black
- Diesel particulate filter (DPF)
- Electronic Shifter
- Driver information system with on-board computer, color (10.7 cm screen diagonal)
- Chassis with increased ground clearance
- Electric parking brake with auto-hold function
- Ford Power Start function (keyless start)
- Luggage compartment cover
- Luggage compartment lighting
- Speed limiter (Intelligent speed limiter with speed limit display)
- Illuminated glove compartment
- Rear window wiper
- Interior mirror, automatically dimming
- Intelligent safety system (front airbag for driver and front passenger - front and rear head and shoulder airbags - side airbag for driver and front passenger - seat belt tensioners and force limiters in the front and on the outer seats of the 2nd row - 3-point seat belts on all seats, height-adjustable in the front - safety pedal assembly)
- LED taillights
- Steering wheel: 3-spoke design steering wheel (in Sensico leather look)
- Steering column, adjustable (adjustable in height and reach)
- Center console "Premium" front
- Navigation: Ford SYNC 4 including Ford navigation system with AppLink, 13.2" touchscreen and DAB/DAB+ (6 speakers - Amazon Alexa built-in voice assistant - Android Auto and Apple CarPlay - Steering wheel controls - Digital user manual - Bluetooth hands-free calling and audio streaming - USB ports - Voice control for audio and phone - Ford Power-Up software updates - Intelligent route suggestions - Customizable user profiles - Radio player - Audible and visual route guidance, dynamic and cloud-based navigation with advanced traffic information system, lane guidance and road map for Europe)
- Tire repair kit (for use at a maximum speed of 80 km/h)
- Tire Pressure Monitoring System (TPMS)
- Headlight dipped beam (with switch-off delay)
- Selective driving mode switch (Active) (incl. 5 selectable driving modes: Normal, Sport, Eco, Slippery and Unpaved Road)
- Seats: Driver's seat height adjustable (with manually adjustable lumbar support)
- Seats: Front sports seats with enhanced lateral support
- 12-volt power outlet in the luggage compartment
- Variable radiator air intake
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Attachment points behind the second row of seats for mounting the safety partition net
- Hill start assist
- Crossover body kit (radiator grille, active design - wheel arch trim, black - side skirts, black, with silver insert - front and rear bumpers, active design)
- Roof spoiler painted in car color
- Tachometer
- Electronic Stability Program (ESP) (with Emergency Brake Assist (EBA) and Traction Control System (TCS))
- Lane keeping assist including lane keeping assist
- Electric front and rear windows (with all-around closing function)
- FordPass Connect including live traffic information (Additionally for PowerShift automatic transmission: Ford Mobile Remote remote start function)
- Cruise control
- Transmission: 8-speed automatic transmission
- Back window, heater
- Interior lighting with LED technology (front and rear and map reading lights at the front)
- Isofix mounting (including top tether anchor points on the outer seats of the 2nd row)
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- Headrests: 2 front and 3 rear, height adjustable
- LED headlights (LED low beam - LED high beam - LED daytime running lights incl. integrated LED turn signals at the front - LED cornering lights, static, incl. integrated LED fog light function and maneuvering light)
- Make-up mirrors in driver and passenger sun visors
- MyKey key system (individually programmable second key)
- Emergency call assistant
- Front and rear parking pilot system
- Upholstery: Cloth
- Post-Collision Assist (In the event of a severe collision, which would also deploy the airbag and in which the driver might be incapacitated, this system initiates the braking process. This reduces the risk of colliding with further obstacles and road users after the initial collision. The driver can intervene and operate the accelerator or brake pedal manually throughout the entire process.)
- Pre-Collision Assist (Forward Alert system with pedestrian and bicycle detection)
- Windscreen wipers with rain sensor (sensitivity adjustable)
- Headlight assistant with day/night sensor
- Electro-mechanical speed-dependent power steering (EPAS - Electric Power Assisted Steering)



- Warning system for unfastened seat belts for the 1st and 2nd rows of seats

- Seats: Passenger seat height-adjustable, manually (with adjustable lumbar support)
- Seats: Rear seat backrest (foldable, 60:40 split)
- Start-stop system
- Carpet floor mats in the front
- Lashing eyes in the luggage compartment
- Electronic immobilizer
- Central locking with remote control and remote luggage compartment release

### Extra equipment

- Paint finish: Metallic
- Package: Winter (heated windscreen - heated steering wheel - individually and variably heated front seats)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Safety partition net for luggage compartment

- Package: Easy Parking (Active Parking Assist with parking and exiting function (in conjunction with 8-speed automatic transmission including semi-automated vehicle guidance) - Door edge protection - Rearview camera with "Split View" technology)

### Brief expert findings

|                      |                                                                                                                                                                                                                                               |
|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 1 (registration document) was available, but the vehicle registration certificate Part 2 (title) was not. (Copy)                                                     |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.                                                                     |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                                                                                         |
| Engine function test | An engine test run was performed.                                                                                                                                                                                                             |

### Value reducing factors

| No. | Component group      | Description                                                             |
|-----|----------------------|-------------------------------------------------------------------------|
| 1   | 2nd wheel set        | 1 alloy rim - Scratched - No deduction                                  |
| 2   | Seat - front         | Seat cover - left side - Clean                                          |
| 3   | Trim / covers        | Door trim - front left side - Scratched - Loss in value                 |
| 4   | Boot lid / rear door | Boot lid - Glued / labelled - De-glue / neutralise                      |
| 5   | Engine               | Engine cover - Damaged - Replace                                        |
| 6   | Wheel / tyres        | Alloy rim - rear right side - Scratched - Loss in value                 |
| 7   | Mudguard - left side | Mudguard - left side - Stone chips - Paint                              |
| 8   | Rear bumper          | Rear bumper (Zusätzlich Spoiler und Blende Kratzer) - Scratched - Paint |



## Wear and tear

| No. | Component group              | Description                                               |
|-----|------------------------------|-----------------------------------------------------------|
| 1   | Vehicle glazing              | Windscreen - Stone chips - No deduction                   |
| 2   | 2nd wheel set                | 1 tyre - Scratched - No deduction                         |
| 3   | Front bumper                 | Front bumper - Stone chips - No deduction                 |
| 4   | Front bumper                 | Spoiler - Scratch(es) - No deduction                      |
| 5   | Side panel - rear right side | Side panel - dent(s) - No deduction                       |
| 6   | Bonnet                       | Bonnet - Stone chips - No deduction                       |
| 7   | Sill - right side            | Sill - dent(s) - No deduction                             |
| 8   | Side panel - rear left side  | Sill - dent(s) - No deduction                             |
| 9   | Wheel / tyres                | Alloy rim - front right side - Scratch(es) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Missing parts

### Description

Trim / covers - Floor mats

## Previous damages

| No. | Previous damage                                           | Extent of damage (Net) |
|-----|-----------------------------------------------------------|------------------------|
| 1   | Side right, Provided by user / customer, from 8 Jan 2024  | 1.244,36 €             |
| 2   | Side right, Provided by user / customer, from 14 Dec 2023 | 2.144,70 €             |

## Repainting

### No. Repainting

1 Mudguard - right side, Door - rear right side, Door - front right side, Professionally carried out

## Paint coat thickness measurement

|                         |        |                        |        |
|-------------------------|--------|------------------------|--------|
| Mudguard - right side   | 193 µm | Door - rear right side | 193 µm |
| Door - front right side | 205 µm |                        |        |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

An mehreren Karosserieteilen wurde eine erhöhte Lackschichtdicke festgestellt, was auf nachträgliche Lackierarbeiten oder Reparaturen hinweisen kann.

Da kein Hebebühnenzugang zur Verfügung stand, konnte der Unterboden nicht vollständig begutachtet werden. Schäden am Unterboden sowie an Rädern, Reifen und Felgen von innen können daher nicht ausgeschlossen werden.

Aufgrund der erheblichen Verschmutzung des Fahrzeugs ist die Erkennbarkeit von Kratzer sowie Dellen eingeschränkt.

Frontbereich Nachbesichtigung notwendig.

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



**Damage 2:** Seat - front: Seat cover - left side - Clean



**Damage 2:** Seat - front: Seat cover - left side - Clean



**Damage 3:** Trim / covers: Door trim - front left side - Scratched - Loss in value




**Damage 3:** Trim / covers: Door trim - front left side - Scratched - Loss in value



**Damage 4:** Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



**Damage 4:** Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



**Damage 5:** Engine: Engine cover - Damaged - Replace



**Damage 5:** Engine: Engine cover - Damaged - Replace



**Damage 6:** Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



**Damage 6:** Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



**Damage 6:** Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



**Damage 7:** Mudguard - left side: Mudguard - left side - Stone chips - Paint



**Damage 7:** Mudguard - left side: Mudguard - left side - Stone chips - Paint



**Damage 8:** Rear bumper: Rear bumper (Zusätzlich Spoiler und Blende Kratzer) - Scratched - Paint



**Damage 8:** Rear bumper: Rear bumper (Zusätzlich Spoiler und Blende Kratzer) - Scratched - Paint



**Damage 8:** Rear bumper: Rear bumper (Zusätzlich Spoiler und Blende Kratzer) - Scratched - Paint



**Damage 8:** Rear bumper: Rear bumper (Zusätzlich Spoiler und Blende Kratzer) - Scratched - Paint



**Damage 8:** Rear bumper: Rear bumper (Zusätzlich Spoiler und Blende Kratzer) - Scratched - Paint



**Damage 8:** Rear bumper: Rear bumper (Zusätzlich Spoiler und Blende Kratzer) - Scratched - Paint




**Damage 8:** Rear bumper: Rear bumper (Zusätzlich Spoiler und Blende Kratzer) - Scratched - Paint




**Damage 8:** Rear bumper: Rear bumper (Zusätzlich Spoiler und Blende Kratzer) - Scratched - Paint



**Damage 8:** Rear bumper: Rear bumper (Zusätzlich Spoiler und Blende Kratzer) - Scratched - Paint



**Missing part 1:** Trim / covers: Floor mats - Missing - Replace



**Missing part 1:** Trim / covers: Floor mats - Missing - Replace



**Repainting 1:** Mudguard - right side, Door - rear right side, Door - front right side



**Repainting 1:** Mudguard - right side, Door - rear right side, Door - front right side



**Repainting 1:** Mudguard - right side, Door - rear right side, Door - front right side



**Repainting 1:** Mudguard - right side, Door - rear right side, Door - front right side



**Repainting 1:** Mudguard - right side, Door - rear right side, Door - front right side



**Repainting 1:** Mudguard - right side, Door - rear right side, Door - front right side