



Expertise

Protocol number: 46550588
Order No. / Reference: 26566618
Inspection date: 15 Jul 2026

Manufacturer: Ford

Model: Kuga 2.5 Duratec PHEV TITANIUM X

VIN: WF0FXXWPMHPK60250



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Kuga 2.5 Duratec PHEV TITANIUM X	
Vehicle Identification number	WF0FXXWPMHPK60250
Mileage (Read)	99,285 km
First registration	17 Apr 2023
Number of holders	1
Next periodical technical inspection	05/2028
(Report on hand)	
Power / Engine displacement	112 kw / 2,488 ccm
Fuel type / Cylinder	Hybr.B/E ext.aufll / 4
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Blazer Blue
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Anthracite-Black
Vehicle with smoke odor	no



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	93 %
Last service on / at	05/2026 at 98,071 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT884494
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BTM 00020		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,320 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R20 103V	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	245/45 R20 103V	Summer tyres on Light alloy	Continental	4mm / 4mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R17 106H	Winter tyres on Light alloy	Pirelli	6mm / 6mm
2)	225/65 R17 106H	Winter tyres on Light alloy	Pirelli	7mm / 7mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Acoustic Vehicle Alerting System (AVAS)
- Anti-lock braking system
- Passenger airbag deactivation
- Tires: Tire repair kit
- Fabric headliner
- Roof spoiler
- Tachometer
- Driving mode switch selective
- Electric front and rear windows with all-around closing function
- Ford EcoCoach
- FordPass Connect
- Luggage compartment cover, roller blind, removable
- Luggage compartment lighting
- Transmission: continuously variable automatic transmission
- Heated rear window
- rear window wiper
- Intelligent Protection System (IPS)
- Air conditioning with automatic temperature control
- Front and rear headrests (5) height adjustable
- Charging cable for household socket
- Steering wheel: Steering wheel, 3-spoke design, in Sensico synthetic leather
- Rear center armrest with two cup holders
- Front center console with integrated armrest
- Navigation system: Ford navigation system including Ford SYNC 3
- Front and rear parking pilot system
- Post-Collision Assist
- Pre-Collision Assist
- Tire Pressure Monitoring System (TPMS)
- Windscreen wipers with rain sensor
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Seats: Driver's seat electrically adjustable, 10-way including electrically adjustable lumbar support
- Seats: Rear bench seat, sliding, with split-folding backrest
- Seats: Front seats, individually and variably heated
- Carpet floor mats front and rear, velour
- Immobiliser
- Ambient lighting at the front
- Electrically adjustable, heated and folding exterior mirrors
- Tires: 7 J x 17 alloy wheels (4) in 5x2-spoke design
- third brake light
- Roof rails, silver-colored
- 12.3-inch digital instrument panel
- Electronic Safety and Stability Program (ESP)
- Lane keeping assist including lane keeping assist
- Electric parking brake with auto hold function
- Ford Easy Fuel
- Ford Power Start Function & Ford Key Free System
- Geofencing - Display of emission zones with Euro 6 and higher in the SYNC navigation device
- Cruise control
- Illuminated glove compartment
- Electric tailgate, sensor-controlled (opens via foot movement)
- Interior mirror, automatically dimming
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Paint finish: Solid
- LED taillights
- Steering column, adjustable in height and reach
- Illuminated makeup mirrors in the driver's and passenger's sun visors
- MyKey key system
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Upholstery: Premium Sensico upholstery in leather look/fabric
- Radio accessories: B&O Sound System
- Rear view camera
- Headlights with delayed shut-off
- Power steering
- Seats: Passenger seat, 8-way manually adjustable
- Seats: Map pockets on the driver's and front passenger's seat backrests
- Seats: Front sports seats with integrated headrests
- Static LED headlights
- Variable radiator air intake
- Central locking with remote control and remote luggage compartment release



Extra equipment

- All-weather floor mats in a tub shape with raised edges
- Mounting points behind the first and second row of seats according to ISO 27955, (required for the installation of the safety partition available as an accessory from your participating Ford dealer)
- Anti-theft alarm system including double locking with interior monitoring (including dual-tone horn)
- Rear bumper protector/loading sill protector
- Mounting accessories
- Package: Driver Assistance Package (Automatic Transmission) (Intelligent Adaptive Cruise Control with Traffic Sign Recognition System - Traffic Jam Assist with Stop&Go Function and Lane Keeping Assist - Wrong-Way Driver Warning System - Evasive Steering Assist - Driver Drowsiness Detection - Pre-Collision Assist including Forward Collision Warning System with Cross Traffic Alert - Blind Spot Assist with Emergency Braking Function and Trailer Detection - Active Park Assist with Parking Assist and Semi-Autonomous Vehicle Steering - Front Camera with Split View - Door Edge Protectors - Intelligent Speed Limiter with Speed Limit Display)
- Panoramic sliding sunroof, electric, including roof console with glasses storage compartment
- Wind deflectors for rear side windows, transparent
- Wind deflectors for front side windows, transparent
- Cigarette lighter and ashtray in the center console
- Swiveling towbar (incl. ESP trailer stabilization)
- Tires: 8 J x 20 light alloy wheels (4) in 10-spoke design in Pearl Grey premium paint finish (gloss-turned, with tires 245/45 R20)
- Dash Cam with Full HD resolution
- Luggage compartment tray
- Reversible luggage compartment mat
- Inductive charging station for mobile devices (The inductive charging station allows you to charge your compatible smartphone while driving without the hassle of connecting it to a cable. The charging station is located in the vehicle's center console and is only activated when it comes into contact with a compatible device. If you place a wallet or other items on the charging station, it remains inactive.)
- Package: Technology (Adaptive LED headlights with glare-free high beam assist and dynamic cornering lights, automatic headlight range control and LED fog lights - Head-up display)
- Package: Winter II (Heated windscreen - Heated leather steering wheel - Heated outer rear seats)
- Seats: Ford ergonomic seats, driver and front passenger seats, 18-way adjustable (position, height and tilt of the backrest and seat cushion electrically adjustable - thigh support, manually extendable - lumbar support 4-way electrically adjustable - front headrests, 4-way adjustable)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Boot lid - Glued / labelled - De-glue / neutralise
2	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
3	Body	B-pillar - left side - dent(s) - Smooth repair work
4	Roof	Roof - dent(s) - Smooth repair work
5	Side panel - rear left side	Sill - dent(s) - Smooth repair work
6	Door - front left side	Door - dent(s) - Smooth repair work
7	Mudguard - left side	Mudguard - left side - Stone chips - Smart repair
8	Interior	Interior - Odour - Ozone treatment
9	Rear bumper	Rear bumper (unpainted) - dent(s) - Loss in value
10	Wheel / tyres	Alloy rim - front right side (Materialabtrag) - Scratch(es) - Replace
11	Front bumper	Front bumper (Sandstrahleffekt) - Stone chips - Paint
12	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint
13	Vehicle glazing	Windscreen - Stone chips - repair according to calculation

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Door - rear right side	Door - Stone chips
3	Wheel / tyres	Alloy rim - rear right side - Scratch(es)
4	Boot lid / rear door	Rear spoiler - dent(s)

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 5 May 2023	660,73 €
2	Side right, Provided by user / customer, from 18 Jul 2025	1.736,91 €
3	Side right, Provided by user / customer, from 28 Feb 2026	1.899,95 €
4	Side - left, Provided by user / customer, from 2 Oct 2023	8.997,09 €

Repainting

No.	Repainting
1	Roof rail - right side, Professionally carried out, Invoice of repair done Non-existent
2	Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent
3	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
4	Door - rear left side
5	Door - rear left side, Professionally carried out, Invoice of repair done Non-existent
6	Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
7	Door - front left side



Paint coat thickness measurement

Roof rail - left side	170 µm	Roof rail - right side	186 µm
Side panel - rear left side	794 µm	Side panel - rear right side	240 µm
Door - rear left side	182 µm	Door - rear right side	252 µm
Door - front left side	167 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.





Figure 36: Misc.



Damage 1: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



Damage 1: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise




Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 3: Body: B-pillar - left side - dent(s) - Smooth repair work



Damage 3: Body: B-pillar - left side - dent(s) - Smooth repair work



Damage 4: Roof: Roof - dent(s) - Smooth repair work




Damage 4: Roof: Roof - dent(s) - Smooth repair work




Damage 5: Side panel - rear left side: Sill - dent(s) - Smooth repair work



Damage 5: Side panel - rear left side: Sill - dent(s) - Smooth repair work




Damage 6: Door - front left side: Door - dent(s) - Smooth repair work



Damage 6: Door - front left side: Door - dent(s) - Smooth repair work



Damage 6: Door - front left side: Door - dent(s) - Smooth repair work



Damage 6: Door - front left side: Door - dent(s) - Smooth repair work



Damage 7: Mudguard - left side: Mudguard - left side - Stone chips - Smart repair



Damage 7: Mudguard - left side: Mudguard - left side - Stone chips - Smart repair



Damage 7: Mudguard - left side: Mudguard - left side - Stone chips - Smart repair




Damage 9: Rear bumper: Rear bumper (unpainted) - dent(s) - Loss in value




Damage 9: Rear bumper: Rear bumper (unpainted) - dent(s) - Loss in value



Damage 10: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratch(es) - Replace



Damage 10: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratch(es) - Replace



Damage 11: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



Damage 11: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



Damage 11: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



Damage 11: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint




Damage 11: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 13: Vehicle glazing: Windscreen - Stone chips - repair according to calculation




Damage 13: Vehicle glazing: Windscreen - Stone chips - repair according to calculation



Damage 13: Vehicle glazing: Windscreen - Stone chips - repair according to calculation



Wear and tear 2: Door - rear right side: Door - Stone chips



Wear and tear 2: Door - rear right side: Door - Stone chips



Wear and tear 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es)



Wear and tear 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es)



Wear and tear 4: Boot lid / rear door: Rear spoiler - dent(s)




Repainting 1: Roof rail - right side



Repainting 1: Roof rail - right side




Repainting 2: Side panel - rear left side



Repainting 2: Side panel - rear left side



Repainting 3: Side panel - rear right side



Repainting 3: Side panel - rear right side



Repainting 4: Door - rear left side



Repainting 4: Door - rear left side



Repainting 5: Door - rear left side



Repainting 5: Door - rear left side




Repainting 6: Door - rear right side



Repainting 6: Door - rear right side



Repainting 6: Door - rear right side



Repainting 7: Door - front left side



Repainting 7: Door - front left side




Roof rail - left side: 170 µm



Roof rail - right side: 186 µm



Side panel - rear left side: 794 µm



Side panel - rear right side: 240 µm



Door - rear left side: 182 µm



Door - rear right side: 252 µm



Door - front left side: 167 µm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0FXXWPMHPK60250

Hersteller / Modell: FORD FORD Kuga 2.5 Duratec PHEV TITANIUM X

Datum	KM-Stand	Beschreibung
03.06.2026	98.072	HU + AU
28.05.2026	98.071	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
14.11.2025	82.296	Motoröl b. Wartung; Regelwartungsdienst
04.04.2025	61.710	Bremsflüssigkeit; Bremsflüssigkeit ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern
20.09.2024	45.954	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
23.01.2024	23.138	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst