

VIN	WMWLV1104 02M92181
Brand	MINI
Model	MINI CLUBMAN

Registration date	01/01/1900
Licence Plate	2AQU041

Exterior Color	Unknown
Odometer	100 907 km

Arrival Date	19/12/2025
Assign Date	19/12/2025

Inspection ID	6655673
Fleet owner	LIZY Belgique

Inspection date	29/12/2025
Inspection loc.	Parc Lizy



Load cover	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Fire extinguisher	✓
Triangle	✗
Safety vest	✗

Service manual holder	✓
User manual	✓
Spare key	✓
Key	✓
Certificate of conformity	✓
Title / License document	✓
First aid kit	✗

Diagram illustrating the tire placement for the vehicle:

- Front axle (Left side): Uniroyal 225/45/17 V All seasons 7.0 mm
- Front axle (Right side): Uniroyal 225/45/17 V All seasons 7.0 mm
- Rear axle (Left side): Michelin 225/45/17 V All seasons 4.0 mm
- Rear axle (Right side): Michelin 225/45/17 V All seasons 4.0 mm

1		Part	Interior boot lining	Repair Time	-	Part Cost	-
		Position	-	Repair Cost	-	Gross Cost	68.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	68.00€	Net Cost	68.00€
2		Part	Interior cleaning	Repair Time	1.00	Part Cost	-
		Position	-	Repair Cost	60.00€	Gross Cost	60.00€
		Damages	Stained/dirty	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Cleaning	Flat Rate	60.00€	Net Cost	60.00€

DEKRA Automotive Solutions

3		Part	Bumper	Repair Time	2.50	Part Cost	-
		Position	Back	Repair Cost	150.00€	Gross Cost	294.00€
		Damages	Dented	Paint Time	1.80	Depreciation %	-
		Severity	-	Paint cost	144.00€	Depreciation	-
		Repair mode	Repair	Flat Rate	-	Net Cost	294.00€
4		Part	Lower bumper	Repair Time	-	Part Cost	-
		Position	Back	Repair Cost	-	Gross Cost	90.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	90.00€	Net Cost	90.00€
5		Part	Wing moulding	Repair Time	-	Part Cost	-
		Position	Back left	Repair Cost	-	Gross Cost	90.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	90.00€	Net Cost	90.00€
6		Part	Tailgate / Boot door	Repair Time	-	Part Cost	-
		Position	Back left	Repair Cost	-	Gross Cost	49.00€
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	49.00€	Net Cost	49.00€
7		Part	Alloy wheel 17"	Repair Time	-	Part Cost	-
		Position	Front left	Repair Cost	-	Gross Cost	165.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	165.00€	Net Cost	165.00€
8		Part	Wing moulding	Repair Time	-	Part Cost	-
		Position	Front left	Repair Cost	-	Gross Cost	90.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	90.00€	Net Cost	90.00€
9		Part	Carpet	Repair Time	-	Part Cost	-
		Position	-	Repair Cost	-	Gross Cost	68.00€
		Damages	Burnt	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	68.00€	Net Cost	68.00€

DEKRA Automotive Solutions

10		Part	Door	Repair Time	-	Part Cost	-
		Position	Back left	Repair Cost	-	Gross Cost	-
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
11		Part	Fabric door lining	Repair Time	-	Part Cost	-
		Position	Back left	Repair Cost	-	Gross Cost	68.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	68.00€	Net Cost	68.00€
12		Part	Alloy wheel 17"	Repair Time	-	Part Cost	-
		Position	Back right	Repair Cost	-	Gross Cost	165.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	165.00€	Net Cost	165.00€
13		Part	Wing moulding	Repair Time	-	Part Cost	-
		Position	Back right	Repair Cost	-	Gross Cost	90.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	90.00€	Net Cost	90.00€
14		Part	Door	Repair Time	0.30	Part Cost	-
		Position	Back right	Repair Cost	18.00€	Gross Cost	18.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Polishing	Flat Rate	18.00€	Net Cost	18.00€
15		Part	Door sill	Repair Time	-	Part Cost	-
		Position	Back right	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
16		Part	Fabric door lining	Repair Time	-	Part Cost	-
		Position	Back right	Repair Cost	-	Gross Cost	68.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	68.00€	Net Cost	68.00€
17		Part	Roof	Repair Time	0.30	Part Cost	-
		Position	-	Repair Cost	18.00€	Gross Cost	18.00€
		Damages	Chemical deposit	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Polishing	Flat Rate	18.00€	Net Cost	18.00€

DEKRA Automotive Solutions

18		Part	Alloy wheel 17"	Repair Time	-	Part Cost	-
		Position	Front right	Repair Cost	-	Gross Cost	165.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	165.00€	Net Cost	165.00€
19		Part	Triangle	Repair Time	-	Part Cost	11.24€
		Position	-	Repair Cost	-	Gross Cost	11.24€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	11.24€
20		Part	Safety vest	Repair Time	-	Part Cost	5.00€
		Position	-	Repair Cost	-	Gross Cost	5.00€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	5.00€
21		Part	First aid kit	Repair Time	-	Part Cost	16.44€
		Position	-	Repair Cost	-	Gross Cost	16.44€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	16.44€
22		Part	Fabric seat	Repair Time	1.70	Part Cost	228.71€
		Position	Front left	Repair Cost	102.00€	Gross Cost	330.71€
		Damages	Burnt	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	330.71€

Comments

OVB van geur
OVB voertuig nat

Summary Inspection

Gross Price	1,929.39€	Depreciation	-	Net Price	1,929.39€
-------------	-----------	--------------	---	-----------	-----------

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	60.00€	5.80	348.00€	-	-	348.00€
Paintwork	80.00€	1.80	144.00€	-	-	144.00€
Paint preparation	80.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	261.39€	-	-	261.39€
Flat Rate	1,176.00€	-	-	1,176.00€

Signatures		
Signature Receiver	Signature Expert	Signature Customer / Driver