



Expertise

Protocol number: 46525895
Order No. / Reference: 26584535
Inspection date: 8 Jul 2026

Manufacturer: Kia

Model: Niro 1.6 GDI PHEV 2WD OPF Aut. Vision

VIN: KNACD81DGM5460614



Vehicle details	
Manufacturer / Type / Model / Equipment	
Kia Niro 1.6 GDI PHEV 2WD OPF Aut. Vision	
Vehicle Identification number	KNACD81DGM5460614
Mileage (Read)	119,876 km
First registration	29 Mar 2021
Number of holders	1
Next periodical technical inspection	03/2028
(Report on hand)	
Power / Engine displacement	77 kw / 1,580 ccm
Fuel type / Cylinder	Hybr.B/E ext.aufll / 4
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Schneeweiß
Doors / Seats	5 / 5
Upholstery type	Part leather
Colour of upholstery	Black
Re-import	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	10,808 km
Last service on / at	03/2026 at 115,684 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC757481
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8253 / AGL 00018		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,000 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92H	Summer tyres on Light alloy	Michelin	3mm / 3mm
2)	205/60 R16 92H	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92H	Winter tyres on Steel	Dunlop	5mm / 5mm
2)	205/60 R16 92H	Winter tyres on Steel	Dunlop	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
Tirefit		Expiration date 12/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the luggage compartment floor
- Airbag: 2 front airbags
- Airbag: 2 curtain airbags
- Dashboard and door trim with gloss black applications
- Electrically adjustable exterior mirrors
- Exterior mirrors with integrated LED turn signals
- Brake Assist (BAS)
- Third brake light with LED
- twilight sensor
- Electric windows, front and rear
- Forward Collision Warning (FCA) with braking intervention and pedestrian detection
- Countersteering support
- Luggage compartment lighting
- Adaptive cruise control
- Rear diffuser in aluminum look
- rear window wiper
- Interior rearview mirror self-dimming (electrochromatic)
- Insulating glazing for the windshield
- Headrests on all seats are height-adjustable.
- Charging cable (Schuko plug to Type 2 plug)
- Heated steering wheel
- Steering wheel: Multifunction steering wheel
- Steering wheel: Paddle shifters on the steering wheel
- front center armrest
- Fog light
- Rear parking sensors
- Radio accessories: 6 speakers
- Radio accessories: USB port
- Tire pressure monitoring system (TPMS)
- Wheels: Tire repair kit
- LED taillights
- Power steering
- Seat: Passenger seat height adjustable
- Seat: Front seat heating
- Lane Keeping Assist active (LKA)
- Bumper underside, wheel arches and side sills black
- Phone accessories: Bluetooth hands-free kit
- Virtual Engine Sound System (VESS) for pedestrian protection
- Central locking with remote control

Extra equipment

- Charging cable Type 2 to Type 2 plug

- Airbag: 1 knee airbag (driver's side)
- Airbag: 2 side airbags
- Anti-lock braking system (ABS)
- Electrically folding exterior mirrors
- Exterior mirrors with gloss black accents
- Hill start assist
- Roof rails
- Drive Mode Select
- Electronic Stability Program (ESP) with TCS (Traction Control)
- Headlights with halogen technology
- Floor mats
- luggage compartment cover
- Speed limiter
- 6-speed dual-clutch transmission
- Back window, heater
- Interior color in black
- ISOFIX mounts on outer rear seats
- Automatic air conditioning
- Paint finish: Solid
- Leather steering wheel and leather gear knob
- Steering wheel: Steering wheel adjustable for height and reach
- Armrest - centre, rear
- Driver Alert System (DAW)
- Electronic parking brake with auto-hold function
- Upholstery: Fabric-leather combination
- Radio accessories: Digital radio reception (DAB/DAB+)
- Rain sensor
- Wheels: 16" alloy wheels
- Rear view camera
- Rear seat backrest asymmetrically split (60:40), foldable
- Seat belts
- Seat: Driver's seat height adjustable
- Sun visors with illuminated makeup mirrors
- Traffic Jam Assist (LFA)
- LED daytime running lights
- Exterior door handles in chrome
- Electronic immobilizer
- thermal insulation glazing
- Auxiliary heater, electric

- Package: P2 - Navigation Package (Kia Map Navigation (10.25 inch) incl. 7-year Kia navigation map update - Apple CarPlay and Android Auto - Digital radio reception (DAB+) - Instrument cluster with Supervision LCD display (7.0 inch) - Inductive charging station for smartphones - Traffic sign recognition for speed limits (Intelligent Speed Limit Warning, ISLW) - UVO Connect online services)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Interior	Interior - Soiled - Clean
3	Body	Body - Glued / labelled - De-glue / neutralise
4	Mudguard - left side	Mudguard - left side - Dent / paintcoat damage - Repair and paint
5	Side panel - rear right side	Side panel - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Rear of vehicle - Key trailer hitch (2x)
Equipment - charging cable (Ladekabel für Wallboxes und Öffentliche Ladestationen)

Paint coat thickness measurement

Roof	102 µm	Roof rail - left side	100 µm
Roof rail - right side	106 µm	Boot lid / rear door	89 µm
Mudguard - left side	97 µm	Mudguard - right side	98 µm
Bonnet	133 µm	Side panel - rear left side	99 µm
Side panel - rear right side	91 µm	Door - rear left side	94 µm
Door - rear right side	99 µm	Door - front left side	92 µm
Door - front right side	108 µm		



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.
- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.




Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Interior: Interior - Soiled - Clean



Damage 2: Interior: Interior - Soiled - Clean



Damage 2: Interior: Interior - Soiled - Clean



Damage 3: Body: Body - Glued / labelled - De-glue / neutralise



Damage 3: Body: Body - Glued / labelled - De-glue / neutralise



Damage 3: Body: Body - Glued / labelled - De-glue / neutralise



Damage 3: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint



Damage 4: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint



Damage 5: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 5: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 5: Side panel - rear right side: Side panel - Scratch(es) - Paint



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction



Missing part 1: Rear of vehicle: Key trailer hitch (2x) - Missing - Replace



Missing part 1: Rear of vehicle: Key trailer hitch (2x) - Missing - Replace



Missing part 2: Equipment: charging cable (Ladekabel für Wallboxes und Öffentliche Ladestationen) - Missing - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: KNACD81DGM5460614

Hersteller / Modell: KIA KIA Niro 1.6 GDI PHEV 2WD OPF Aut. Vision

Datum	KM-Stand	Beschreibung
26.03.2026	115.684	HU + AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges; Wartung Sonstiges
08.05.2025	89.035	Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges
16.10.2023	47.956	Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges
03.01.2023	29.889	Bremsflüssigkeit ern; Motoröl b. Wartung; Regelwartungsdienst; Wartung an Hochvoltanlage
16.03.2022	13.462	Motoröl b. Wartung; Regelwartungsdienst