



Expertise

Protocol number: 46705478
Order No. / Reference: 26803921
Inspection date: 24 Jul 2026

Manufacturer: Mercedes-Benz

Model: Vito 116 CDI Lang HA Aut. BASE

VIN: W1V44760313891345



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz Vito 116 CDI Lang HA Aut. BASE	
Vehicle Identification number	W1V44760313891345
Mileage (Read)	132,142 km
First registration	15 Jul 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	120 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Stahlblau
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Grey



Vehicle details

Maintenance booklet / proof	Available / incomplete	Next maintenance in	-154 Tag(e)
Last service on / at	02/2025 at 94,562		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GD332615
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / BBJ 01777		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,800 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 107T	Summer tyres on Steel rim with wheel cover	Continental	1mm / 0mm
2)	205/65 R16 107T	Summer tyres on Steel rim with wheel cover	Continental	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 107T	Winter tyres on Steel	Michelin	5mm / 5mm
2)	205/65 R16 107T	Winter tyres on Steel	Michelin	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/65 R16 107T	Summer tyres on Steel	Continental	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- AdBlue tank (24 liters)
- Attention Assistant
- Outdoor temperature display
- third brake light
- Ceiling interior light (in driver and passenger area)
- ECO start/stop function
- Electric window regulator driver/passenger (with anti-pinch protection, quick lowering and raising)
- Parking brake
- Speed limit 210 km/h
- Seatbelt warning device for driver and front passenger seat
- Tailgate with an opening angle of approximately 90°
- Instrument cluster with pixel matrix display (operated via the buttons on the multifunction steering wheel - round instruments for speedometer and tachometer or fuel level and coolant temperature - high-quality pixel matrix display in white and red between the large round instruments)
- Multifunction steering wheel (with trip computer)
- Package: BlueEFFICIENCY (Efficiency Package)
- Tires: 205/65 R 16
- Wheels: Steel rims 6.5 J x 16
- Key: 3-button remote control
- electromechanical power steering
- 12V socket
- continuous partition wall
- Lashing eyes in the cargo area
- Warning triangle
- Immobiliser
- Central locking with radio remote control
- Airbag for driver and front passenger
- Exterior mirrors, manually adjustable (2)
- Hill start assist
- Brake lights, adaptive
- Diesel particulate filter
- Electronic Stability Program (ADAPTIVE ESP) with integrated anti-lock braking system (ABS) (traction control (ASR) - electronic brake force distribution (EBD) - brake assist (BAS))
- 9G-TRONIC PLUS automatic transmission
- Lockable glove box
- Interior trim of cargo area, side
- Headrests (2), front
- Paint finish: Solid color paint
- Steering wheel adjustable for tilt and height
- Headlight range control
- Mercedes-Benz emergency call system (communication module (LTE) for digital services breakdown management)
- Upholstery: Caluma fabric, black
- Tires: Tires without specified make
- Sliding door on the right, cargo/passenger compartment
- Crosswind Assist
- Front stabilizer
- Cruise control
- First aid kit
- Pre-installation for Remote Services Plus
- Maintenance interval indicator >>ASSYST<
- Heat-insulating glass all around

Extra equipment

- Upgrading/downgrading (upgrading to 3.05 t GVW)
- Battery: fleece battery 12 V / 92 Ah
- Comfort roof control unit
- Fire extinguisher 1 kg
- Comfort locking system with IR remote control (comfort opening and closing)
- leather steering wheel
- Package: Driver Assistance Package (Blind Spot Assist - Lane Keeping Assist - COLLISION PREVENTION ASSIST)
- Spare wheel under the rear of the vehicle with jack
- Weld nuts side wall for extensions
- Seat: Lumbar support driver's seat
- Seats: Comfort passenger seat
- Sun visor, driver/passenger side, illuminated mirror
- Windshield washer fluid level warning light
- Elimination of rear lettering
- Electrically adjustable and heated exterior mirrors, left and right
- Double cup holder in the center of the cockpit
- Tempmatic controlled air conditioning
- Large fuel tank, approx. 70 liters
- LED light strip in the cargo area
- Center console with storage compartment
- Package: Smoker's package
- Rain sensor
- High-resolution reversing camera with guide lines
- Weld nuts on side wall for conversions in conjunction with lashing rails on side wall to parapet strap
- Seats: Comfort driver's seat
- Lane Keeping Assist (including instrument cluster with pixel matrix display)
- Auxiliary heater (hot water) (incl. instrument cluster with pixel matrix display)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Interior	Sun visor - left side - Broken / torn - Replace
2	Instrument panel	Air nozzle - centre (links) - Broken / torn - Replace
3	Mudguard - left side	Mudguard - left side - Scratch(es) - Smart repair
4	Front bumper	Front bumper - Scratch(es) - Loss in value
5	Instrument panel	Centre console - front - Differs from the original configuration - Smart repair
6	Wheel / tyres	Tyre - front - Worn - Replace
7	Body	Underbody panelling - Broken / torn - Replace
8	Misc.	Inspection / maintenance - Due - Perform
9	Body	Body - Glued / labelled - De-glue / neutralise
10	Side panel - rear right side	Side panel - Scratch(es) - Paint
11	Rear bumper	Rear bumper (unpainted) - Scratch(es) - Replace
12	Door - front right side	Door (unterer Teil) - Scratch(es) - Paint
13	Door - front left side	Door (unterer Teil) - Dent / paintcoat damage - Repair and paint
14	Bonnet	Bonnet - Scratch(es) - Paint
15	Sliding door, right	Sliding door - Dent / paintcoat damage - Paint
16	Boot lid / rear door	Boot lid - Deformed - Repair and paint
17	Vehicle glazing	Windscreen - Broken / torn - Replace
18	Side panel - rear left side	Side panel - Deformed - Repair and paint

Wear and tear

No.	Component group	Description
1	Roof	Roof - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Professionally repaired, Invoice of repair done Non-existent, from 31 Dec 2023	2.166,15 €

Repainting

No.	Repainting
1	Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent



Paint coat thickness measurement

Side panel - rear left side

327 µm |

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.

Comments

Der beiliegende Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Interior: Sun visor - left side - Broken / torn - Replace



Damage 2: Instrument panel: Air nozzle - centre (links) - Broken / torn - Replace




Damage 2: Instrument panel: Air nozzle - centre (links) - Broken / torn - Replace



Damage 3: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair




Damage 3: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



Damage 4: Front bumper: Front bumper - Scratch(es) - Loss in value



Damage 4: Front bumper: Front bumper - Scratch(es) - Loss in value




Damage 4: Front bumper: Front bumper - Scratch(es) - Loss in value




Damage 5: Instrument panel: Centre console - front - Differs from the original configuration - Smart repair



Damage 6: Wheel / tyres: Tyre - front - Worn - Replace




Damage 6: Wheel / tyres: Tyre - front - Worn - Replace



Damage 7: Body: Underbody panelling - Broken / torn - Replace



Damage 7: Body: Underbody panelling - Broken / torn - Replace



Damage 8: Misc.: Inspection / maintenance - Due - Perform



Damage 9: Body: Body - Glued / labelled - De-glue / neutralise



Damage 9: Body: Body - Glued / labelled - De-glue / neutralise



Damage 10: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 10: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 10: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 11: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Replace



Damage 11: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Replace



Damage 11: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Replace



Damage 11: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Replace



Damage 12: Door - front right side: Door (unterer Teil) - Scratch(es) - Paint




Damage 12: Door - front right side: Door (unterer Teil) - Scratch(es) - Paint



Damage 12: Door - front right side: Door (unterer Teil) - Scratch(es) - Paint



Damage 13: Door - front left side: Door (unterer Teil) - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front left side: Door (unterer Teil) - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front left side: Door (unterer Teil) - Dent / paintcoat damage - Repair and paint




Damage 14: Bonnet: Bonnet - Scratch(es) - Paint



Damage 14: Bonnet: Bonnet - Scratch(es) - Paint



Damage 14: Bonnet: Bonnet - Scratch(es) - Paint




Damage 14: Bonnet: Bonnet - Scratch(es) - Paint



Damage 14: Bonnet: Bonnet - Scratch(es) - Paint



Damage 14: Bonnet: Bonnet - Scratch(es) - Paint



Damage 15: Sliding door, right: Sliding door - Dent / paintcoat damage - Paint



Damage 15: Sliding door, right: Sliding door - Dent / paintcoat damage - Paint



Damage 15: Sliding door, right: Sliding door - Dent / paintcoat damage - Paint




Damage 16: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Damage 16: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Damage 16: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Damage 17: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 17: Vehicle glazing: Windscreen - Broken / torn - Replace




Damage 18: Side panel - rear left side: Side panel - Deformed - Repair and paint



Damage 18: Side panel - rear left side: Side panel - Deformed - Repair and paint



Damage 18: Side panel - rear left side: Side panel - Deformed - Repair and paint



Repainting 1: Side panel - rear left side



Repainting 1: Side panel - rear left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1V44760313891345

Hersteller / Modell: MERCEDES-BENZ MB Vito 116 CDI Lang HA Aut. BASE

Datum	KM-Stand	Beschreibung
11.09.2025	109.615	Bremsbelagfühler ern; Bremse Sonstiges; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
30.06.2025	104.162	AU
18.02.2025	94.562	Batterie ern; Systemtest/Eigendiagnose
10.02.2025	94.562	Bremsinspektion vo + hi; Regelwartungsdienst
05.12.2023	65.315	Regelwartungsdienst
20.03.2023	45.858	Bremsinspektion vo + hi
10.10.2022	32.125	Regelwartungsdienst