



Expertise

Protocol number: 46881945
Order No. / Reference: 26782872
Inspection date: 4 Aug 2026

Manufacturer: Opel

Model: Astra 1.5 D Start/Stop Sports Tourer Elegance

VIN: W0VBE8EV1M8021661



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Astra 1.5 D Start/Stop Sports Tourer Elegance	
Vehicle Identification number	W0VBE8EV1M8021661
Mileage (Read)	105,312 km
First registration	22 Jul 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,496 ccm / 3
Power	90 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Argonsilber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite



Vehicle details			
Maintenance booklet / proof	Available / complete	Next maintenance in	88 %
Last service on / at	06/2026 at 104,713 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA231373
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / ALM 00259		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,945 kg	Empty weight	

Tyres			
Mounted tyres			
#	Tyre size	Type of tyre	Tread depth
1)	205/55 R16 91V	Summer tyres on Light alloy	5mm / 5mm
2)	205/55 R16 91V	Summer tyres on Light alloy	6mm / 6mm

Replacement			
Typ	Tyre size	Type of tyre	Tread depth
	Tirefit	Expiration date 12/2025	

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 ignition keys
- Airbag for driver and passenger side
- Airbag: Head airbags, 1st and 2nd row (outer seats)
- Ambient lighting, front doors
- Automatic activation of the hazard warning lights
- Hill Start Assist
- On-board computer
- Roof rails, silver
- Diesel particulate filter (DPF)
- Electronic Stability Program Plus (ESP Plus)
- Front camera
- Transmission: 6-speed manual transmission
- rear window wiper
- Instruments, black, with high-gloss chrome rings, 3.5" driver information display
- Rear headrests (3)
- Cargo area cover
- LED daytime running lights
- Steering column, height and reach adjustable
- Sliding center armrest, front
- Pedals: Disengaging safety pedals
- Quickheat rapid heating system
- Tire repair kit
- Rear seat backrest folds forward in a 60:40 split
- Seat belts: Three-point seat belts in all seats
- Visibility equipment
- 12V power outlet in the center console
- Pre-installation for child seat mounting system "ISOFIX"
- Heat-insulating glazing, green tinted, and windshield

Extra equipment

- Detachable trailer hitch (including trailer stability program TSP)
- OPC Line interior equipment (3-spoke sport leather steering wheel, flattened - aluminum sport pedals - black headliner)
- Radio: Multimedia Navi Pro and Bose sound system (7 speakers - 1 subwoofer - 2 midrange speakers in the front and rear doors - 2 tweeters in the dashboard - digital sound processor)
- Keyless locking and starting system (for driver and passenger doors as well as the luggage compartment)
- Solar Protect heat-insulating glazing (in the rear, heavily tinted)
- Phone: Wireless charging including 2 USB ports, rear
- Heated windscreen, ThermoTec

- Storage compartments
- Airbag: Chest-pelvis side airbag for driver and front passenger side
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- third brake light
- Decorative trim strips in piano black
- Tachometer
- Electric windows front and rear
- Speed controller with limiter
- Back window, heater
- Interior lighting, front and rear
- Automatic climate control, two zones
- trunk light
- Front headrests
- LED headlights
- Light alloy wheels 7 J x 16 in a "10-spoke" design
- Lighting equipment
- Electric parking brake
- Upholstery: Fabric/Premium leather look
- Radio: Digital radio reception DAB/DAB+/DMB-R
- Tire pressure monitoring system
- Power steering
- Luggage compartment safety net
- Start/Stop System
- Traction Control (TC) Plus
- Immobiliser
- Central locking with remote control and interior switches

- Paint finish: Metallic
- Steering wheel: Heated leather steering wheel and seat heating, multi-stage, driver and front passenger (including rear footwell heating)
- Park & Go Digital (Automatic parking assistant including parking pilot, front and rear parking aid - blind spot warning in both exterior mirrors - electrically folding exterior mirrors - digital reversing camera with steering guidelines)
- Digital reversing camera with steering guidelines
- Seats: Ergonomic active seat, driver and front passenger (certified by the Campaign for Healthy Backs (AGR) Driver and front passenger seat: - Length, height and tilt adjustable - Electropneumatic lumbar support adjustable in height and length - Extendable thigh support - Pocket on the back of the front seats, driver and front passenger)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Floor mats - Broken / torn - Replace
2	Equipment	Tirefit filler - Expired - Replace
3	Side panel - rear left side	Sill - dent(s) - Smooth repair work
4	Wheel / tyres	Tyre - front left side - Damaged - Replace
5	Sill - right side	Sill - Dent / paintcoat damage - Smart repair
6	Wheel / tyres	Alloy rim - rear left side - Scratched - Loss in value
7	Wheel / tyres	Alloy rim - front left side - Scratched - Replace
8	Door - rear right side	Door - Scratched - Paint
9	Door - rear left side	Door - Scratched - Paint
10	Door - front right side	Door - Scratched - Paint
11	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint
12	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction
2	Door - front left side	Door edge - Scratched - No deduction
3	Door - front left side	Door handle - outside - Stone chips - No deduction
4	Bonnet	Bonnet - dent(s) - No deduction
5	Roof	Roof - dent(s) - No deduction
6	Front bumper	Front bumper - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Multimedia system - Navigation data storage
Interior - Rear shelf

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 30 Sept 2024	1.758,66 €
2	Front, Provided by user / customer, from 21 Jul 2022	2.014,51 €



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Fahrzeug weist dem Alter und Laufleistung entsprechende Gebrauchspuren auf.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Documents



Figure 18: Documents



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Damage 1: Trim / covers: Floor mats - Broken / torn - Replace



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Side panel - rear left side: Sill - dent(s) - Smooth repair work



Damage 3: Side panel - rear left side: Sill - dent(s) - Smooth repair work



Damage 4: Wheel / tyres: Tyre - front left side - Damaged - Replace



Damage 4: Wheel / tyres: Tyre - front left side - Damaged - Replace



Damage 5: Sill - right side: Sill - Dent / paintcoat damage - Smart repair



Damage 5: Sill - right side: Sill - Dent / paintcoat damage - Smart repair



Damage 5: Sill - right side: Sill - Dent / paintcoat damage - Smart repair



Damage 6: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Damage 7: Wheel / tyres: Alloy rim - front left side - Scratched - Replace




Damage 8: Door - rear right side: Door - Scratched - Paint



Damage 8: Door - rear right side: Door - Scratched - Paint




Damage 8: Door - rear right side: Door - Scratched - Paint




Damage 8: Door - rear right side: Door - Scratched - Paint



Damage 9: Door - rear left side: Door - Scratched - Paint




Damage 9: Door - rear left side: Door - Scratched - Paint



Damage 9: Door - rear left side: Door - Scratched - Paint




Damage 10: Door - front right side: Door - Scratched - Paint




Damage 10: Door - front right side: Door - Scratched - Paint




Damage 10: Door - front right side: Door - Scratched - Paint




Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 12: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 12: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 12: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 12: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Wear and tear 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 2: Door - front left side: Door edge - Scratched - No deduction



Wear and tear 2: Door - front left side: Door edge - Scratched - No deduction



Wear and tear 3: Door - front left side: Door handle - outside - Stone chips - No deduction



Wear and tear 3: Door - front left side: Door handle - outside - Stone chips - No deduction



Wear and tear 4: Bonnet: Bonnet - dent(s) - No deduction



Wear and tear 5: Roof: Roof - dent(s) - No deduction



Wear and tear 5: Roof: Roof - dent(s) - No deduction



Wear and tear 6: Front bumper: Front bumper - Scratched - No deduction



Wear and tear 6: Front bumper: Front bumper - Scratched - No deduction



Wear and tear 6: Front bumper: Front bumper - Scratched - No deduction



Wear and tear 6: Front bumper: Front bumper - Scratched - No deduction




Wear and tear 6: Front bumper: Front bumper - Scratched - No deduction



Wear and tear 6: Front bumper: Front bumper - Scratched - No deduction



Missing part 1: Multimedia system: Navigation data storage - Missing - Replace



Missing part 2: Interior: Rear shelf - Missing - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VBE8EV1M8021661

Hersteller / Modell: OPEL OPEL Astra 1.5 D Start/Stop Sports Tourer Elegance

Datum	KM-Stand	Beschreibung
22.06.2026	104.713	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
07.11.2025	95.438	Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
06.02.2025	81.429	Bremsflüssigkeit; Getriebeöl ern/prüfen; Motor ern; Motoröl b. Wartung; Ölfilter ern; Reparatur Sonstiges; Systemtest/Eigendiagnose; Turbolader ern
15.08.2024	77.867	AU; Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges
28.07.2023	52.759	Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Kraftstofffilter ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
22.03.2022	17.581	Motoröl b. Wartung; Regelwartungsdienst