


Vehicle details

VIN	WF0TK1E76 MMA33005	Brand	FORD	Maintenance date	-
Licence Plate		Model	Mustang Mach-E 98kWh Extended Range RWD auto	Maintenance mileage	-
Registration date	16/12/2021	Year	2021	Exterior Color	Black Metallic
Odometer	298 844 km	Engine size	-	Interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Hankook 225/60/18 Summer 7.0 mm



Hankook 225/60/18 Summer 7.0 mm



Hankook 225/60/18 Summer 6.0 mm



Hankook 225/60/18 Summer 6.0 mm

Exterior

1



Part	Wing
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

2



Part	Door
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

3



Part	Door
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

4



Part	Wing
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

5



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

7



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

8



Part	Step plate
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

9



Part	Door
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Repair

10



Part	Door
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

11



Part	Step plate
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

12



Part	Spoiler
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

13



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

15



Part	Roof post A/B/C
Position	Right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair


16



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

6




Part	Interior tailgate lining
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

</

Others

14



Part	Damage appraisal
Position	Front
Damages	Stone impact
Severity	-
Repair mode	For info