



Opel Vivaro:

Vinnnumber:	VXEVFAHKKLZ048947	Versionname:	Vivaro 2.0D 90kW GBDC L3H1 Innovation HP
First Registrationdate:	22/07/2020	Fiscalpower:	
Expertise Mileage:	183459	Power Kw:	90
Bodytype:		Body colour:	White Jade basis lak
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:		Type of rims (mounted):	Aluminium
Fueltype:	Diesel	Parking lot:	889
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	1	Rear parking sensors
GPS		Hook
Manual climate control		Sliding door right-side
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 17 / 107 / T / Aluminium	4,1 mm	Goodyear	Winter
	Right	215 / 60 / 17 / 107 / T / Aluminium	4,1 mm	Goodyear	Winter
Rear	Left	215 / 60 / 17 / 107 / T / Aluminium	6,8 mm	Goodyear	Winter
	Right	215 / 60 / 17 / 107 / T / Aluminium	5,1 mm	Goodyear	Winter

Assistance equipment

Number of charging cables (rapid charge)	0
--	----------

Service, Maintenance, Execute



Malfunction, Not functioning (well), Diagnosis



Ignition key, Missing, Replace

No pictures to display

Interior, Dirty, Cleaning






Door FL, Scratch(es), Repair and paint (complete)



Wing trim RL, Missing, Replace and paint



Side wall RL, Dent(s), Paintless dent repair



Bonnet, Stone chip(s), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Bumper FM, Scratch(es), Repair and paint (complete)



Side bar R, Scratch(es), Replace



Side wall RR, Scratch(es), Repair and paint (complete)





Boot door lining L, Scratch(es), Replace



Partition wall, Scratch(es), Repair and paint (complete)



Side wall panel RR, Crack, Replace



Bumper R, Scratch(es), Smart repair



Boot door panel RR, Scratch(es), Repair and paint (complete)



Bumper corner RL, Scratch(es), Repair and paint (complete)



Bodywork, Chemical polution, Polish



Roof, Hail damage, Paintless dent repair (hail)

