



Expertise

Protocol number: 46553099
Order No. / Reference: 26577045
Inspection date: 16 Jul 2026

Manufacturer: MAN
VIN: WMA03VUYXP9012685

Model: TGE 3.140 4X2F SB



Vehicle details

Manufacturer / Type / Model / Equipment

MAN TGE 3.140 4X2F SB	
Vehicle Identification number	WMA03VUYXP9012685
Mileage (Read)	86,722 km
First registration	14 Dec 2022
Number of holders	1
Next periodical technical inspection	04/2027
(Report on hand)	
Power / Engine displacement	103 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candy Weiß
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Re-import	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	2,100 km
Last service on / at	04/2025 at 79,327 km		
Key is / should be	1 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS155512
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1516 / AYN 58721		
Emission standard	EURO6;WLTP;AR;PI/CI;N1 III, N2	fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/75 R16 113R	Winter tyres on Steel	Nexen	5mm / 5mm
2)	205/75 R16 113R	Winter tyres on Steel	Nexen	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/75 R16 113R C	All-season tyres on Steel	Continental	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Extra equipment

- Storage package 2
- Battery with increased capacity
- Fitting point
- Wooden floor in the cargo area with wheel arch cladding
- Center wheel cover with chrome emblem
- Steel spare wheel with road tires
- Side interior paneling in the cargo area made of plywood
- Rear step, across the entire width
- Driver and passenger airbags
- Cab doors, additionally with reinforced door seals
- All-season tyres
- MAN Media Van package with 4 speakers
- Smoker's version
- Rear View reversing camera
- Comfort seat, left
- Lashing rails in the cargo area



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Door - front right side	Door - dent(s) - Smart repair
2	Boot lid / rear door	Rear door - left side - dent(s) - Smooth repair work
3	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Smart repair
4	Body	C-pillar - left side - Dent / paintcoat damage - Smart repair
5	Door - front left side	Door - dent(s) - Smooth repair work
6	Tail light	Tail lamp - right side - Damaged - Replace
7	Body	Body - Glued / labelled - De-glue / neutralise
8	Side panel - rear left side	Wheel arch - Damaged - Repair and paint

Missing parts

Description

Equipment - Vehicle key

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Damage 1: Door - front right side: Door - dent(s) - Smart repair



Damage 1: Door - front right side: Door - dent(s) - Smart repair



Damage 2: Boot lid / rear door: Rear door - left side - dent(s) - Smooth repair work




Damage 2: Boot lid / rear door: Rear door - left side - dent(s) - Smooth repair work



Damage 3: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair



Damage 3: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair



Damage 3: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair



Damage 4: Body: C-pillar - left side - Dent / paintcoat damage - Smart repair




Damage 4: Body: C-pillar - left side - Dent / paintcoat damage - Smart repair




Damage 5: Door - front left side: Door - dent(s) - Smooth repair work



Damage 5: Door - front left side: Door - dent(s) - Smooth repair work



Damage 6: Tail light: Tail lamp - right side - Damaged - Replace



Damage 6: Tail light: Tail lamp - right side - Damaged - Replace



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 8: Side panel - rear left side: Wheel arch - Damaged - Repair and paint



Damage 8: Side panel - rear left side: Wheel arch - Damaged - Repair and paint



Damage 8: Side panel - rear left side: Wheel arch - Damaged - Repair and paint



Damage 8: Side panel - rear left side: Wheel arch - Damaged - Repair and paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WMA03VUYXP9012685

Hersteller / Modell: MAN MAN TGE 3.140 4X2F SB

Datum	KM-Stand	Beschreibung
08.05.2025	77.757	Bremsbelagfühler ern; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Bremsscheiben vorne; Reparatur Sonstiges
10.04.2025	79.327	AU; Reparatur Sonstiges; Wartung Sonstiges
11.11.2024	60.721	Motoröl b. Wartung; Ölwechsel
01.10.2024	54.055	Regelwartungsdienst
06.03.2024	32.944	Motoröl b. Wartung; Ölwechsel