



Model / version: C4 Space Tourer
Vin: VF73AHNS4NJ616019
Mileage: 65517
First registration: 20/05/2022
Color: BLEU FOREST




ADDITIONAL INFORMATION




Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✗
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

Radio
6 haut-parleurs
Feux avant de jour à LED
Lettre repère (J)
Largeur avant 7,0
Diamètre arrière 17
Indice de vitesse avant V
Largeur arrière 205
Accoudoir central avant
1199 cm3
130 ch
Métallisée vernissée

Rétroviseur intérieur miroir surveillance enfants
Siège avant gauche réglable en hauteur
Sièges avant à réglage lombaire
Garnitures cuir
Volant cuir
Aide au stationnement arrière
Équipement Stop & Start
Vitres de portes avant acoustiques
Vitres de custode teintées foncées

Radio avec système de navigation
Grand Monospace
Poignées de portes ton caisse
Diamètre avant 17
Largeur arrière 7,0
Hauteur avant 55
Indice de vitesse arrière V
Climatisation
Store de portes arrière
1.20 litre
Alternateur 150 Ampères
Freins arrière à disques

Siège avant gauche chauffant
Sièges avant réglable en hauteur
Siège avant droit rabattable
Suspension surbaissée
Volant sport
Caméra arrière de recul
Pare-brise athermique
Vitres portes arrière teintées foncées
détecteur de pluie essuie-vitre

Système navigation
Projecteurs antibrouillard
Matière : alliage
Diamètre arrière 17
Diamètre avant 17
Hauteur arrière 55
Largeur avant 205
Climatisation automatique 2 zones
Essence
96 kw
Euro 6.3
Rétroviseur intérieur jour/nuit automatique
Sièges avant chauffants
Siège avant gauche à réglage mémorisé
Sièges avant massants
Direction assistée électrique
Aide au stationnement avant
Régulateur et limiteur de vitesse
Vitres de portes avant feuilletées
Vitres de portes arrière acoustiques
Programme électronique de stabilité ESP

bras de suspension av en acier de 5 mm e1.1700 e2.75 SYM	depuis 10.21 16401	Keyless Entry/Start
pack feux d'ambiance dans l'habitacle à LED	Display HD de 12"	lecteur de panneaux de signalisation
3 sièges ar individuels et coulissants	sièges av confort	acoustique améliorée
appuis-tête ar avec position pour dormir	guide d'air radiateur réglable à taille double	protection bagages
pièces av reculées	batterie 70 Ah EFBC	radiateur de 28 dm² et de 28 mm d'épaisseur en aluminium
barre stabilisatrice av 23 mm	train ar 30000 Nm	rallonge traverse du train av
possibilité de réparation améliorée	arceaux de pavillon (Grand Picasso)	7 places
Facelift	bandeau de protection du pare-chocs av noir brillant	

EQUIPMENT

Board computer:		Central locking:	
Compressor:		Cruise control:	
Gps:		Power steering:	
Rear parking sensor:		Repair kit:	
Front seats heated:		Steering wheel:	
Electric windows:		Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Summer		
Front right	5 mm			Summer		
Rear left	5 mm			Summer		
Rear right	5 mm			Summer		

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Seat cover RL	Dirty
2	Roof liner	Stain
3	Luggage compartment cover	Stain
4	Boot lid covering R	Dirty
5	Bumper R	Scratch(es)
6	Tailgate / Boot	Scratch(es)
7	Bonnet	Scratch(es)
8	Bumper F	Damaged
9	Wing FL	Scratch(es)
11	Inner door sill RL	Dent(s) and scratch(es)
12	Wing RL	Dent(s) and scratch(es)
13	Outer door handle RL	Scratch(es)
14	Roof	Hail damage
15	Outside rear-view mirror housing R	Dent(s) and scratch(es)
16	Alloy rim FR polished	Dent(s) and scratch(es)
17	Alloy rim RL polished	Dent(s) and scratch(es)
18	Alloy rim RL polished	Dent(s) and scratch(es)
19	Alloy rim FL polished	Dent(s) and scratch(es)

Total: 18


ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
10	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS

1 - Seat cover RL - Dirty




2 - Roof liner - Stain



3 - Luggage compartment cover - Stain



4 - Boot lid covering R - Dirty



5 - Bumper R - Scratch(es)






6 - Tailgate / Boot - Scratch(es)



7 - Bonnet - Scratch(es)




8 - Bumper F - Damaged



9 - Wing FL - Scratch(es)



11 - Inner door sill RL - Dent(s) and scratch(es)





12 - Wing RL - Dent(s) and scratch(es)




13 - Outer door handle RL - Scratch(es)



14 - Roof - Hail damage





15 - Outside rear-view mirror housing R - Dent(s) and scratch(es)



16 - Alloy rim FR polished - Dent(s) and scratch(es)



17 - Alloy rim RL polished - Dent(s) and scratch(es)



18 - Alloy rim RL polished - Dent(s) and scratch(es)





19 - Alloy rim FL polished - Dent(s) and scratch(es)



10 - Bodywork - Dent(s) and scratch(es) - Renta®



SIGNATURE

Expert
30/07/2026 13:45