



Expertise

Protocol number: 46507870
Order No. / Reference: 26559489
Inspection date: 7 Jul 2026

Manufacturer: Volkswagen

Model: Golf Variant 2.0 TDI SCR Life

VIN: WVGZZCDZNW502395



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Golf Variant 2.0 TDI SCR Life	
Vehicle Identification number	WVGZZCDZNW502395
Mileage (Read)	124,465 km
First registration	4 Aug 2021
Number of holders	1
Next periodical technical inspection	08/2026
(Report on hand)	
Power / Engine displacement	85 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Uranograu
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black
readiness to drive	Not roadworthy / moveable



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	11,100 km
Last service on / at	01/2026 at 119,792 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC420569
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	0603 / CNM 00417		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,000 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91V	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	205/55 R16 91V	Summer tyres on Light alloy	Continental	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Continental	7mm / 7mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Ambient lighting
- App-Connect
- Exterior mirror housings and door handles in body color
- third brake light
- Car2X
- Decorative inlays "Nature Cross Brushed"
- Digital Cockpit Pro, multicolor
- Electronic differential lock XDS
- Electronic stability program and electromechanical brake booster
- Electric windows, front and rear
- Pedestrian protection measures expanded
- luggage compartment cover
- Transmission: 6-speed manual transmission
- Rear window wiper with intermittent function
- ISOFIX mounting points
- Front headrests
- LED reading lights at the front (2) and 2 at the rear
- LED headlights
- Dynamic headlight range control
- Non-smoking version
- Emergency call service
- Package: Seat Comfort Package
- Wheels: Alloy wheels (4) "Norfolk" 7 J x 16
- Rear bench seat undivided, backrest asymmetrically split and foldable with center armrest
- Seat belts: Three-point automatic seat belt for the middle rear seat
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Lane keeping assistant "Lane Assist"
- 12-volt power outlet in the luggage compartment
- Telephone interface with inductive charging function
- Electronic immobilizer
- Central locking without safe locking, with remote control and 2 remote folding keys
- Airbag: Head airbag system for front and rear passengers including front side airbags
- Electrically adjustable and heated exterior mirrors with memory function and passenger-side mirror lowering function.
- black roof rails
- Diesel particulate filter and SCR catalyst
- Parking assistance
- Electronic parking brake including auto-hold function
- Automatic headlight control, with LED daytime running lights
- Windscreen made of laminated safety glass, heat and sound insulating
- Speed limiter
- Rear window heated
- Rear spoiler in car color
- Rear headrests (3)
- Paint finish: Solid
- LED taillights
- Steering wheel: Multifunction leather steering wheel
- Fatigue detection
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Tire pressure monitoring system (passive)
- Wheels: Tire Mobility Set
- Keyless start system without safe locking
- electromechanical power steering
- Seat belts: Three-point automatic seat belts for the outer rear seats
- Seat covers in "Life" fabric
- Seats: Comfort seats in the front
- Start-stop system
- Bumpers in body color
- Ambient lighting with logo projection
- Green thermal insulation glazing, sides and rear



Extra equipment

- Mesh partition
- Navigation system "Discover Media" incl. "Streaming & Internet" (6+1 speakers - App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto - Multifunction camera - Navigation system "Discover Media" incl. "Streaming & Internet" - Radio - Traffic sign recognition)
- Package: Winter (Multifunction steering wheel in leather, heated - Gearshift knob in leather - Windscreen washer nozzles automatically heated - Front seats heated)
- Rear side windows and rear window tinted
- Seats: Front passenger seat backrest folds down completely
- Textile floor mats front and rear
- Towbar, foldable with electric release
- Adaptive Cruise Control ACC "stop & go" (Adaptive Cruise Control ACC incl. speed limiter - Emergency braking assistant "Front Assist" with pedestrian and cyclist detection)
- Package: Top Package (2 LED reading lights front, 2 rear, Dynamic High Beam Control, Dynamic Light Assist, Automatically dimming interior mirror, IQ.LIGHT - LED matrix headlights with LED daytime running lights, cornering lights and dynamic turn signals, Air Care Climatronic air conditioning with 3-zone temperature control, allergen filter and rear controls, LED taillights with dynamic turn signals, Dynamic headlight range control with dynamic cornering lights, Multifunction camera, Panoramic tilt/slide sunroof, Rain sensor, Bad weather lights and cornering lights)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Front bumper	Front bumper (Kleberreste Kennzeichenhalter) - Glued / labelled - De-glue / neutralise
3	Door - front right side	Door edge - Scratch(es) - Smart repair
4	Door - rear right side	Door edge - Scratch(es) - Smart repair
5	Bonnet	Bonnet - dent(s) - Smooth repair work
6	Wheel / tyres	Tyre - rear right side (Flankenbeschädigung) - Damaged - Replace
7	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Smart repair
8	Door - front left side	Door - Scratch(es) - Smart repair
9	Electronic systems	Electronic systems (Notrufsystem) - Specify findings - Perform diagnosis
10	Rear bumper	Spoiler (Kunststoffbauteil) - Scratch(es) - Replace
11	Vehicle glazing	Rear window (Tiefe Kratzer) - Scratch(es) - Replace
12	Equipment	Vehicle key - Damaged - Replace
13	Rear bumper	Rear bumper - Scratch(es) - Paint
14	Side panel - rear right side	Side panel - Dent / paintcoat damage - Paint
15	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint



Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 15 Apr 2026	1.815,45 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Der angegebene Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Front bumper: Front bumper (Kleberreste Kennzeichenhalter)
- Glued / labelled - De-glue / neutralise




Damage 2: Front bumper: Front bumper (Kleberreste Kennzeichenhalter)
- Glued / labelled - De-glue / neutralise



Damage 3: Door - front right side: Door edge - Scratch(es) - Smart repair




Damage 3: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 4: Door - rear right side: Door edge - Scratch(es) - Smart repair




Damage 4: Door - rear right side: Door edge - Scratch(es) - Smart repair



Damage 5: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 5: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 5: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 5: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 6: Wheel / tyres: Tyre - rear right side (Flankenbeschädigung) - Damaged - Replace




Damage 6: Wheel / tyres: Tyre - rear right side (Flankenbeschädigung) - Damaged - Replace



Damage 7: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Smart repair



Damage 7: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Smart repair




Damage 8: Door - front left side: Door - Scratch(es) - Smart repair



Damage 8: Door - front left side: Door - Scratch(es) - Smart repair



Damage 8: Door - front left side: Door - Scratch(es) - Smart repair



Damage 9: Electronic systems: Electronic systems (Notruffsystem) - Specify findings - Perform diagnosis



Damage 10: Rear bumper: Spoiler (Kunststoffbauteil) - Scratch(es) - Replace



Damage 10: Rear bumper: Spoiler (Kunststoffbauteil) - Scratch(es) - Replace



Damage 11: Vehicle glazing: Rear window (Tiefe Kratzer) - Scratch(es) - Replace



Damage 11: Vehicle glazing: Rear window (Tiefe Kratzer) - Scratch(es) - Replace



Damage 11: Vehicle glazing: Rear window (Tiefe Kratzer) - Scratch(es) - Replace



Damage 12: Equipment: Vehicle key - Damaged - Replace



Damage 12: Equipment: Vehicle key - Damaged - Replace



Damage 12: Equipment: Vehicle key - Damaged - Replace



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 14: Side panel - rear right side: Side panel - Dent / paintcoat damage - Paint



Damage 14: Side panel - rear right side: Side panel - Dent / paintcoat damage - Paint



Damage 14: Side panel - rear right side: Side panel - Dent / paintcoat damage - Paint



Damage 14: Side panel - rear right side: Side panel - Dent / paintcoat damage - Paint



Damage 15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVVZZZCDZNW502395

Hersteller / Modell: VOLKSWAGEN VOLKSWAGEN Golf Variant 2.0 TDI SCR Life

Datum	KM-Stand	Beschreibung
20.01.2026	119.792	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
02.01.2025	111.717	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
14.08.2024	106.840	HU + AU
14.12.2023	91.366	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
29.09.2023	78.005	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
05.05.2023	63.068	Bremsflüssigkeit ern; Motoröl b. Wartung; Regelwartungsdienst
12.07.2022	32.628	Motoröl b. Wartung; Regelwartungsdienst