

DEKRA Automotive Solutions

Vehicle details

VIN	VXKUPMHHD P4262321	Registration date	01/01/1900	Exterior Color	Unknown
Brand	OPEL	Licence Plate		Odometer	43 476 km
Model	CORSA 1.2 55kW S/S				

Inspection Details




Generic equipment

Removable element

Technical Document

Emergency compressor kit	✓	Service manual holder	✓
Refill emergency kit	✓	User manual	✓
Triangle	✓	First aid kit	✓
Safety vest	✓	Spare key	✓
Rear parcel shelf	✓	Key	✓
Fire extinguisher	✓	Certificate of conformity	✓
		Title / License document	✓

Tyres











Damages





Part	Tyre	Repair Time	0.50	Part Cost	153.00€
Position	Front left	Repair Cost	30.00€	Gross Cost	183.00€
Damages	Cut	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	Net Cost	183.00€

DEKRA Automotive Solutions

2		Part	Wheelcap 16"	Repair Time	-	Part Cost	-
		Position	Front left	Repair Cost	-	Gross Cost	25.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Lumpsum replacement	Flat Rate	25.00€	Net Cost	25.00€
3		Part	Wheelcap 16"	Repair Time	-	Part Cost	-
		Position	Back left	Repair Cost	-	Gross Cost	25.00€
		Damages	Broken	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Lumpsum replacement	Flat Rate	25.00€	Net Cost	25.00€
4		Part	Tyre	Repair Time	0.50	Part Cost	153.00€
		Position	Back left	Repair Cost	30.00€	Gross Cost	183.00€
		Damages	Cut	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	183.00€
5		Part	Wheelcap 16"	Repair Time	-	Part Cost	-
		Position	Front right	Repair Cost	-	Gross Cost	25.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Lumpsum replacement	Flat Rate	25.00€	Net Cost	25.00€
6		Part	Tyre	Repair Time	0.50	Part Cost	153.00€
		Position	Front right	Repair Cost	30.00€	Gross Cost	183.00€
		Damages	Cut	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	183.00€
7		Part	Carpet	Repair Time	-	Part Cost	-
		Position	Front left	Repair Cost	-	Gross Cost	55.00€
		Damages	Damaged	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	55.00€	Net Cost	55.00€
			brandgat				
8		Part	Bumper	Repair Time	-	Part Cost	-
		Position	Back	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
9		Part	C-pillar trim	Repair Time	-	Part Cost	-
		Position	Back right	Repair Cost	-	Gross Cost	55.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	55.00€	Net Cost	55.00€

DEKRA Automotive Solutions

10		Part	Door	Repair Time	1.00	Part Cost	-
		Position	Back right	Repair Cost	60.00€	Gross Cost	265.00€
		Damages	Dented	Paint Time	2.05	Depreciation %	-
		Severity	-	Paint cost	205.00€	Depreciation	-
		Repair mode	Repair	Flat Rate	-	Net Cost	265.00€
		● ● ● ● ●					
11		Part	Windscreen	Repair Time	1.90	Part Cost	576.02€
		Position	-	Repair Cost	114.00€	Gross Cost	690.02€
		Damages	Stone impact	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	690.02€
		● ● ●					

Comments
ovb weersomstandigheden

Signatures

Signature Receiver	Signature Expert