



Expertise

Protocol number: 46222926
Order No. / Reference: 26598375
Inspection date: 26 Jun 2026

Manufacturer: Opel

Model: Astra Sports Tourer 1.5 D Automatik Ultimate

VIN: VXXKFCYHZTR1013811



Vehicle details

Manufacturer / Type / Model / Equipment

Opel Astra Sports Tourer 1.5 D Automatik Ultimate

Vehicle Identification number VXXKFCYHZTR1013811
Mileage (Read) 102,206 km
First registration 10 Apr 2024
Number of holders 1
Next periodical technical inspection 04/2027
(Report not on hand)

Power / Engine displacement 96 kw / 1,498 ccm
Fuel type / Cylinder Diesel / 4
Gearbox / Number of gears Automatic / 8
Type of drive Front drive
Type of vehicle Station wagon

Colour / colour code Silver Metallic
Doors / Seats 5 / 5
Upholstery type Cloth / leather combination
Colour of upholstery Anthracite-Black



Vehicle details

Maintenance booklet / proof	Available / incomplete	Next maintenance in	km
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GX993582
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1889 / AEY 00108		
Emission standard	EURO6;WLTP;EA;PI/CI;M, N1, N2	fine dust sticker	
Permitted total weight	1,980 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92Y	Summer tyres on Light alloy	Michelin	4mm / 4mm
2)	225/40 R18 92Y	Summer tyres on Light alloy	Michelin	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • Storage compartments • Airbag: Front airbags, driver and front passenger • Airbag: Front and rear outer head airbags • Anti-lock braking system (ABS) • Exterior mirrors, electrically adjustable, heated and folding • Hill Start Assist • third brake light • Headliner, Black • Tachometer • Electronic Stability Program (ESP) and Traction Control with engine and brake intervention (TCPlus) • Glass sliding/sunroof, electric with spoiler position • Back window, heater • Interior rearview mirror, automatically dimming • IntelliLux LED Pixel Light • Dual-zone automatic climate control • Paint finish: Roof in carbon black • LED interior lighting • Steering wheel heating • Illuminated makeup mirrors in both sun visors • Center armrest, front and rear • Fog light • Opel Blitz logo, Astra lettering on the rear • Electric parking brake • Tire repair kit • Reversing camera: 360-degree reversing camera • Keyless locking and starting system Keyless Open & Start • safety net • Heated seats, driver and passenger • Solar Protect thermal insulation glazing • 12V power outlet in the center console • Pre-wiring for ISOFIX child seat mounting system • Heated windscreen, ThermoTec • Central locking with remote control | <ul style="list-style-type: none"> • Airbag: Chest-pelvis-side airbags, driver and front passenger • Aluminum pedals • Automatic activation of the hazard warning lights • Exterior mirror housings in black • On-board computer • Roof design line, in black • Diesel particulate filter (DPF) maintenance-free • Electronic brake force distribution (EBD) • Electric windows front and rear • Transmission: 8-speed automatic transmission • Electric, sensor-controlled tailgate • rear window wiper • Intelli-Drive 1.0 • Wiring harness for trailer hitch • Front headrests and 3 rear headrests, height adjustable • LED ambient lighting • Steering wheel: Leather steering wheel, flattened, perforated, with steering wheel remote control and paddle shifters • Navigation system, Hi-Fi sound system and head-up display • Opel Vizor with frame in high-gloss black • Parkpilot, front and rear parking aid • Tire pressure monitoring system • Rear seat backrest folds forward in a 40:20:40 split • Seat belts: Three-point seat belts in all seats • Seats: Ergonomic sport active seat driver Stoff Greta/Premium leather look • Start/Stop System • Door sill trims with Ultimate lettering, front • Electronic immobilizer • Wireless Charging |
|--|--|

Extra equipment

- 18 inch alloy wheels

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Door - rear left side	Door handle - outside - Scratch(es) - Smart repair
2	Boot lid / rear door	Boot lid - Scratch(es) - Smart repair
3	Door - front left side	Door edge - Scratch(es) - Smart repair
4	Sill - left side	Sill - Dent / paintcoat damage - Smart repair
5	Body	C-pillar - right side - dent(s) - Smart repair
6	Wheel / tyres	Tyre - front left side (nicht fahrbereit) - Damaged - Replace
7	Wheel / tyres	Tyre - front right side (nicht fahrbereit) - Damaged - Replace
8	Rear bumper	Spoiler - Scratch(es) - Smart repair
9	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
10	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
11	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Replace
12	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Replace
13	Tail light	Tail lamp - left side (2 x) - Damaged - Replace

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 12 May 2025	1.784,00 €

Paint coat thickness measurement

Side panel - rear left side	232 µm	Door - front right side	198 µm
-----------------------------	--------	-------------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Die Wartungshistorie ist nicht vorhanden und kann somit nicht auf Vollständigkeit geprüft werden.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Damage 1: Door - rear left side: Door handle - outside - Scratch(es) - Smart repair



Damage 1: Door - rear left side: Door handle - outside - Scratch(es) - Smart repair



Damage 2: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



Damage 2: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 4: Sill - left side: Sill - Dent / paintcoat damage - Smart repair




Damage 4: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 4: Sill - left side: Sill - Dent / paintcoat damage - Smart repair




Damage 4: Sill - left side: Sill - Dent / paintcoat damage - Smart repair




Damage 4: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 4: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 5: Body: C-pillar - right side - dent(s) - Smart repair



Damage 5: Body: C-pillar - right side - dent(s) - Smart repair



Damage 6: Wheel / tyres: Tyre - front left side (nicht fahrbereit) - Damaged - Replace



Damage 6: Wheel / tyres: Tyre - front left side (nicht fahrbereit) - Damaged - Replace




Damage 6: Wheel / tyres: Tyre - front left side (nicht fahrbereit) - Damaged - Replace



Damage 7: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Damaged - Replace



Damage 7: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Damaged - Replace



Damage 7: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Damaged - Replace



Damage 7: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Damaged - Replace



Damage 8: Rear bumper: Spoiler - Scratch(es) - Smart repair



Damage 8: Rear bumper: Spoiler - Scratch(es) - Smart repair




Damage 8: Rear bumper: Spoiler - Scratch(es) - Smart repair



Damage 8: Rear bumper: Spoiler - Scratch(es) - Smart repair



Damage 8: Rear bumper: Spoiler - Scratch(es) - Smart repair



Damage 9: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 9: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 9: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 9: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 10: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 10: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 11: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 11: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 11: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace




Damage 11: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 12: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace



Damage 12: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace




Damage 13: Tail light: Tail lamp - left side (2 x) - Damaged - Replace



Damage 13: Tail light: Tail lamp - left side (2 x) - Damaged - Replace



Damage 13: Tail light: Tail lamp - left side (2 x) - Damaged - Replace



Damage 13: Tail light: Tail lamp - left side (2 x) - Damaged - Replace



Damage 13: Tail light: Tail lamp - left side (2 x) - Damaged - Replace



Damage 13: Tail light: Tail lamp - left side (2 x) - Damaged - Replace



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction



Side panel - rear left side: 232 µm



Side panel - rear left side: 232 µm



Door - front right side: 198 µm



Door - front right side: 198 µm