



Expertise

Protocol number: 46470156  
Order No. / Reference: 26196230  
Inspection date: 9 Jul 2026

Manufacturer: Mercedes-Benz

Model: Vito 116 CDI Lang HA Aut. PRO

VIN: W1VVLBEZ7T4560751



| Vehicle details                             |                    |
|---------------------------------------------|--------------------|
| Manufacturer / Type / Model / Equipment     |                    |
| Mercedes-Benz Vito 116 CDI Lang HA Aut. PRO |                    |
| Vehicle Identification number               | W1VVLBEZ7T4560751  |
| Mileage (Read)                              | 15,382 km          |
| First registration                          | 16 Sept 2025       |
| Number of holders                           | 1                  |
| Next periodical technical inspection        | 09/2026            |
| (Report not on hand)                        |                    |
| Power / Engine displacement                 | 120 kw / 1,950 ccm |
| Fuel type / Cylinder                        | Diesel / 4         |
| Gearbox / Number of gears                   | Automatic / 9      |
| Type of drive                               | Rear drive         |
| Type of vehicle                             | Van                |
| Colour / colour code                        | ARKTIKWEISS        |
| Doors / Seats                               | 4 / 3              |
| Upholstery type                             | Cloth              |
| Colour of upholstery                        | Black              |
| Type of use                                 | rental car         |
| readiness to drive                          | Roadworthy         |



## Vehicle details

|                                                  |                               |                                |                                                            |
|--------------------------------------------------|-------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | Non-existent                  | <b>Next maintenance in</b>     | 420 Tag(e)                                                 |
| <b>Key is / should be</b>                        | 1 / 2                         | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                               | <b>Letter No.</b>              | HN437699                                                   |
| <b>Previous damage / Accident</b>                | None detectable               | <b>Repainting</b>              | None detectable                                            |
| <b>Inspection conditions</b>                     | sufficient                    | <b>Lifting equipment / pit</b> | No                                                         |
| <b>Test drive</b>                                | Not performed                 | <b>Engine function test</b>    | Performed                                                  |
| <b>readiness to drive</b>                        | Roadworthy                    |                                |                                                            |
| <b>Manufacturer key number/ type code number</b> | 2222 / BBJ 11512              |                                |                                                            |
| <b>Emission standard</b>                         | EURO6;WLTP;EB;PI/CI;M, N1, N2 | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,800 kg                      | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size       | Type of tyre                                   | Manufacturer | Tread depth |
|----|-----------------|------------------------------------------------|--------------|-------------|
| 1) | 225/55 R17 109H | All-season tyres on Steel rim with wheel cover | Goodyear     | 6mm / 6mm   |
| 2) | 225/55 R17 109H | All-season tyres on Steel rim with wheel cover | Goodyear     | 7mm / 7mm   |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



## Equipment

## Standard equipment

- Screw-in towing eye front/rear
- Driver's side airbag
- ATTENTION ASSIST (ATTENTION ASSIST can assist the driver on long, monotonous journeys by monitoring attention. If signs of fatigue or increasing inattention are detected, it suggests a break.)
- Fixing points in the roof frame
- Brake assist, active
- Brake lights, adaptive
- Front cupholder
- Electronic tachometer
- Electronic Stability Program (ADAPTIVE ESP) with integrated anti-lock braking system (ABS) (traction control (ASR) - electronic brake force distribution (EBD) - brake assist (BAS))
- Electric window regulator driver/passenger (with anti-pinch protection, quick lowering and raising)
- Generator management (Generator management helps reduce fuel consumption and CO2 emissions. The generator is switched off and the vehicle's electrical system is powered by the battery when it is sufficiently charged. This relieves the engine of the burden of charging the battery, for example, during acceleration. - When braking and during coasting downhill, the generator is switched on and the vehicle's kinetic energy is recuperated to charge the battery.)
- Interior trim of cargo area, side
- Tempmatic controlled air conditioning
- Comfort closing (comfort opening and closing of windows)
- Headrests (2), front
- Paint finish: Solid color paint
- Steering wheel: Multifunction steering wheel
- Mercedes-Benz emergency call system (communication module (LTE) for digital services breakdown management)
- Breakdown management
- Radio: Digital Radio DAB
- Full wheel cover
- Tires: Tires without specified make
- Wheels: Premium complete wheel protection (3 years)
- Wheels: Steel rims 6.5 J x 17
- Electric suction fan, power level 5
- Sliding door on the right, cargo/passenger compartment
- Crosswind Assist
- Seat: Lumbar support, passenger seat
- Seats: Driver's seat Plus with flat seat surface (with Rawson Plus fabric)
- Seats: Passenger seat cushion depth adjustment
- Lane Keeping Assist active
- 12V socket
- Blind Spot Assist
- Updates to the intelligent speed assistant
- Pre-installation for Remote Services Plus
- ASSYST maintenance interval indicator
- Heat-insulating glass all around
- Passenger side airbag
- Towing capacity 0 kg/lbs
- Electrically adjustable and heated exterior mirrors, left and right
- Outdoor temperature display
- Battery: fleece battery 12 V / 92 Ah
- Hill start assist
- third brake light
- COC documents
- Diesel particulate filter
- Electrical components for trailer socket (electrical lines for power supply of the trailer - without trailer hitch control unit)
- Driving light assistant (automatically switching on driving lights)
- Chassis: Standard chassis
- electric parking brake
- Generator 14 V / 250 A
- Speed limit 210 km/h
- Transmission: 9G-TRONIC
- Weight variant 2,800 kg
- Seatbelt warning device for front passenger seat
- Seatbelt warning device for driver's seat
- Lockable glove box
- Rear camera not foldable
- Boot lid
- HOLD function
- Intelligent speed assistant
- Instrument cluster with color display
- Communication module (LTE) for digital services
- Large fuel tank, approx. 70 liters
- Steering wheel adjustable for tilt and height
- Headlight range control
- Navigation: Navigation pre-installation
- Package: BlueEFFICIENCY (Efficiency Package)
- Upholstery: Caluma fabric, black
- Radio: MBUX multimedia system
- Tires: 225/55R17
- Tire pressure monitoring (on front and rear axles (wireless))
- High-resolution reversing camera with guide lines
- Headlights: halogen technology
- Key: Multi-button remote control
- electromechanical power steering
- Seat: Lumbar support driver's seat
- Seats: Comfort passenger seat
- Seats: Comfort driver's seat
- Seats: Driver's seat cushion depth adjustment
- Start-stop function
- Cruise control
- continuous partition wall
- First aid kit
- Warning triangle
- Immobiliser



- Registration as a truck

- Central locking with radio remote control

### Extra equipment

- Towing capacity 2500 kg
- Wooden floor (cargo area)
- Paintwork: Special paintwork (according to sample card)
- Package: Parking package with reversing camera (12 ultrasonic sensors (6 in the front and 6 in the rear bumper) - reversing camera - PARKTRONIC with active parking assist - Rear Cross Traffic Alert - Maneuvering brake - Drive Away Assist)
- Electrically folding exterior mirrors, left and right
- Interior lining of the cargo area up to roof height (wood)
- Load anchoring rail system
- Tires: All-season tires
- Seats: Passenger seat, two-seater
- Seat heating on driver's side
- Phone: Smartphone integration package

### Brief expert findings

|                      |                                                                                                                                                                                                                                               |
|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)                                                                  |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.                                                                     |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                                                                                         |
| Engine function test | An engine test run was performed.                                                                                                                                                                                                             |
| readiness to drive   | The vehicle was roadworthy at the time of inspection.                                                                                                                                                                                         |

### Value reducing factors

| No. | Component group              | Description                                                |
|-----|------------------------------|------------------------------------------------------------|
| 1   | Wheel / tyres                | Wheel cover - front right side - Scratch(es) - Replace     |
| 2   | Side panel - rear right side | Side panel - dent(s) - Smooth repair work                  |
| 3   | Door - front right side      | Door - Dent / paintcoat damage - Smart repair              |
| 4   | Door - front left side       | Door - Dent / paintcoat damage - Repair and paint          |
| 5   | Vehicle glazing              | Windscreen - Stone chips - repair according to calculation |

### Wear and tear

| No. | Component group          | Description                                           |
|-----|--------------------------|-------------------------------------------------------|
| 1   | Wing mirror - left side  | Cap - Scratch(es) - No deduction                      |
| 2   | Bonnet                   | Bonnet - Stone chips - No deduction                   |
| 3   | Front bumper             | Front bumper (unpainted) - Scratch(es) - No deduction |
| 4   | Wing mirror - right side | Cap - Scratch(es) - No deduction                      |
| 5   | Rear bumper              | Rear bumper - Scratch(es) - No deduction              |

The vehicle shows signs of wear and tear commensurate with its age and use.

### Missing parts

#### Description

Equipment - Vehicle key



## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
*(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
*(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Misc.




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



**Figure 25:** Misc.



**Damage 1:** Wheel / tyres: Wheel cover - front right side - Scratch(es) - Replace



**Damage 1:** Wheel / tyres: Wheel cover - front right side - Scratch(es) - Replace



**Damage 1:** Wheel / tyres: Wheel cover - front right side - Scratch(es) - Replace




**Damage 2:** Side panel - rear right side: Side panel - dent(s) - Smooth repair work




**Damage 2:** Side panel - rear right side: Side panel - dent(s) - Smooth repair work



**Damage 3:** Door - front right side: Door - Dent / paintcoat damage - Smart repair




**Damage 3:** Door - front right side: Door - Dent / paintcoat damage - Smart repair




**Damage 4:** Door - front left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 4:** Door - front left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 4:** Door - front left side: Door - Dent / paintcoat damage - Repair and paint




**Damage 4:** Door - front left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 5:** Vehicle glazing: Windscreen - Stone chips - repair according to calculation



**Damage 5:** Vehicle glazing: Windscreen - Stone chips - repair according to calculation



**Missing part 1:** Equipment: Vehicle key - Missing - Replace