



Expertise

Protocol number: 46516491
Order No. / Reference: 26652071
Inspection date: 1 Jul 2026

Manufacturer: Seat

Model: Cupra Leon Sportstourer 1.4 e-Hybrid (150 kW System)

VIN: VSSZZKL2RR022534



Vehicle details	
Manufacturer / Type / Model / Equipment	
Seat Cupra Leon Sportstourer 1.4 e-Hybrid (150 kW System)	
Vehicle Identification number	VSSZZKL2RR022534
Mileage (Read)	93,045 km
First registration	5 Oct 2023
Number of holders	1
Next periodical technical inspection	10/2026
(Report not on hand)	
Power / Engine displacement	110 kw / 1,395 ccm
Fuel type / Cylinder	Hybr.B/E ext.aufll / 4
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Black Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Anthracite-Black



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	0 km
Last service on / at	10/2025 at 67,135 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT086166
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	7593 / ART 00050		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,090 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92Y	Summer tyres on Light alloy	Bridgestone	6mm / 6mm
2)	225/40 R18 92Y	Summer tyres on Light alloy	Bridgestone	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92V	Winter tyres on Light alloy	Pirelli	6mm / 6mm
2)	225/40 R18 92V	Winter tyres on Light alloy	Pirelli	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
Tirefit		Expiration date 07/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- Storage compartment in the doors
- Airbag: Passenger airbag deactivation
- Electrically adjustable, folding and heated exterior mirrors (including passenger-side mirror lowering function)
- third brake light
- CUPRA CONNECT (prepared for activation of the security/ assistance and remote access service packages)
- Electronic differential lock (XDS) for front axle
- Drive Profile CUPRA (Driving profiles can be individually selected - Selected driving profile influences steering assistance and throttle response, chassis control (with DCC), and shift characteristics (with DSG))
- Luggage compartment lighting
- luggage compartment roller blind
- Cruise control system (CCS)
- Illuminated glove compartment
- rear window wiper
- Keyless Go (engine start/stop button)
- Climatronic air conditioning with 3-zone temperature control
- Trim strips on the side windows (outside) in Glossy Black
- Steering wheel: CUPRA sport multifunction steering wheel with shift paddles
- front center armrest
- Navigation system (prepared for activation of the CUPRA CONNECT online infotainment service package - navigation system with 12" display - 3D navigation - voice control - MAPCARE with integrated map for Europe)
- Package: Light and Sight Package (Rain sensor - Automatically dimming interior mirror - Light sensor with automatic headlight control - Automatic Coming Home and Leaving Home function)
- PreCrash Assist (Proactive occupant protection system)
- Radio: Digital radio reception DAB+
- Radio accessories: 6 speakers
- Radio accessories: Connectivity Box in the center console storage compartment including wireless charger
- Tire pressure monitoring system
- Wheels: Tyre fit
- Keyless locking and opening system, Kessy Advanced
- Servotronic
- Seat belts - three-point automatic, front and rear (warning tone for unfastened seat belts)
- Seats: Remote release for folding down the rear seat backrest into the boot
- Seats: Front sports bucket seats in "Sharp Textil"
- Smart Ambient Light (All-around ambient lighting in the interior - CUPRA Welcome Light - Interaction with assistance systems and Drive Profile)
- Start-stop system
- Door trim in leather look
- Airbag: Airbag for driver and front passenger (center airbag - side airbag for driver and front passenger - head airbag system, front and rear)
- Exterior mirror caps painted in "Dark Aluminium"
- CUPRA front brake caliper in black
- CUPRA pedals and footrest in silver/black
- Roof rails in Glossy Black
- Tachometer
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC) (Anti-lock Braking System (ABS) - Traction Control System (ASR))
- Electric window regulator with anti-pinch protection and one-touch function
- Speed limiter
- Transmission: 6-speed DSG
- Heated rear window
- ISOFIX child seat restraint system, in the 2nd row left and right (incl. top tether anchor points)
- Headrests, 2 front
- Headrests, 3 rear
- Heated steering wheel
- Front/rear reading lights
- Rear center armrest with pass-through option
- Fatigue detection
- Emergency call service (no registration required - service is activated upon delivery)
- Otto particulate filter
- Package: Dynamic (Adaptive Chassis Control DCC - Progressive Steering)
- Package: Full LED package (Full LED headlights - Full LED taillights - Turn signals with LED technology integrated into exterior mirrors - Rear turn signals with dynamic LED technology - Infinite Light; Dynamic LED light strip at the rear - Fog lights with cornering light function in LED technology - Dynamic headlight range control)
- Radio accessories: 2 USB-C ports front / 2 rear (charging function)
- Wheels: Alloy wheels (4) 7.5J x 18" "Performance I Black/Silver", diamond-turned (tires 225/40 R 18)
- Side windows from the 2nd row of seats and rear window are dark tinted.
- Seats: Passenger seat with height adjustment
- Seats: Driver's seat with height adjustment
- Seats: Lumbar support for driver/passenger seat
- Seats: Rear seat backrest asymmetrically split and foldable
- Sun visor on driver and passenger side with make-up mirror and lighting
- Lane departure warning system
- Illuminated door sill trims, front
- Ultrasonic parking aid, rear
- Lashing eyes in the luggage compartment



- Front Assist area monitoring system with City Emergency Braking function
- Electronic immobilizer
- thermal insulation glazing

- Virtual Cockpit (Fully digital instrument cluster with 10.25" TFT display)
- Central locking with remote control

Extra equipment

- Airbag: Rear side airbag and driver's side knee airbag
- Anti-theft alarm system including interior monitoring, backup horn and tow-away protection
- Mode 3 Type 2 charging cable, 16 A
- Package: Driving Assistance Package M for navigation system (Adaptive Cruise Control up to 210 km/h with predictive speed control PCC - High Beam Assist - Traffic Sign Recognition)
- Package: Vision Plus (reversing camera - parking assist with front parking aid)
- Keyless locking and opening system for anti-theft alarm system, Kessy Advanced

- CUPRA exterior mirror caps in carbon/black
- Luggage partition net
- Paint finish: Metallic
- Package: Driving Assistance Package L for navigation system (Adaptive Cruise Control up to 210 km/h with Predictive Cruise Control PCC - High Beam Assist - Side Assist incl. Blind Spot Assist - Exit Assist & Exit Warning - Traffic Sign Recognition)
- Package: Winter Package (heated front seats)
- Radio accessories: Wireless Full Link Connectivity (Android Auto - Apple CarPlay)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	2nd wheel set	1 tyre (Platt) - Perform diagnosis
2	Door - front left side	Door handle - outside - Scratch(es) - Smart repair
3	Bonnet	Bonnet - dent(s) - Smooth repair work
4	Engine	Engine cover - Damage caused by marten / rodent - Replace
5	Sill - left side	Sill - Scratch(es) - Smart repair
6	Side panel - rear left side	Side panel - Scratch(es) - Smart repair
7	Side panel - rear left side	Sill - Scratch(es) - Smart repair
8	Front bumper	Front bumper - Scratch(es) - Smart repair
9	Side panel - rear right side	Sill - Scratch(es) - Smart repair
10	Rear bumper	Rear bumper - Scratch(es) - Smart repair
11	Door - rear right side	Door - Scratch(es) - Smart repair
12	Wheel / tyres	Tyre - rear right side (nicht fahrbereit) - Damaged - Replace
13	Wing mirror - right side	Cap - Scratch(es) - Replace
14	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
15	Wheel / tyres	Alloy rim - rear right side - Scratched - Replace
16	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Replace
17	Boot lid / rear door	Boot lid - Scratch(es) - Paint
18	Vehicle glazing	Rear window - Scratch(es) - Replace



Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Side right, Provided by user / customer, from 21 May 2024	2.138,75 €
2	Side - left, Side right, Provided by user / customer, from 1 Apr 2025	8.812,39 €
3	Rear, Provided by user / customer, from 21 May 2024	14.699,33 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Damage 1: 2nd wheel set: 1 tyre (Platt) - Perform diagnosis



Damage 2: Door - front left side: Door handle - outside - Scratch(es) - Smart repair




Damage 2: Door - front left side: Door handle - outside - Scratch(es) - Smart repair




Damage 3: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 3: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 4: Engine: Engine cover - Damage caused by marten / rodent - Replace




Damage 4: Engine: Engine cover - Damage caused by marten / rodent - Replace




Damage 5: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 5: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 6: Side panel - rear left side: Side panel - Scratch(es) - Smart repair




Damage 6: Side panel - rear left side: Side panel - Scratch(es) - Smart repair




Damage 7: Side panel - rear left side: Sill - Scratch(es) - Smart repair




Damage 7: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 7: Side panel - rear left side: Sill - Scratch(es) - Smart repair




Damage 8: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 8: Front bumper: Front bumper - Scratch(es) - Smart repair




Damage 8: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 9: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 9: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 9: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 10: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 10: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 11: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 11: Door - rear right side: Door - Scratch(es) - Smart repair




Damage 12: Wheel / tyres: Tyre - rear right side (nicht fahrbereit) - Damaged - Replace




Damage 12: Wheel / tyres: Tyre - rear right side (nicht fahrbereit) - Damaged - Replace




Damage 13: Wing mirror - right side: Cap - Scratch(es) - Replace




Damage 13: Wing mirror - right side: Cap - Scratch(es) - Replace



Damage 13: Wing mirror - right side: Cap - Scratch(es) - Replace



Damage 14: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 14: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 14: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 14: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 14: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 15: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 15: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace




Damage 16: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 16: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 17: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 17: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 17: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 17: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 18: Vehicle glazing: Rear window - Scratch(es) - Replace



Damage 18: Vehicle glazing: Rear window - Scratch(es) - Replace



Damage 18: Vehicle glazing: Rear window - Scratch(es) - Replace



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction