



Expertise

Protocol number: 46632568  
Order No. / Reference: 26662974  
Inspection date: 1 Jul 2026

Manufacturer: Volkswagen

Model: Caddy Cargo 2.0 TDI BMT

VIN: WV1ZZZSK3PX080479



| Vehicle details                         |                   |
|-----------------------------------------|-------------------|
| Manufacturer / Type / Model / Equipment |                   |
| Volkswagen Caddy Cargo 2.0 TDI BMT      |                   |
| Vehicle Identification number           | WV1ZZZSK3PX080479 |
| Mileage (Read)                          | 166,424 km        |
| First registration                      | 2 Jun 2023        |
| Number of holders                       | 1                 |
| Fuel type                               | Diesel            |
| Engine displacement / Cylinder          | 1,968 ccm / 4     |
| Power                                   | 75 kW             |
| Gearbox / Number of gears               | Manual / 6        |
| Type of drive                           | Front drive       |
| Type of vehicle                         | Station wagon     |
| Colour / colour code                    | Candy White (B9A) |
| Doors / Seats                           | 4 / 2             |
| Upholstery type                         | Cloth             |
| Colour of upholstery                    | Anthracite-Grey   |



## Vehicle details

|                                                  |                          |                                |                                                            |
|--------------------------------------------------|--------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete | <b>Next maintenance in</b>     | 6,500 km                                                   |
| <b>Last service on / at</b>                      | 09/2025 at 149,000 km    |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                    | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                          | <b>Letter No.</b>              | GS577275                                                   |
| <b>Previous damage / Accident</b>                | None detectable          | <b>Repainting</b>              | None detectable                                            |
| <b>Inspection conditions</b>                     | sufficient               | <b>Lifting equipment / pit</b> | No                                                         |
| <b>Test drive</b>                                | Not performed            | <b>Engine function test</b>    | Performed                                                  |
| <b>Manufacturer key number/ type code number</b> | 0603 / CMF 00371         |                                |                                                            |
| <b>Emission standard</b>                         | EURO6                    | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,220 kg                 | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size      | Type of tyre          | Manufacturer                | Tread depth |
|----|----------------|-----------------------|-----------------------------|-------------|
| 1) | 205/60 R16 96H | Summer tyres on Steel | unterschiedliche Hersteller | 5mm / 5mm   |
| 2) | 205/60 R16 96H | Summer tyres on Steel | Kleber                      | 7mm / 7mm   |

### Additional tyres

| #  | Tyre size      | Type of tyre          | Manufacturer | Tread depth |
|----|----------------|-----------------------|--------------|-------------|
| 1) | 205/60 R16 96H | Winter tyres on Steel | Fulda        | 5mm / 5mm   |
| 2) | 205/60 R16 96H | Winter tyres on Steel | Fulda        | 7mm / 7mm   |

### Replacement

| Typ | Tyre size      | Type of tyre          | Manufacturer | Tread depth |
|-----|----------------|-----------------------|--------------|-------------|
| E   | 205/65 R15 99H | Summer tyres on Steel | Hankook      | 8 mm        |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

## Equipment

### Standard equipment

- Storage compartments: Glove compartment open
- Exterior mirrors: electrically adjustable
- Exterior mirror housings and door handles in black, sliding door track in silver
- Floor coverings: Carpet in the driver's cab
- third brake light
- Roof rail/roof rack preparation
- Three-point automatic seat belts (with front belt height adjustment and electric belt tensioners)
- Omission: Without interior safety mirror
- ESP Electronic Stability Program with Brake Assist (incl. Anti-lock Braking System (ABS), Traction Control (ASR), (EDS and MSR))
- Electric windows, front
- Halogen dual headlights-H7
- Heating and ventilation system in the driver's cab
- Interior lighting in the cargo area (1 light)
- Fuel fill quantity, standard fuel initial fill
- Diesel fuel system
- Steering column adjustable in height and tilt
- Center console with 2 universal cup holders
- Multi-collision brake
- Fatigue detection
- Non-smoking version
- Particulate filter: Diesel particulate filter (incl. SCR and AdBlue tank)
- Wheels/Tires: 205/65 R 15 99 H XL, optimized for low rolling resistance
- Gearshift lever in plastic
- Sliding door, on the right in the passenger/cargo area
- Standard side panels in the cargo area
- Speed-sensitive power steering (Servotronic)
- Seats: Height adjustment for left seat, manual
- Seats: Left and right seats in the 1st row (including headrests)
- Start-stop system (with brake energy recuperation)
- Tire Mobility Set (12-volt compressor and tire sealant)
- First aid kit, warning triangle and high-visibility vest
- Warning tone and light for unfastened front seat belts
- Green thermal insulation glazing
- Additional dust protection seal on the outside
- Airbag for driver and front passenger (with passenger airbag deactivation)
- Reinforced battery (70 Ah/ 420 A)
- Operating voltage 12 V
- Brake booster
- Cockpit panel, matte
- Three-phase generator 140 A
- Electronic parking brake including auto-hold function
- Deletion: Without rear window (sheet metal)
- Omission: Without additional child seat anchorage
- Automatic headlight control with daytime running lights
- Windows: Laminated glass front pane in heat-insulating glazing
- Transmission: 6-speed transmission
- Rear wing door (asymmetrically divided) without window cutout
- Instrument cluster (km/h) (displays for speed, total/trip distance, engine speed, fuel level and time)
- Steering wheel
- Headlight range control
- Multifunction display: 16.51 cm (6.5 inch) color touchscreen for convenient operation (with USB charging port (Type C), no radio function)
- eCall emergency call system
- Upholstery: Fabric, "Double Grid" design
- Wheels, tires: Wheel covers
- Wheels/Tires: Steel wheels 6J x 15, in black
- taillights
- Windscreen wiper intermittent control with light sensor
- Keys for locking system: 2 remote control flip keys
- Side indicator lights
- Seat belt indicator (warning tone and light for unfastened front seat belts)
- Sun visors without mirrors, with ticket pocket on the driver's side, plus airbag label on the sun visor
- Bumper in grey
- Partition wall (tall) without window
- Lashing points: 6 lashing points for securing cargo
- Electronic immobilizer
- Central locking with remote control and interior operation



## Extra equipment

- Storage compartments: Glove compartment with lockable, illuminated flap
- Floor coverings, rubber floor covering in the cargo area
- Deletion: Lettering on the rear
- Cruise control system including speed limiter
- Paint finish: Solid
- Steering wheel: Multifunction steering wheel
- Navigation system "Discover Media" (25.4 cm (10 inch) touch color display - streaming & internet - 2 USB interfaces (Type C) in the center console, front - glove compartment with lockable, illuminated flap - 4 speakers - mobile phone interface)
- Package: Cool & Sound (Refrigerant R1234yf - Safety interior mirror, automatically dimming - Air Care Climatronic air conditioning with 2-zone temperature control and air purification function)
- Radio accessories: Digital radio reception DAB+
- dimmable interior safety mirror
- Partition wall (high) with grilles
- Adaptive Cruise Control (ACC) with speed limiter
- Electrically adjustable and heated exterior mirrors
- Parking assistance (parking distance control, front and rear)
- Air conditioning system "Air Care Climatronic" with 2-zone temperature control and air purification function
- Multifunction display "Plus"
- Fog lights including cornering lights
- Emergency braking assistant "Front Assist", evasive steering assist and turning assistant (multifunction camera - multifunction steering wheel - evasive steering assist and turning assistant - auto-dimming rearview mirror - emergency braking assistant "Front Assist" with pedestrian and cyclist detection - cruise control including speed limiter - multifunction display "Plus")
- Package: Winter Package
- Wheels/Tires: Spare wheel in driving tire size, steel (spare wheel in driving tire size, steel - on-board tools and jack)

## Brief expert findings

|                      |                                                                                                                                                                                                                                               |
|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)                                                                  |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.                                                                     |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                                                                                         |
| Engine function test | An engine test run was performed.                                                                                                                                                                                                             |

## Value reducing factors

| No. | Component group        | Description                            |
|-----|------------------------|----------------------------------------|
| 1   | Door - front left side | Door edge - Scratch(es) - Smart repair |
| 2   | Sill - left side       | Sill - Scratch(es) - Smart repair      |

## Wear and tear

| No. | Component group      | Description                                     |
|-----|----------------------|-------------------------------------------------|
| 1   | Vehicle glazing      | Windscreen - Stone chips - No deduction         |
| 2   | Bonnet               | Bonnet - Stone chips - No deduction             |
| 3   | Front bumper         | Front bumper - Scratch(es) - No deduction       |
| 4   | Rear bumper          | Rear bumper - Scratch(es) - No deduction        |
| 5   | Boot lid / rear door | Rear door - left side - dent(s) - No deduction  |
| 6   | Boot lid / rear door | Rear door - right side - dent(s) - No deduction |
| 7   | Sliding door, right  | Sliding door - dent(s) - No deduction           |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Paint coat thickness measurement

Side panel - rear right side

301 µm

Door - rear right side

302 µm



## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
*(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
*(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



**Damage 1:** Door - front left side: Door edge - Scratch(es) - Smart repair



**Damage 2:** Sill - left side: Sill - Scratch(es) - Smart repair



**Damage 2:** Sill - left side: Sill - Scratch(es) - Smart repair



**Wear and tear 1:** Vehicle glazing: Windscreen - Stone chips - No deduction




**Wear and tear 3:** Front bumper: Front bumper - Scratch(es) - No deduction




**Wear and tear 3:** Front bumper: Front bumper - Scratch(es) - No deduction



**Wear and tear 4:** Rear bumper: Rear bumper - Scratch(es) - No deduction




**Wear and tear 4:** Rear bumper: Rear bumper - Scratch(es) - No deduction




**Wear and tear 4:** Rear bumper: Rear bumper - Scratch(es) - No deduction



**Wear and tear 5:** Boot lid / rear door: Rear door - left side - dent(s) - No deduction



**Wear and tear 5:** Boot lid / rear door: Rear door - left side - dent(s) - No deduction



**Wear and tear 6:** Boot lid / rear door: Rear door - right side - dent(s) - No deduction




**Wear and tear 6:** Boot lid / rear door: Rear door - right side - dent(s) - No deduction



**Wear and tear 7:** Sliding door, right: Sliding door - dent(s) - No deduction




**Wear and tear 7:** Sliding door, right: Sliding door - dent(s) - No deduction



**Side panel - rear right side:** 301 µm



**Side panel - rear right side:** 301 µm



**Door - rear right side:** 302 µm



Door - rear right side: 302 µm