

Condition Report

Ordered By

Ordered By		
------------	--	--

Vehicle

License Plate		Contract Number		Bodywork Type	Estate car	Transmission	Automatic
Brand	SKODA	VIN	TMBJR8NX9PY037770	Drive Wheel	Front-wheel-drive	First Registration	2022.11.03
Model	Octavia	Year Built	2022	Color	Black	Fuel Type	Hybrid
Label	-	Capacity	1.498 cm3	Power	110 kW	Mileage	81.912 km
MOT	2026.11.03						

Equipment

- Automatic air conditioning / digital
- Electrically adjustable front and rear windows
- Multifunction steering wheel
- ESP / DSC
- ASD / EDS / ASR
- Navigation

Documents

- Original Key
- Registration Book

Wheels

Position	Rim Type	Dimensions	Thread Depth
FL	Könnyűfém	205/55R17	5.00
FR	Könnyűfém	205/55R17	5.00
RL	Könnyűfém	205/55R17	5.00
RR	Könnyűfém	205/55R17	5.00

Paint Thickness [µm]

Part	Left Value	Right Value
Front mudguard	115	114
Engine cover	120	0
Front door	116	122
Rear door	121	202
Roof	124	0
Rear mudguard	121	175
Luggage compartment lid / Rear door	143	0

Last Service

Type	Date	KM
------	------	----

Standard Images





Unacceptable Damage

Első vészhártó

Part	Első vészhártó	Damage	Scratched	Repair Method	Painting

Bal hátsó oldalfal

Part	Bal hátsó oldalfal	Damage	Scratched	Repair Method	Painting

Jobb első ajtó

Part	Jobb első ajtó	Damage	Dented	Repair Method	Painting and Repairment

Fényezett elemek

		No images or videos available.			
Part	Fényezett elemek	Damage		Repair Method	Preparation and painting

Special Notes

A gépjármű a szemle időpontjában szennyezett volt.

Inspection Details

Inspection Place	LANZS Kft Budapest Gyömrői út	Inspection Person	Szloboda István	Inspection Date	2026.05.05
------------------	-------------------------------	-------------------	-----------------	-----------------	------------

This condition report was prepared by an expert of DEKRA-Expert Kft.
The vehicle inspection was carried out by external visual examination. No test drive was performed and no parts were disassembled during the inspection.
The calculation of unacceptable defects and deficiencies was prepared using data from the Audatex and Eurotax calculation programs.
The expert inspection was carried out in accordance with DEKRA regulations, applying the client's guidelines regarding acceptable and unacceptable defects

and deficiencies for returned vehicles.