

Expertise

Protocol number: 45304332
Order No. / Reference: 25785008
Inspection date: 27 Apr 2026

Manufacturer: Mercedes-Benz

Model: eSprinter Standard 55/47 kWh

VIN: W1V4UBHZ0SP739621



Vehicle details

Manufacturer / Type / Model / Equipment

Mercedes-Benz eSprinter Standard 55/47 kWh

Vehicle Identification number W1V4UBHZ0SP739621

Mileage (Read) 23,804 km

First registration 29 Jul 2024

Number of holders 1

Power / Engine displacement 80 kw / 0 ccm

Fuel type / Cylinder Electric / 0

Gearbox / Number of gears Direct drive / 1

Type of drive Rear drive

Type of vehicle Van

Colour / colour code ARKTIKWEISS

Doors / Seats 4 / 3

Upholstery type Artificial leather

Colour of upholstery Black



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	222 Tag(e)
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HE687959
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / BQX 00217		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	4,100 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/75 R16 121R	Winter tyres on Steel	Continental	9mm / 9mm
2)	225/75 R16 121R	Winter tyres on Steel	Continental	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/75 R16 121R	Summer tyres on Steel	Continental	6mm / 6mm
2)	225/75 R16 121R	Summer tyres on Steel	Continental	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	225/75 R16	Summer tyres on Steel	Continental	9 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Turn assist
- Storage compartment under cockpit
- Driver's side airbag
- Anti-lock braking system
- Electrically folding exterior mirrors
- Outdoor temperature display
- Battery: AC charging 11 kW / DC charging 50 kW
- Battery: High-voltage battery (56 kWh)
- Hill start assist
- Brake lights, adaptive
- ESP - Adaptive ESP9i
- Comfort electric window regulator front (driver/passenger)
- Speed limit 80 km/h
- Weight variant 4,100 kg
- Grab handle for entry to the cargo area sliding door on the partition wall
- Intelligent speed assistant
- semi-automatic air conditioning system controlled by TEMPATIC
- Paint finish: Solid color paint
- Cable duct at rear portal
- Steering wheel adjustable for tilt and height
- electric steering
- Longitudinal beam reinforcement
- Navigation: Navigation pre-installation
- Package: Maintenance Package
- Radio: Digital Radio DAB
- Radio: MBUX multimedia system
- Rain sensor
- Tires: 225/75 R16C
- Tires: Tires optimized for rolling resistance
- Tires: Summer tires
- Tire pressure monitoring (on front and rear axles (wireless))
- Sliding door on the right, cargo/passenger compartment
- Seats: Driver's seat adjustable
- Jump start contact (The jump start contact facilitates jump-starting the vehicle and externally charging the starter battery. The contact is located in the engine compartment on the air filter box.)
- Wheel chock
- Pre-installation for remote and navigation services
- Pre-installation Remote and Charging Services Premium
- Immobiliser
- Heat-insulating glass all around

Extra equipment

- Storage for smartphones including wireless charging
- Entrance rear door
- Battery: AC charging 11 kW / DC charging 115 kW

- Storage compartment above windshield
- Rear towing eye
- Acoustic environmental protection
- ATTENTION ASSIST (ATTENTION ASSIST can assist the driver on long, monotonous journeys by monitoring attention. If signs of fatigue or increasing inattention are detected, it suggests a break.)
- Battery: fleece battery 12 V / 92 Ah
- third brake light
- Roof: High roof
- Driving light assistant (automatically switching on driving lights)
- Transmission: Direct drive
- Seatbelt warning device for driver's seat
- Grab handle for entry of driver and passenger
- HOLD function
- Climate: Pre-conditioning
- Communication module (LTE) for digital services
- Headrests (2), front
- Mode 3 charging cable (Type 2, 3x20A) 8m
- Cable duct on side wall
- Steering wheel: Multifunction steering wheel
- Headlight range control
- Mercedes-Benz emergency call system (communication module (LTE) for digital services breakdown management)
- Breakdown Management (By pressing the breakdown button or via the phone book entry in the vehicle's address book, the disabled vehicle automatically establishes a voice connection with the Customer Assistance Center (CAC). It transmits the current location and all relevant vehicle information. The CAC staff immediately inform the nearest Mercedes-Benz Service24h, which dispatches a repair service.)
- Wheels: Steel rims 6.5 J x 16
- Crosswind Assist
- Seat heating on driver's side
- Storage compartment for charging cables
- USB 5V socket
- Blind Spot Assist
- continuous partition wall
- First aid kit
- Pre-installation for Remote Services Plus
- Warning triangle
- Parking light removed
- Central locking with multi-button remote control

- Passenger side airbag
- Electrically adjustable and heated exterior mirrors, left and right
- BOTT - Installation



- Plastic flooring
 - Brake assist, active
 - Roof and rear door up
 - Entry handle on rear left corner pillar
 - Entry handle on rear right corner pillar
 - All-weather floor mats with high surrounding edge
 - Hinged lid for storage compartment
 - LED High Performance Headlights
 - Marker lights, side
 - Navigation accessories: Pre-installation for Live Traffic Information
 - Package: Instrument Panel Charging Package (The charging package expands the charging options in the cockpit with two 5V USB-C ports and one 12V socket. One USB port and the 12V socket are installed in the center storage compartment of the instrument panel, and another USB port is located in the lower part of the center console. This allows for the charging of electronic devices such as mobile phones within easy reach of the driver and front passenger.)
 - Seats: Driver's seat box, low
 - Seats: Suspension seat comfort version, driver's seat
 - Rear panel
 - WET WIPER SYSTEM
 - Winter complete wheels
 - Thermal insulation driver's compartment
 - Additional rear door locking mechanism at 90 degrees
- Brakes: Electric parking brake
 - Ceiling light in the cargo/passenger compartment (with door contact)
 - Lockable compartment in storage area above windshield
 - Seatbelt warning device for front passenger seat
 - Clothes hooks in the driver's cab
 - leather steering wheel
 - Navigation
 - Fog lights with cornering function
 - Package: Acoustics
 - Package: Smartphone Integration Package
 - Upholstery: ARTICO black leatherette
 - Spare wheel
 - Spare wheel carrier under frame end
 - Double-leaf rear door, opening to side wall
 - Key: Multi-button radio remote control
 - Seats: Driver's seat armrest
 - Seats: Passenger seat, two-seater (including two headrests)
 - Seats: Lumbar support for driver's seat
 - Seat heating on passenger side
 - Long-throw nozzles in I-panel
 - Heated windshield
 - Heat-insulating glass all around with band filter on the windshield

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction

Wear and tear

No.	Component group	Description
1	Sliding door, right	Sliding door - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.