



Expertise

Protocol number: 46607899
Order No. / Reference: 26688208
Inspection date: 20 Jul 2026

Manufacturer: Ford

Model: Grand Tourneo Connect 2.0 EcoBlue TITANIUM

VIN: WF0EXXSK7PX013710



Vehicle details

Manufacturer / Type / Model / Equipment

Ford Grand Tourneo Connect 2.0 EcoBlue TITANIUM

Vehicle Identification number WF0EXXSK7PX013710
Mileage (Read) 160,950 km
First registration 23 Jun 2023
Number of holders 1

Fuel type Diesel
Engine displacement / Cylinder 1,968 ccm / 4
Power 90 kW
Gearbox / Number of gears Manual / 6
Type of drive Front drive
Type of vehicle Van

Colour / colour code Frost-Weiß
Doors / Seats 5 / 5
Upholstery type Cloth
Colour of upholstery Anthracite-Black



Vehicle details

Maintenance booklet / proof	Available / incomplete	Next maintenance in	0 Tag(e)
Last service on / at	09/2025 at 140,396 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT918579
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BVY 00112		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,300 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96V	Summer tyres on Light alloy	Goodyear	3mm / 3mm
2)	205/60 R16 96V	Summer tyres on Light alloy	Goodyear	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/60 R16 96H	Summer tyres on Light alloy	Sonstige	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • Anti-lock braking system (ABS) • Exterior mirror caps, painted black • Tires: 6.5 J x 16 alloy wheels (4) with 205/60 R16 • Front overhead storage compartment • Diesel particulate filter (DPF) • Electric front windows • Plastic luggage compartment cover, shaped • Halogen headlights with daytime running lights • Tailgate handle, painted in body color • Interior mirror automatically dimming • Isofix bracket • Headrests: 2 front and 3 rear, height adjustable • Paint finish: Solid • Steering wheel: Multifunction leather steering wheel, 4 spokes • Fog light • Package: Seat Package 18 • Upholstery: Cloth • Windscreen wipers with rain sensor • Side windows fixed, 2nd row, right and left • Start-stop system • Front bumper with chrome trim • Carpet (1st and 2nd row) • Carpet floor mats for the front (2-piece set) • Doors: Rear swing door • Door handles painted in car color • circulating air heating • USB port for the 2nd row of seats • Heat-insulating glazing, tinted (from the B-pillar) • Auxiliary heater, electric | <ul style="list-style-type: none"> • Exterior mirrors, electrically adjustable, heated and electrically folding • third brake light • Roof rails, silver-colored • Tachometer • Ford Power Start function • Transmission: 6-speed manual transmission • Illuminated glove compartment with lid • Back window, heater • Intelligent Protection System (IPS) • Front air conditioning, manual, with semi-electronic recirculation function • Leather gear knob • Adjustable steering column • Front center console "Premium" • Package: Driver Assistance Package 1 • Pollen and dust filter • Tire Pressure Monitoring System (TPMS) • Headlight assistant with day/night sensor • Bench seat (in the 2nd row, 3 seats) • Rear bumper painted in body color • Daytime running light • Carpeted floor in the luggage compartment • Child safety lock on sliding doors • Doors: Sliding door, right and left • Front door interior trim with illuminated switches including door storage compartments for 1.5 L bottles • Electronic immobilizer • Central locking: 2nd remote control key for central locking |
|---|---|

Extra equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • Radio equipment: Audio system 4 (Ford navigation system - 10" touchscreen (25.4 cm screen diagonal) in the center console - digital radio reception DAB/DAB+ (Digital Audio Broadcasting) - AM/FM antenna - 6 speakers - voice control for audio and telephone - support for Android Auto and Apple CarPlay) | <ul style="list-style-type: none"> • spare wheel, alloy wheel • Safety partition net for luggage compartment |
|--|--|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Trim / covers	Trim / covers (Dämmung Kotflügel) - Damage caused by marten / rodent - Replace
2	Engine	Engine cowling - lower - Broken / torn - Replace
3	Misc.	Inspection / maintenance - Due - Perform
4	Front bumper	Front bumper (+ Steinschläge) - Scratch(es) - Paint
5	Rear bumper	Rear bumper (+ Abdeckkappe) - Scratch(es) - Paint
6	Sill - right side	Sill - Deformed - Repair and paint
7	Door - front left side	Door - Scratch(es) - Paint
8	Sliding door - left side	Sliding door with glass panel - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
2	Boot lid / rear door	Boot lid - Abrasion - No deduction
3	Gearbox	Gear knob - Scratched - No deduction
4	Side panel - rear right side	Side panel - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Accident damages

No. Accident

- 1 Side right

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

Das Fahrzeug befand sich zum Besichtigungszeitpunkt in beschädigtem, nicht demontiertem Zustand. Schadenausweitung möglich, Zusatzkosten können entstehen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents



Figure 19: Navigation



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Damage 1: Trim / covers: Trim / covers (Dämmung Kotflügel) - Damage caused by marten / rodent - Replace



Damage 1: Trim / covers: Trim / covers (Dämmung Kotflügel) - Damage caused by marten / rodent - Replace



Damage 1: Trim / covers: Trim / covers (Dämmung Kotflügel) - Damage caused by marten / rodent - Replace



Damage 1: Trim / covers: Trim / covers (Dämmung Kotflügel) - Damage caused by marten / rodent - Replace



Damage 2: Engine: Engine cowling - lower - Broken / torn - Replace



Damage 2: Engine: Engine cowling - lower - Broken / torn - Replace



Damage 3: Misc.: Inspection / maintenance - Due - Perform



Damage 4: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 4: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 4: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 4: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper (+ Abdeckkappe) - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper (+ Abdeckkappe) - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper (+ Abdeckkappe) - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper (+ Abdeckkappe) - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper (+ Abdeckkappe) - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper (+ Abdeckkappe) - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper (+ Abdeckkappe) - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper (+ Abdeckkappe) - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper (+ Abdeckkappe) - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper (+ Abdeckkappe) - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper (+ Abdeckkappe) - Scratch(es) - Paint



Damage 6: Sill - right side: Sill - Deformed - Repair and paint




Damage 6: Sill - right side: Sill - Deformed - Repair and paint



Damage 7: Door - front left side: Door - Scratch(es) - Paint



Damage 7: Door - front left side: Door - Scratch(es) - Paint



Damage 7: Door - front left side: Door - Scratch(es) - Paint



Damage 7: Door - front left side: Door - Scratch(es) - Paint



Damage 7: Door - front left side: Door - Scratch(es) - Paint



Damage 7: Door - front left side: Door - Scratch(es) - Paint



Damage 8: Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint



Damage 8: Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint



Damage 8: Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint



Wear and tear 4: Side panel - rear right side: Side panel - dent(s) - No deduction



Wear and tear 4: Side panel - rear right side: Side panel - dent(s) - No deduction




Accident 1: Side right




Accident 1: Side right




Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right