



Expertise

Protocol number: 46631492
Order No. / Reference: 26662986
Inspection date: 1 Jul 2026

Manufacturer: Mazda

Model: CX-60 AWD PHEV Aut. HOMURA

VIN: JMZKH0HB301110765



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mazda CX-60 AWD PHEV Aut. HOMURA	
Vehicle Identification number	JMZKH0HB301110765
Mileage (Read)	50,000 km
First registration	12 Dec 2022
Number of holders	1
Fuel type	Hybr.B/E ext.auf
Engine displacement / Cylinder	2,488 ccm / 4
Power	141 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Deep Crystal Blue Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	12,000 km
Last service on / at	01/2025 at 40,736 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GR183371
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	With complaint
Manufacturer key number/ type code number	7118 / AIL 00009		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,667 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R20 100W	Summer tyres on Light alloy	Bridgestone	6mm / 6mm
2)	235/50 R20 104Y	Summer tyres on Light alloy	Pirelli	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 107H	Winter tyres on Light alloy	Fulda	7mm / 7mm
2)	235/60 R18 107H	Winter tyres on Light alloy	Fulda	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Adaptive cruise control with traffic jam assist function (MRCC)
- Airbag: Knee airbag for driver
- Airbag: Front and rear outer side airbags
- All-wheel drive (AWD)
- Anti-lock braking system
- Dual exhaust system
- Electrically adjustable and heated exterior mirrors
- Hill Descent Control (HDC)
- City emergency brake assistant SCBS/SBS (Smart City Brake Support)
- Third brake light
- E-Call emergency call system
- Electric parking brake with auto-hold function
- Driving mode selection Mi-Drive
- High Beam Assist HBC
- Transmission: 8-speed automatic
- Head-up display
- rear window wiper
- i-stop stop/start system
- automatic climate control
- Front headrests are height-adjustable
- Cargo securing including luggage compartment partition net
- Charging cable: Type 2 charging cable (20 A) for charging stations (Mode 3)
- leather steering wheel
- 20" alloy wheels, black
- Steering wheel: Paddle shifters on the steering wheel
- Login: Keyless access system
- Armrest - centre, rear
- Driver Alertness Detection (DAA)
- Package: Premium Comfort
- Front parking sensors
- PTC heating system for the interior
- Rain sensor
- Wheels: Mobility Kit
- Rear seat backrests split folding (40:20:40)
- Seat belts: 3-point automatic seat belts for all seats
- Front seat heating
- Lane Keeping Assist (ELK) with steering support
- Rear bumper in body color
- Traffic Sign Recognition (TSR)
- Immobiliser
- Airbag: Center airbag front
- Airbag: Front airbags
- Airbag: Head/shoulder airbags, front and rear
- Alarm system with interior monitoring
- Ambient lighting on the headliner
- Rear Cross Traffic Alert (RCTA)
- Exit Warning (BSM)
- Exterior mirror caps in black
- Hill Start Assist (HLA)
- Coming/leaving home light function
- Roof spoiler
- Dynamic Stability Control (DSC) with Traction Control System (TCS)
- De-icer function for windshield wipers
- Vehicle stability program: Kinematic Posture Control (KPC)
- Cruise control system with speed limiter
- Illuminated glove compartment
- Heated rear window
- i-Active Display
- iSize child seat anchor
- Rear headrests (3)
- Paint finish: Solid
- Charging cable: Type 2 charging cable (13 A) for household socket (Mode 2)
- LED taillights
- LED daytime running lights
- Leather gear knob
- Steering wheel: Steering wheel heating
- light sensor
- Mazda Connect
- MyMazda App
- Otto particulate filter
- Rear parking sensors
- Upholstery: Leather interior
- Radio accessories: USB port (2)
- Tire pressure monitoring system (TPMS)
- Rear view camera
- Electric power steering
- Seats: Driver's seat tilt adjustment
- Sound Simulator (AVAS)
- Lane Change Assist Plus (BSM)
- Lower bumper in body color
- Full LED headlights
- Central locking with remote control



Extra equipment

- Boot mat with loading edge protection
- Key cover Polymetal Grey
- Paint finish: Metallic
- Standard floor mats
- Package: Convenience & Sound (Electric tailgate - Darkened rear and side windows - 360° monitor with see-through view - 230V/150W socket (rear of center console) - 230V/1500W socket (trunk) - Bose BassMatch Centerpoint 2 sound system with 12 speakers - Qi: Inductive charging (for compatible smartphones) - Lighting in door sills, center console, door storage compartment)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed, problem has been detected This is due to the following reason.: Motorkontrolle aktiv

Value reducing factors

No.	Component group	Description
1	Front bumper	Spoiler - Deformed - Loss in value
2	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
3	Roof	Roof - dent(s) - Smooth repair work
4	Roof	Roof rail - left side - Scratch(es) - Smart repair
5	Mudguard - right side	Wheel well extension - Scratch(es) - Smart repair
6	Sill - left side	Sill - Scratch(es) - Smart repair
7	Sill - right side	Sill - Scratch(es) - Smart repair
8	Instrument panel	Indicator light (Motorkontrollleuchte ist aktiv) - on - Perform diagnosis
9	Rear bumper	Rear bumper - Dent / paintcoat damage - Repair and paint
10	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Replace

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Door - front left side	Door edge - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Roof, Rear, Provided by user / customer, from 24 May 2025	2.663,71 €



Paint coat thickness measurement

Boot lid / rear door 222 µm |

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.





Figure 30: Misc.



Damage 1: Front bumper: Spoiler - Deformed - Loss in value



Damage 1: Front bumper: Spoiler - Deformed - Loss in value



Damage 2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 3: Roof: Roof - dent(s) - Smooth repair work




Damage 3: Roof: Roof - dent(s) - Smooth repair work




Damage 4: Roof: Roof rail - left side - Scratch(es) - Smart repair




Damage 4: Roof: Roof rail - left side - Scratch(es) - Smart repair



Damage 5: Mudguard - right side: Wheel well extension - Scratch(es) - Smart repair



Damage 5: Mudguard - right side: Wheel well extension - Scratch(es) - Smart repair



Damage 6: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 6: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 7: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 7: Sill - right side: Sill - Scratch(es) - Smart repair




Damage 8: Instrument panel: Indicator light (Motorkontrollleuchte ist aktiv) - on - Perform diagnosis




Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint




Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint




Damage 9: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint




Damage 10: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace



Damage 10: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 3: Door - front left side: Door edge - Scratch(es) - No deduction



Wear and tear 3: Door - front left side: Door edge - Scratch(es) - No deduction



Boot lid / rear door: 222 µm



Boot lid / rear door: 222 µm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: JMZKH0HB301110765

Hersteller / Modell: MAZDA MAZDA CX-60 AWD PHEV Aut. HOMURA

Datum	KM-Stand	Beschreibung
21.01.2025	40.736	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
18.12.2023	19.637	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges