

Vehicle details

VIN	VXEVBHVM P7862677	Registration date	01/01/1900	Exterior Color	Unknown
Brand	OPEL	Licence Plate		Odometer	64 884 km
Model	VIVARO 1.5 Turbo 88kW L2H1				

Inspection Details




Generic equipment

Removable element



Technical Document

Triangle	✓	Service manual holder	✓
Fire extinguisher	✓	User manual	✓
Towing hook	✓	Warranty booklet	✓
Spare wheel (wheel & tyre)	✗	First aid kit	✓
Safety vest	✗	Spare key	✓
Aerial cable	✗	Remote key	✓









Tyres






Damages

1		Part	Unpainted bumper	Repair Time	-	Part Cost	-
		Position	Front	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
2		Part	Door	Repair Time	-	Part Cost	-
		Position	Front right	Repair Cost	-	Gross Cost	75.00€
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	75.00€	Net Cost	75.00€

DEKRA Automotive Solutions

3		Part	Roof	Repair Time	2.00	Part Cost	-
		Position	-	Repair Cost	120.00€	Gross Cost	1,030.00€
		Damages	Dented	Paint Time	9.10	Depreciation %	-
		Severity	-	Paint cost	910.00€	Depreciation	-
		Repair mode	Repair	Flat Rate	-	Net Cost	1,030.00€
4		Part	Door	Repair Time	-	Part Cost	-
		Position	Front left	Repair Cost	-	Gross Cost	-
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
5		Part	Side panel	Repair Time	-	Part Cost	-
		Position	Back left	Repair Cost	-	Gross Cost	-
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
6		Part	Unpainted bumper	Repair Time	-	Part Cost	-
		Position	Back	Repair Cost	-	Gross Cost	190.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Lumpsum repair	Flat Rate	190.00€	Net Cost	190.00€
7		Part	Interior door panel	Repair Time	-	Part Cost	-
		Position	Back left	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
8		Part	Interior door panel	Repair Time	-	Part Cost	-
		Position	Back right	Repair Cost	-	Gross Cost	-
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
9		Part	Wheel arch	Repair Time	-	Part Cost	-
		Position	Back left	Repair Cost	-	Gross Cost	75.00€
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	75.00€	Net Cost	75.00€
10		Part	Wheel arch	Repair Time	-	Part Cost	-
		Position	Back right	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-

DEKRA Automotive Solutions

11		Part	Spare wheel kit	Repair Time	-	Part Cost	100.42€
		Position	-	Repair Cost	-	Gross Cost	100.42€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	100.42€
12		Part	Safety vest	Repair Time	-	Part Cost	5.00€
		Position	-	Repair Cost	-	Gross Cost	5.00€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	5.00€
13		Part	Aerial cable	Repair Time	0.10	Part Cost	22.31€
		Position	-	Repair Cost	6.00€	Gross Cost	28.31€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	28.31€

Signatures

Signature Receiver

Signature Expert