

MACDAM

Mercedes-Benz EQC '19 BEV

Vehicle information

Make:	Mercedes-Benz	License:	
Gearbox:	Automatic	Body color:	
Model:	EQC '19 BEV	VIN:	W1K2938901F038907
Fuel type:	Electric	Power:	300 kW
Version:	EQC 400 4Matic Bus.Sol.Lux.	First registration	30/12/2021
Mileage:	185283 km	N° of doors:	

Damage summary

Front	2
Interior	2
Left	3
Rear	1
Right	3
Roof & others	1

Commercial pictures





Options according to the inspector



Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser	Yes
Hook	Yes	Panoramic roof	Yes	Radio multimedia	Yes
Rear view camera	Yes	Sun Roof electric	Yes	Telephone equipment	Yes

Damages

Alloy rim RR
Scratch(es)
Repair and paint (complete)
Right



Bonnet
Stone chip(s)
Repair and paint (complete)
Front



Bumper F
Scratch(es)
Repair and paint (partial)
Front



Bumper R
Scratch(es)
Repair and paint (complete)
Rear



Door RL
Scratch(es)
Repair and paint (partial)
Left



Door RR
Bad repair
Repair and paint (complete)
Right



Roof
Stone chip(s)
Repair and paint (complete)
Roof & others



Seat cover FL
Worn
Replace
Interior




Steering wheel
Worn
Replace
Interior



Wing FL
Bad repair
Repair and paint (complete)
Left



Wing FR
Scratch(es)
Repair and paint (complete)
Right



Wing RL
Scratch(es)
Repair and paint (complete)
Left



Tyres	
	Front Left
	Summer
	255/45/20/105/Y
	Michelin
	5.2 mm
	Front Right
	Summer
	255/45/20/105/Y
	Michelin
	5.2 mm
	Rear Left
	Summer
	255/45/20/105/Y
	Michelin
	6.0 mm
	Rear Right
	Summer
	255/45/20/105/Y
	Michelin
	6.0 mm

Checks			
CO2 Emission	0	Digital maintenance	N/A
Luggage cover	Yes	Number head rests	5
Number of charging cables (rapid charge)	1	Number of keys total	2
Reset to factory settings	Yes, vehicle is reset to factory settings		Service book
User's manual	Yes		Yes

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.