



Expertise

Protocol number: 46104543
Order No. / Reference: 26121552
Inspection date: 23 Jun 2026

Manufacturer: Opel

Model: Astra 1.5 D Start/Stop Sports Tourer Business Edition

VIN: W0VBD8EV7N8033821



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Astra 1.5 D Start/Stop Sports Tourer Business Edition	
Vehicle Identification number	W0VBD8EV7N8033821
Mileage (Read)	89,469 km
First registration	27 Jan 2022
Number of holders	1
Power / Engine displacement	90 kw / 1,496 ccm
Fuel type / Cylinder	Diesel / 3
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Summit White S
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	48 %
Last service on / at	12/2025 at 87,139 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GF961964
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / ALL 00257		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,945 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Steel rim with wheel cover	Fulda	8mm / 8mm
2)	205/55 R16 91H	Winter tyres on Steel rim with wheel cover	Fulda	8mm / 8mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91V	Summer tyres (Without wheel rim)	Continental	5mm / 5mm
2)	205/55 R16 91V	Summer tyres (Without wheel rim)	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • 2 ignition keys • Airbag for driver and passenger side • Airbag: Head airbags, 1st and 2nd row (outer seats) • Anti-lock braking system (ABS) • Electrically adjustable and heated exterior mirrors for driver and passenger side • third brake light • black roof rails • Diesel particulate filter (DPF) • Electronic Stability Program Plus (ESP Plus) • Speed controller with limiter • Back window, heater • Interior lighting, front and rear • Air conditioning • trunk light • Front headrests • LED headlights • Steering wheel: Leather steering wheel • Lighting equipment • Parkpilot, rear parking aid • Upholstery: Cloth • Radio: Digital radio reception DAB/DAB+/DMB-R • Tire repair kit • Wheels: Designer wheels, 7 J x 16 with tires 205/55 R16 • Power steering • Luggage compartment safety net • Seats: Comfort seats, front • 12V power outlet in the center console • Pre-installation for child seat mounting system "ISOFIX" • Heat-insulating glazing, green tinted, and windshield | <ul style="list-style-type: none"> • Storage compartments • Airbag: Chest-pelvis side airbag for driver and front passenger side • Automatic activation of the hazard warning lights • Hill Start Assist • On-board computer • Roof design line, above in black • Decorative trim strips Antelao Sand/Polar Silver • Tachometer • Electric windows front and rear • Transmission: 6-speed manual transmission • rear window wiper • Instruments, black, with high-gloss chrome rings, 3.5" driver information display • Rear headrests (3) • Cargo area cover • LED daytime running lights • Steering column, height and reach adjustable • Fog light • Pedals: Disengaging safety pedals • Quickheat rapid heating system • Radio: Multimedia radio with 7" touchscreen color display • Tire pressure monitoring system • Rear seat backrest folds forward in a 60:40 split • Seat belts: Three-point seat belts in all seats • Visibility equipment • Start/Stop System • Traction Control (TC) Plus • Immobiliser • Central locking with remote control and interior switches |
|---|--|

Extra equipment

- Paintwork: Solid special color Snow White

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Interior trim - Scratch(es) - Loss in value
2	Equipment	Tirefit filler - Expired - Replace
3	Trim / covers	Boot lid - interior trim - Scratch(es) - Loss in value
4	Side panel - rear right side	Wheel arch (Radhausschale) - Broken / torn - Replace
5	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
6	Door - rear right side	Door - Scratch(es) - Smart repair
7	Body	Underbody panelling - Broken / torn - Replace
8	Roof	Roof rail - left side - dent(s) - Smooth repair work
9	Roof	Roof rail - right side - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Interior	Interior - Scratch(es) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Door - front left side	Door edge - Scratch(es) - No deduction
5	Body	Body - Scratch(es) - No deduction
6	Front bumper	Spoiler - Scratch(es) - No deduction
7	Front bumper	Front bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 26 Sept 2025	5.237,39 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Das Fahrzeug weist der Laufzeit entsprechende Gebrauchsspuren auf.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument cluster



Figure 9: Instrument panel



Figure 10: Interior 360° view



Figure 11: Cargo area




Figure 12: VIN



Figure 13: Mounted tyres




Figure 14: Documents




Figure 15: Documents



Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.





Figure 27: Misc.



Damage 1: Side panel - rear right side: Interior trim - Scratch(es) - Loss in value



Damage 1: Side panel - rear right side: Interior trim - Scratch(es) - Loss in value



Damage 2: Equipment: Tirefit filler - Expired - Replace




Damage 3: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value




Damage 3: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value




Damage 3: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value



Damage 3: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value




Damage 3: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value



Damage 3: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value




Damage 4: Side panel - rear right side: Wheel arch (Radhausschale) - Broken / torn - Replace



Damage 4: Side panel - rear right side: Wheel arch (Radhausschale) - Broken / torn - Replace



Damage 5: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 5: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage 6: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 7: Body: Underbody panelling - Broken / torn - Replace



Damage 7: Body: Underbody panelling - Broken / torn - Replace



Damage 8: Roof: Roof rail - left side - dent(s) - Smooth repair work




Damage 8: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 8: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 9: Roof: Roof rail - right side - Dent / paintcoat damage - Repair and paint



Damage 9: Roof: Roof rail - right side - Dent / paintcoat damage - Repair and paint



Damage 9: Roof: Roof rail - right side - Dent / paintcoat damage - Repair and paint



Damage 9: Roof: Roof rail - right side - Dent / paintcoat damage - Repair and paint