



Expertise

Protocol number: 45819962
Order No. / Reference: 26382533
Inspection date: 8 Jun 2026

Manufacturer: Skoda
VIN: TMBJJ7NX8NY023051

Model: Octavia Combi 2.0 TDI DSG Ambition



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Octavia Combi 2.0 TDI DSG Ambition	
Vehicle Identification number	TMBJJ7NX8NY023051
Mileage (Read)	186,504 km
First registration	10 Feb 2022
Number of holders	2
Next periodical technical inspection	02/2027
(Report on hand)	
Power / Engine displacement	110 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Brillant-Silber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	10,100 km
Last service on / at	02/2026 at 177,796 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GG214664
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8004 / AWL 00091		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,990 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96V	Summer tyres on Light alloy	Goodyear	8mm / 8mm
2)	205/60 R16 96V	Summer tyres on Light alloy	Goodyear	8mm / 8mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	205/60 R16 96H	Winter tyres on Light alloy	Goodyear	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/60 R16 92V	Summer tyres on Steel	Kumho	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Storage compartment in the luggage compartment with cargo element
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Airbag, driver's knee airbag
- Airbag, head airbags
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors
- Heated windshield washer nozzles including 5l washer fluid reservoir
- Glasses compartment in the headliner
- Roof rails, black
- Tachometer
- Electronic parking brake
- Electronic Stability Control (ESC)
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Cruise control system
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec: Start/stop system including brake energy recuperation
- Interior mirror automatically dimming
- Electronic child safety lock
- Climatronic air conditioning (2-zone) (fully automatic, separately adjustable for driver and front passenger and anti-allergen filter & activated carbon filter - air-conditioned and illuminated glove compartment)
- LED license plate lights
- Steering wheel: height and reach adjustable
- Manual headlight range adjustment
- Rear center armrest with pass-through option
- Front center armrest, including storage compartment
- Engine drag torque control (MSR)
- Rear parking sensors
- Radio: Bolero music system with capacitive 10" color display
- Radio accessories: Digital radio reception DAB+
- Rain sensor
- Tire mobility kit (tire repair spray incl. compressor)
- Electromechanical power steering
- Seat belts (Three three-point seat belts in the rear)
- Seats: Rear seat backrest split 60:40, foldable
- SKODA Care Connect (SOS emergency call function (Emergency Call incl. automatic activation in the event of an accident with airbag deployment), Mobility service (connection for rapid assistance in case of breakdown), Information service (connection to the hotline for all questions relating to vehicle functions), Free remote vehicle access for 1 year (Remote Access) with access to vehicle data and functions via smartphone, e.g. parking position, activating hazard warning lights, current fuel level)
- Storage compartments (Four roof grab handles, rear with coat hooks; holder for the warning vest under the driver's seat; storage compartments in the front door panels with 1.5l bottle holders; storage compartments in the rear door panels with 0.5l bottle holders; ticket holder on the windshield; coat hooks on the B-pillars; storage compartments in the doors with felt lining)
- Traction control (ASR)
- Electrically folding exterior mirrors
- Hill start assist including auto-hold function
- Hydraulic brake assist (HBA)
- Grey headliner
- Diesel particulate filter
- Third brake light
- Electronic transverse differential lock (XDS+)
- Driving light assistant (Coming Home / Leaving Home function)
- Front radar assistant including city emergency braking function and pedestrian and cyclist detection
- Tinted windows
- Heated rear window
- Rear window wiper including windshield washer system
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Removable boot cover
- Headrests (5) front and rear height adjustable
- LED fog lights
- LED taillights
- LED headlights with LED daytime running lights
- Steering wheel: Leather steering wheel with multifunction buttons and paddle shifters (leather steering wheel and gearshift lever with leather elements - infotainment and driver assistance system operation)
- Multifunction display in the instrument cluster
- Upholstery: Cloth
- Radio accessories: 2 USB-C ports on the front
- Radio accessories: 8 speakers
- Radio accessories: Voice control
- Tire pressure monitoring
- Wheels: 16" alloy wheels Twister AERO (7J x 16, ET 46 with tires 205/60 R16)
- Seats: Height-adjustable driver and passenger seats (including lumbar support)
- Speed limiter
- Lane keeping assistant (Lane Assist)
- 12V socket in the trunk
- Phone: SmartLink (MirrorLink, Apple CarPlay, Android Auto)
- Phone: Wireless SmartLink for Apple CarPlay
- Bluetooth hands-free phone system
- Lashing eyes in the trunk
- Immobiliser



- Central locking including remote control integrated into the key and EASY Start

Extra equipment

- Paint finish: Metallic
- Package: Comfort (3-zone Climatronic - Sunset (dark tinted rear window and rear side windows) - Acoustic glazing in the front side windows - Heated front and outer rear seats - Heated steering wheel)
- Front and rear parking sensors
- Package: Columbus Infotainment Package (Combi) (Columbus Navigation System - Infotainment Online (3-year subscription) - Digital Instrument Cluster (Virtual Cockpit) - Phone Box - KESSY (Keyless Entry and Start-Stop System) - Luggage Net Partition)
- Wheels: Steel spare wheel 16" (with tires 205/55 R16 including jack and wheel wrench)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front left side - Scratched - Loss in value
2	Wheel / tyres	Alloy rim - rear left side - Scratched - Replace
3	Side panel - rear left side	Side panel - Dent / paintcoat damage - Paint
4	Body	Body - Damage by hail - Smooth repair work

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction
3	Rear bumper	Rear bumper (Ladekante) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Side - left, Professionally repaired, Invoice of repair done Non-existent, from 22 Oct 2024	2.429,66 €
2	Side right, Provided by user / customer, from 21 Jan 2026	2.686,37 €

Repainting

No.	Repainting
1	Mudguard - left side, Bonnet, Door - rear right side, Door - front left side, Door - front right side, Professionally carried out



Paint coat thickness measurement

Mudguard - left side	799 µm	Bonnet	122 µm
Door - rear right side	217 µm	Door - front left side	178 µm
Door - front right side	251 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.

Comments

Der beiliegende Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Damage 1: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 1: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratched - Replace



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratched - Replace



Damage 3: Side panel - rear left side: Side panel - Dent / paintcoat damage - Paint



Damage 3: Side panel - rear left side: Side panel - Dent / paintcoat damage - Paint




Damage 3: Side panel - rear left side: Side panel - Dent / paintcoat damage - Paint



Damage 4: Body: Body - Damage by hail - Smooth repair work



Damage 4: Body: Body - Damage by hail - Smooth repair work



Damage 4: Body: Body - Damage by hail - Smooth repair work



Damage 4: Body: Body - Damage by hail - Smooth repair work




Damage 4: Body: Body - Damage by hail - Smooth repair work



Damage 4: Body: Body - Damage by hail - Smooth repair work




Damage 4: Body: Body - Damage by hail - Smooth repair work



Damage 4: Body: Body - Damage by hail - Smooth repair work



Damage 4: Body: Body - Damage by hail - Smooth repair work



Damage 4: Body: Body - Damage by hail - Smooth repair work



Damage 4: Body: Body - Damage by hail - Smooth repair work



Damage 4: Body: Body - Damage by hail - Smooth repair work



Damage 4: Body: Body - Damage by hail - Smooth repair work



Repainting 1: Mudguard - left side, Bonnet, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Mudguard - left side, Bonnet, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Mudguard - left side, Bonnet, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Mudguard - left side, Bonnet, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Mudguard - left side, Bonnet, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Mudguard - left side, Bonnet, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Mudguard - left side, Bonnet, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Mudguard - left side, Bonnet, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Mudguard - left side, Bonnet, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Mudguard - left side, Bonnet, Door - rear right side, Door - front left side, Door - front right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: TMBJJ7NX8NY023051
Hersteller / Modell: SKODA SKODA Octavia Combi 2.0 TDI DSG Ambition

Datum	KM-Stand	Beschreibung
28.02.2026	177.796	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
09.10.2025	166.535	Kraftstofffilter ern; Luftfiltereinsatz ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
31.07.2025	156.089	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
23.04.2025	138.644	Systemtest/Eigendiagnose
03.03.2025	138.307	Motoröl b. Wartung; Reparatur Sonstiges; Systemtest/Eigendiagnose
10.02.2025	136.239	Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Getriebeöl ern/prüfen; HU + AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
22.03.2024	112.069	Batterie ern; Systemtest/Eigendiagnose
21.02.2024	107.639	Systemtest/Eigendiagnose
02.02.2024	104.524	Bremse Sonstiges; Bremsklötze vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
25.10.2023	86.826	Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben hinten; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Reparatur Sonstiges; Systemtest/Eigendiagnose; Wartung Sonstiges
06.06.2023	66.813	Regelwartungsdienst
19.04.2023	61.151	Motoröl b. Wartung; Ölwechsel
27.02.2023	54.000	Bremsscheiben + Klötze v
22.11.2022	38.576	Motoröl b. Wartung; Regelwartungsdienst