

Peugeot 308 SW '21



Vehicle information

Make:	Peugeot	License:	
Gearbox:	Automatic	Body color:	
Model:	308 SW '21	VIN:	VR3F4DGXTNY630695
Fuel type:	Petrol leaded	Power:	133 kW
Version:	308 SW PHEV 180 All.P.Bus.Aut	First registration	29/11/2022
Mileage:	120692 km	N° of doors:	

Damage summary

Front	①
Interior	①
Left	④
Rear	②
Right	⑤
Roof & others	②

Commercial pictures





Options according to the inspector

Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser	Yes
Hook	Yes	Radio multimedia	Yes	Telephone equipment	Yes

Damages

--	--	--	--	--	--

Alloy rim FR

Scratch(es)
Repair and paint (complete)
Right



Alloy rim RR

Scratch(es)
Repair and paint (complete)
Right





Bodywork

No damage
No repair
Roof & others

Bonnet

Scratch(es)
Repair and paint (complete)
Front






Bumper R

Scratch(es)

Repair and paint (complete)

Rear




Door FL

Scratch(es)

Repair and paint (complete)

Left



Door FR

Scratch(es)


Repair and paint (complete)

Right



Door RL

Scratch(es)
Repair and paint (complete)
Left



Door RR

Scratch(es)
Repair and paint (complete)
Right





Malfunction

Not functioning (well)
Diagnosis
Interior



Roof

Dent(s)
Repair and paint (complete)
Roof & others



Roof pillar L

Scratch(es)

Repair and paint (complete)

Left




Tailgate / Boot

Scratch(es)

Repair and paint (complete)

Rear




Wing RL

Bad repair

Repair and paint (complete)

Left



Wing RR

Dent(s)

Paintless dent repair

Right



Tyres

Front Left

Winter

225/45/17/94/Y

Goodyear

5.0 mm

Front Right

Winter

225/45/17/94/Y

Goodyear

6.0 mm

Rear Left

Winter

225/45/17/94/Y

Vredestein

5.0 mm

Rear Right

Winter

225/45/17/94/Y

Vredestein

4.0 mm

Checks

CO2 Emission	25	Customer data reset (contacts, e-mails, messages)	Yes
Digital maintenance	N/A	GPS storage	Yes
GPS storage	HD	Luggage cover	Yes
Number head rests	5	Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0	Number of keys total	2
Service book	N/A	User's manual	N/A

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.