



Expertise

Protocol number: 46028855
Order No. / Reference: 26423211
Inspection date: 17 Jun 2026

Manufacturer: Skoda
VIN: TMBJR7NU3NC203145

Model: Karoq 1.5 TSI ACT Ambition



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Karoq 1.5 TSI ACT Ambition	
Vehicle Identification number	TMBJR7NU3NC203145
Mileage (Read)	75,792 km
First registration	17 Jun 2022
Number of holders	1
Power / Engine displacement	110 kw / 1,498 ccm
Fuel type / Cylinder	Petrol / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Graphit-Grau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Grey



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	14,500 km
Last service on / at	08/2025 at 60,566 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ929019
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8004 / ASO 03173		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,920 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 94V	Summer tyres on Light alloy	Goodyear	5mm / 5mm
2)	215/55 R17 94V	Summer tyres on Light alloy	Goodyear	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98H	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	215/55 R17 98H	Winter tyres on Light alloy	Pirelli	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag, driver and passenger
- Airbag, head airbags
- Allergen filter
- Traction control (ASR)
- Electrically folding exterior mirrors including interior and exterior mirrors with automatic dimming.
- Exterior mirrors and door handles painted in body color
- Hill start assist
- Care Connect: Proactive services (10-year term)
- Roof rails, black
- Easy Start (start-stop button)
- Electronic parking brake including auto-hold function
- ESC Electronic Stability Control
- Electric windows front and rear
- Closed storage compartment on the dashboard
- Cruise control
- Tinted windows
- Automatic interior mirror dimming
- ISOFIX preparation on the outer rear seats
- Trunk cover, fixed
- Paint finish: Solid
- LED headlights with daytime running lights
- LED fog lights
- Reading lights at the front of the headliner
- Rear center armrest with cup holders and pass-through option
- Multifunction display in the instrument cluster, color
- Fatigue detection
- Rear parking sensors
- Wheel arch cover
- Radio accessories: 8 speakers
- Radio accessories: USB port in the center console (Type-C)
- Wheels: 17" Scutus Aero alloy wheels, matte black
- Gear shift indicator
- Seat belts
- Skoda Care Connect
- Speed limiter
- 12V socket - in the trunk
- Bumpers partially painted in body color
- Lashing eyes in the trunk
- Immobiliser
- front aero windshield wipers
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Dashboard in black / black, door trim in black
- Electrically adjustable and heated exterior mirrors with integrated side indicators
- Illuminated trunk
- Hydraulic brake assist (HBA)
- Grey headliner
- Ambition decorative inlay
- eCall
- Electronic transverse differential lock (XDS+)
- Driving light assistant and rain sensor
- Front radar assistant including city emergency braking function with pedestrian detection
- Transmission: 6-speed transmission
- Green tec (start/stop system and brake energy recuperation)
- Air conditioning
- Front and rear headrests are height-adjustable.
- LED brake light in the rear spoiler
- LED taillights in crystal glass look
- Steering wheel: Leather steering wheel with multifunction buttons
- Front center armrest, including storage compartment
- Engine drag torque control (MSR)
- Multi-collision brake
- Otto particulate filter
- Upholstery: Cloth
- Radio: Swing 6.5" music system
- Radio accessories: Digital radio reception DAB+
- Tire Mobility Kit
- Tire pressure monitoring
- Rear seat backrest split 60:40, foldable
- Electromechanical power steering
- Seats: Height-adjustable front seats
- Sun visor on driver and passenger side with illuminated vanity mirror
- 12V socket - in the center console
- Telephone: Comfort hands-free telephone system (without connection to the external antenna)
- Central locking with remote control



Extra equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Adaptive Cruise Control (ACC) (control range up to 210 km/h) (replaces cruise control) • Paint finish: Metallic • Package: Infotainment package Bolero (Bolero music system - Capacitive 8" color display - Digital instrument cluster (Virtual Cockpit) - SmartLink - Wireless SmartLink - Voice control - Phonebox with inductive charging function (connection via external antenna)) • Package: Winter BASIC (Heated front seats - Heated windshield washer nozzles - Headlight cleaning system) | <ul style="list-style-type: none"> • Electric tailgate operation with comfort opening • Luggage net partition • Heated steering wheel • Package: Comfort PLUS (Adjustable lumbar support in the front seats - Climatronic air conditioning (2-zone) - Sunset - Kessy) • Package: Parking BASIC (front and rear parking sensors - reversing camera) • Auxiliary heating |
|---|--|

Retrofitted equipment

- ACCESSORIES - Reversible boot mat - 57A0611 63A

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim (Halterung) - Missing - Replace
2	Equipment	Tirefit filler - Expired - Replace
3	Door - front right side	Door edge - Scratch(es) - Smart repair
4	Door - front right side	Door handle - outside - Scratch(es) - Smart repair
5	Door - front left side	Door edge - Scratch(es) - Smart repair
6	Sill - left side	Sill - Scratch(es) - Smart repair
7	Rear bumper	Rear bumper - Scratch(es) - Smart repair
8	Side panel - rear left side	Side panel (+ Kratzer Gebrauchsspur) - dent(s) - Smart repair
9	Front bumper	Spoiler - Deformed - Replace
10	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
11	Front bumper	Front bumper - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Der beiliegende Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Damage 1: Trim / covers: Boot lid - interior trim (Halterung) - Missing - Replace



Damage 1: Trim / covers: Boot lid - interior trim (Halterung) - Missing - Replace



Damage 1: Trim / covers: Boot lid - interior trim (Halterung) - Missing - Replace



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 4: Door - front right side: Door handle - outside - Scratch(es) - Smart repair




Damage 4: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 5: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 5: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 6: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 6: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 7: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 8: Side panel - rear left side: Side panel (+ Kratzer Gebrauchsspur) - dent(s) - Smart repair



Damage 8: Side panel - rear left side: Side panel (+ Kratzer Gebrauchsspur) - dent(s) - Smart repair



Damage 8: Side panel - rear left side: Side panel (+ Kratzer Gebrauchsspur) - dent(s) - Smart repair




Damage 9: Front bumper: Spoiler - Deformed - Replace



Damage 9: Front bumper: Spoiler - Deformed - Replace



Damage 9: Front bumper: Spoiler - Deformed - Replace




Damage 10: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 10: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 10: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 11: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



Damage 11: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



Damage 11: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



Damage 11: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



Damage 11: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 2: Bonnet: Bonnet - Stone chips - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: TMBJR7NU3NC203145

Hersteller / Modell: SKODA SKODA Karoq 1.5 TSI ACT Ambition

Datum	KM-Stand	Beschreibung
29.08.2025	60.566	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern
17.07.2025	56.701	AU; Wartung Sonstiges
10.06.2024	29.178	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges